

Inline Inspection- Finishing

Inspection #: 1528971, 1528972, 1528973,
 1528974, 1528975, 1528976, 1528977, 1528978,
 1528979, 1528980, 1528981, 1528982 | Group #:
 144087

Inspection Details

Scheduled Inspection Date	Inspection Started Date	Submitted Inspection Date	
2025-12-13 15:57	2025-12-15 07:51	2025-12-15 07:56	
Report Type	Inline Inspection- Finishing	Project	ARITZIA
Inspector	Haut Hak	Supplier	YM
Total PO Items Qty	11,627	Sample Inspected	80
Factory Name	YM	Approved By	heng
Created Date	2025-12-13	Submitted Inspection Date	2025-12-15
Last Modified Date	2025-12-15		
PO #	GPAR12003	ETD	2025-12-25
Destination	GROVEPORT, Toronto, Vancouver	Supplier ERP ID	YM
SKU #	NOMB 03-01-49772-SP26- ARP2296-65567-2-CAN, NOMB 03-01-49772-SP26- ARP2296-65567-20-CAN, NOMB 03-01-49772-SP26- ARP2296-65567-56-USA, NOMB 03-01-49772-SP26- ARP2400-65567-2-CAN, NOMB 03-01-49772-SP26- ARP2400-65567-20-CAN, NOMB 03-01-49772-SP26- ARP2400-65567-56-USA, NOMB 03-01-49772-SP26- ARP2425-65567-2-CAN, NOMB 03-01-49772-SP26- ARP2425-65567-20-CAN, NOMB 03-01-49772-SP26- ARP2425-65567-56-USA, NOMB 03-01-49772-SP26- ARP2432-65567-2-CAN, NOMB 03-01-49772-SP26- ARP2432-65567-20-CAN, NOMB 03-01-49772-SP26- ARP2432-65567-56-USA	Description	LADIES' 100% COTTON KNITTED T-SHIRTS
Style	NOMB 03-01-49772-SP26	Color	ADMIRAL/ FLASHING RD [QTY : 1, 014], ADMIRAL/ FLASHING RD [QTY : 1, 687], ADMIRAL/ FLASHING RD

			[QTY : 674], LT BIRCH/ADMIRAL [QTY : 1, 126], LT BIRCH/ ADMIRAL [QTY : 1, 875], LT BIRCH/ ADMIRAL [QTY : 750], RCH MCH BRN/LT BRCH [QTY : 1, 313], RCH MCH BRN/LT BRCH [QTY : 524], RCH MCH BRN/LT BRCH [QTY : 787], VILLA PINK/JUICY ROSE [QTY : 376], VILLA PINK/JUICY ROSE [QTY : 563], VILLA PINK/JUICY ROSE [QTY : 938]
Season	S1/2026	Ship Mode	SEA
Customer PO#	4500266509, 4500266510, 4500268041		
Inspected Qty (Pcs)	600	Inspected Carton Numbers	

Conclusion


Inspection Result	PASS	Approval Status	Accepted
Checklists			PASS
Packing, Packaging & Labelling			PASS
Workmanship			PASS
Quality Plan (Quality Plan尺寸表 - ARITZIA)			PASS
PASS	Critical	Major	Minor
Total Product + Quality Plan Defects	0	2	0
Accept/Reject Qty	0/1	3/4	0/1
Total Defective Units	2	Inspection Duration (Mins)	7.03

Comments

Color: LT- Birch/ admiral
ID. 7672 (20pcs)
No Defect.
ID. 8585 (20pcs)
1/ Poor Shape at Bottom hem=1pc.
ID. 7442 (20pcs)
No Defect.
ID. 7698 (20pcs)
1/ Puckering at banding=1pc.


Severity of Defects

Minor: 0.0 % Critical: 0.0 %



Highcharts.com

Pareto Defects



Highcharts.com

Checklists

Order Type	New Order	Samples Available?	Yes
Lab Analysis & Testing	Conform	Master Carton Requirements?	N/A
Drop Test?	N/A	Price?	N/A
Hang Tags?	N/A	Labels?	Conform
Composition	Conform		
Qty Conform	5	Qty Non-Conform	0


Photos

Packing, Packaging & Labelling

Main Label - Size Label Placement



Label 2



Care Label



Product

Product View - Front




Product View - Back




Others

Photos photos 1



Photos photos 2



Packing, Packaging & Labelling

Sample Size & AQL

Inspection Method	Inspection Level	Critical	Major	Minor	Carton Qty	Sample Size (Ctns)
normal	II	0.010	1.500	0.010	0	0

Section Conclusion

	Critical	Major	Minor
Total Defects	0	0	0
Accept/Reject Qty	0/1	0/1	0/1

Total Defective Units

0

Inspection Result

PASS

Workmanship

Sample Size & AQL

Inspection Method	Inspection Level	Critical	Major	Minor	Qty Inspected	Sample Inspected
normal	II	0.010	1.500	0.010	600	80

Section Conclusion

	Critical	Major	Minor
7-Pressing-Pressing: Poor	0	1	0

1-Seam-Seam puckering	0	1	0
Total Defects	0	2	0
Accept/Reject Qty	0/1	3/4	0/1

Total Defective Units	2	Inspection Result	PASS
C-Finishing & Pressing			

7-Pressing-Pressing: Poor (C-23)

Defect Severity	Quantity	Comment
Major	1	

IMAGE



Poor Shape at Bottom hem

E-Sewing & Linking

1-Seam-Seam puckering (E-1)

Defect Severity	Quantity	Comment
Major	1	

IMAGE



Puckering at banding

Quality Plan (Quality Plan尺寸表 - ARITZIA)

Total Defective Units	0	Inspection Result	PASS
Measurement 尺寸表		PASS	

Sample Size & AQL				
Inspection Method	Inspection Level	Qty Inspected	Sample Inspected	
N/A	N/A	600.00	1.00	
Question		Status	Fail Qty	Comment
Is Measurement OK?		Pass	0	