



Coal Report Volume 33

By Illinois Dept of Mines Minerals

Rarebooksclub.com, United States, 2012. Paperback. Book Condition: New. 246 x 189 mm. Language: English . Brand New Book ***** Print on Demand *****. This historic book may have numerous typos and missing text. Purchasers can download a free scanned copy of the original book (without typos) from the publisher. Not indexed. Not illustrated. 1915 Excerpt: .was installed to handle the railroad cars in bad weather. At the washer a new surface trestle was built and an electric motor installed to handle the refuse, also a new feed water heater was put in the boiler-house. The car unloader and jigs were also rebuilt, putting them in first-class condition. In the machineshop a new turning lathe and a flue welding outfit was installed. A locomotive compressor was installed, to make compressed air for driving drills and riveting hammer, in the blacksmith-shop. Some important changes in the management were made. The mines being divided up into sections and an assistant mine manager appointed to take charge of each section. This has resulted in increased safety and efficiency. An arrangement was also made to have two hoisting engineers, one of them being in charge of the generators and compressors, while the other one hoists coal,...



Reviews

It is an awesome publication which i actually have ever read through. it had been writtern really properly and valuable. I found out this book from my i and dad recommended this pdf to discover.

-- Doyle Schmeler

This book is definitely not simple to begin on studying but quite fun to see. I actually have read and that i am sure that i will gonna read through yet again once again in the foreseeable future. It is extremely difficult to leave it before concluding, once you begin to read the book.

-- Brennan Koelpin