(A Govt. of India Enterprise)

Southern Regional Load Despatch Centre

29, Race Course Cross Road, Bengaluru - 560009. CIN No: U40105DL2009G0I188682 Phone: 080 22254525, 22204325, 22252612, 22351146, Fax No: 080-22259219

Mobile: 9513243111, 9845782373.

Website: www.srldc.org, www.srldc.in, Email: srldccr@posoco.in, srldccroom@gmail.com



Message No: SRLDC/BT/2022/Feb/1 Date: 17-02-2022 12:15 Hrs

From: REMC, SRLDC To: Station In Charge

1 BETAM WIND

Sir/Madam,

It has been observed that following data points are not updating at SRLDC REMC.

This is impacting grid visibility and forecasting of RE generation.

SL.No	TimeStamp	Station Name	IEC Address	SCADA Key	Point Name	Point Type	Quality
1	2022-02-17 11:00:00	BETAM WIND	10317	3819318	3_BETAM_5WT155_ MW	Analog	Bad
2	2022-02-17 11:00:00	BETAM WIND	10324	3819325	3_BETAM_5WT168_ MW	Analog	Bad
3	2022-02-17 11:00:00	BETAM WIND	10331	3819332	3_BETAM_5WT155_ MVAR	Analog	Bad
4	2022-02-17 11:00:00	BETAM WIND	10338	3819339	3_BETAM_5WT168_ MVAR	Analog	Bad
5	2022-02-17 11:00:00	BETAM WIND	10345	3819346	3_BETAM_5WT155_ WIND	Analog	Bad
6	2022-02-17 11:00:00	BETAM WIND	10352	3819353	3_BETAM_5WT168_ WIND	Analog	Bad
7	2022-02-17 12:00:00	BETAM WIND	3006	1819007	2_BETAM_2BUS1_B PT	SOE/Status	Bad
8	2022-02-17 12:00:00	BETAM WIND	5142	2819143	3_BETAM_FDR1_1 WT119_LVRT	Status	Bad
9	2022-02-17 12:00:00	BETAM WIND	5143	2819144	3_BETAM_FDR1_1 WT124_LVRT	Status	Bad
10	2022-02-17 12:00:00	BETAM WIND	5144	2819145	3_BETAM_FDR1_1 WT125_LVRT	Status	Bad
11	2022-02-17 12:00:00	BETAM WIND	5145	2819146	3_BETAM_FDR1_1 WT95_LVRT	Status	Bad
12	2022-02-17 12:00:00	BETAM WIND	5146	2819147	3_BETAM_FDR1_1 WT96_LVRT	Status	Bad



(A Govt. of India Enterprise)

Southern Regional Load Despatch Centre

29, Race Course Cross Road, Bengaluru - 560009. CIN No: U40105DL2009G0I188682 Phone: 080 22254525, 22204325, 22252612, 22351146, Fax No: 080-22259219

Mobile: 9513243111, 9845782373.

Website: www.srldc.org, www.srldc.in, Email: srldccr@posoco.in, srldccroom@gmail.com



Real Time Telemetry Discrepancy Report

Message No: SRLDC/BT/2022/Feb/1 **Date:** 17-02-2022 12:15 Hrs

SL.No	TimeStamp	Station Name	IEC Address	SCADA Key	Point Name	Point Type	Quality
13	2022-02-17 12:00:00	BETAM WIND	5147	2819148	3_BETAM_FDR1_1 WT118_LVRT	Status	Bad
14	2022-02-17 12:00:00	BETAM WIND	5148	2819149	3_BETAM_FDR1_1 WT117_LVRT	Status	Bad
15	2022-02-17 12:00:00	BETAM WIND	5149	2819150	3_BETAM_FDR1_1 WT103_LVRT	Status	Bad
16	2022-02-17 12:00:00	BETAM WIND	5150	2819151	3_BETAM_FDR1_1 WT144_LVRT	Status	Bad
17	2022-02-17 12:00:00	BETAM WIND	5151	2819152	3_BETAM_FDR1_1 WT169_LVRT	Status	Bad
18	2022-02-17 12:00:00	BETAM WIND	5152	2819153	3_BETAM_FDR1_1 WT176_LVRT	Status	Bad
19	2022-02-17 12:00:00	BETAM WIND	5153	2819154	3_BETAM_FDR1_1 WT147_LVRT	Status	Bad
20	2022-02-17 12:00:00	BETAM WIND	5154	2819155	3_BETAM_FDR2_2 WT136_LVRT	Status	Bad
21	2022-02-17 12:00:00	BETAM WIND	5155	2819156	3_BETAM_FDR2_2 WT137_LVRT	Status	Bad
22	2022-02-17 12:00:00	BETAM WIND	5156	2819157	3_BETAM_FDR2_2 WT131_LVRT	Status	Bad
23	2022-02-17 12:00:00	BETAM WIND	5157	2819158	3_BETAM_FDR2_2 WT133_LVRT	Status	Bad
24	2022-02-17 12:00:00	BETAM WIND	5158	2819159	3_BETAM_FDR2_2 WT135_LVRT	Status	Bad
25	2022-02-17 12:00:00	BETAM WIND	5159	2819160	3_BETAM_FDR2_2 WT138_LVRT	Status	Bad
26	2022-02-17 12:00:00	BETAM WIND	5160	2819161	3_BETAM_FDR2_2 WT134_LVRT	Status	Bad
27	2022-02-17 12:00:00	BETAM WIND	5161	2819162	3_BETAM_FDR2_2 WT166_LVRT	Status	Bad
28	2022-02-17 12:00:00	BETAM WIND	5162	2819163	3_BETAM_FDR2_2 WT164_LVRT	Status	Bad
29	2022-02-17 12:00:00	BETAM WIND	5163	2819164	3_BETAM_FDR2_2 WT187_LVRT	Status	Bad

(A Govt. of India Enterprise)

Southern Regional Load Despatch Centre

29, Race Course Cross Road, Bengaluru - 560009. CIN No: U40105DL2009G0I188682 Phone: 080 22254525, 22204325, 22252612, 22351146, Fax No: 080-22259219

Mobile: 9513243111, 9845782373.

Website: www.srldc.org, www.srldc.in, Email: srldccr@posoco.in, srldccroom@gmail.com



Real Time Telemetry Discrepancy Report

Message No: SRLDC/BT/2022/Feb/1 **Date:** 17-02-2022 12:15 Hrs

SL.No	TimeStamp	Station Name	IEC Address	SCADA Key	Point Name	Point Type	Quality
30	2022-02-17 12:00:00	BETAM WIND	5164	2819165	3_BETAM_FDR2_2 WT159_LVRT	Status	Bad
31	2022-02-17 12:00:00	BETAM WIND	5165	2819166	3_BETAM_FDR2_2 WT52_LVRT	Status	Bad
32	2022-02-17 12:00:00	BETAM WIND	5166	2819167	3_BETAM_FDR2_2 WT123_LVRT	Status	Bad
33	2022-02-17 12:00:00	BETAM WIND	5167	2819168	3_BETAM_FDR2_2 WT53_LVRT	Status	Bad
34	2022-02-17 12:00:00	BETAM WIND	5168	2819169	3_BETAM_FDR3_3 WT110_LVRT	Status	Bad
35	2022-02-17 12:00:00	BETAM WIND	5169	2819170	3_BETAM_FDR3_3 WT153_LVRT	Status	Bad
36	2022-02-17 12:00:00	BETAM WIND	5170	2819171	3_BETAM_FDR3_3 WT188_LVRT	Status	Bad
37	2022-02-17 12:00:00	BETAM WIND	5171	2819172	3_BETAM_FDR3_3 WT150_LVRT	Status	Bad
38	2022-02-17 12:00:00	BETAM WIND	5172	2819173	3_BETAM_FDR3_3 WT100_LVRT	Status	Bad
39	2022-02-17 12:00:00	BETAM WIND	5173	2819174	3_BETAM_FDR3_3 WT152_LVRT	Status	Bad
40	2022-02-17 12:00:00	BETAM WIND	5174	2819175	3_BETAM_FDR3_3 WT167_LVRT	Status	Bad
41	2022-02-17 12:00:00	BETAM WIND	5175	2819176	3_BETAM_FDR3_3 WT140_LVRT	Status	Bad
42	2022-02-17 12:00:00	BETAM WIND	5176	2819177	3_BETAM_FDR3_3 WT171_LVRT	Status	Bad
43	2022-02-17 12:00:00	BETAM WIND	5177	2819178	3_BETAM_FDR3_3 WT132_LVRT	Status	Bad
44	2022-02-17 12:00:00	BETAM WIND	5178	2819179	3_BETAM_FDR3_3 WT149_LVRT	Status	Bad
45	2022-02-17 12:00:00	BETAM WIND	5179	2819180	3_BETAM_FDR3_3 WT121_LVRT	Status	Bad
46	2022-02-17 12:00:00	BETAM WIND	5180	2819181	3_BETAM_FDR3_3 WT126_LVRT	Status	Bad

(A Govt. of India Enterprise)

Southern Regional Load Despatch Centre

29, Race Course Cross Road, Bengaluru - 560009. CIN No: U40105DL2009G0I188682 Phone: 080 22254525, 22204325, 22252612, 22351146, Fax No: 080-22259219

Mobile: 9513243111, 9845782373.

Website: www.srldc.org, www.srldc.in, Email: srldccr@posoco.in, srldccroom@gmail.com



Real Time Telemetry Discrepancy Report

Message No: SRLDC/BT/2022/Feb/1 **Date:** 17-02-2022 12:15 Hrs

SL.No	TimeStamp	Station Name	IEC Address	SCADA Key	Point Name	Point Type	Quality
47	2022-02-17 12:00:00	BETAM WIND	5181	2819182	3_BETAM_FDR3_3 WT122_LVRT	Status	Bad
48	2022-02-17 12:00:00	BETAM WIND	5182	2819183	3_BETAM_FDR3_3 WTG178_LVRT	Status	Bad
49	2022-02-17 12:00:00	BETAM WIND	5183	2819184	3_BETAM_FDR4_4 WT82_LVRT	Status	Bad
50	2022-02-17 12:00:00	BETAM WIND	5184	2819185	3_BETAM_FDR4_4 WT45_LVRT	Status	Bad
51	2022-02-17 12:00:00	BETAM WIND	5185	2819186	3_BETAM_FDR4_4 WT98_LVRT	Status	Bad
52	2022-02-17 12:00:00	BETAM WIND	5186	2819187	3_BETAM_FDR4_4 WT104_LVRT	Status	Bad
53	2022-02-17 12:00:00	BETAM WIND	5187	2819188	3_BETAM_FDR4_4 WT157_LVRT	Status	Bad
54	2022-02-17 12:00:00	BETAM WIND	5188	2819189	3_BETAM_FDR4_4 WT69_LVRT	Status	Bad
55	2022-02-17 12:00:00	BETAM WIND	5189	2819190	3_BETAM_FDR4_4 WT4_LVRT	Status	Bad
56	2022-02-17 12:00:00	BETAM WIND	5190	2819191	3_BETAM_FDR4_4 WT146_LVRT	Status	Bad
57	2022-02-17 12:00:00	BETAM WIND	5191	2819192	3_BETAM_FDR4_4 WT1_LVRT	Status	Bad
58	2022-02-17 12:00:00	BETAM WIND	5192	2819193	3_BETAM_FDR4_4 WT5_LVRT	Status	Bad
59	2022-02-17 12:00:00	BETAM WIND	5193	2819194	3_BETAM_FDR4_4 WT23_LVRT	Status	Bad
60	2022-02-17 12:00:00	BETAM WIND	5194	2819195	3_BETAM_FDR4_4 WT142_LVRT	Status	Bad
61	2022-02-17 12:00:00	BETAM WIND	5195	2819196	3_BETAM_FDR4_4 WT148_LVRT	Status	Bad
62	2022-02-17 12:00:00	BETAM WIND	5196	2819197	3_BETAM_FDR4_4 WT43_LVRT	Status	Bad
63	2022-02-17 12:00:00	BETAM WIND	5197	2819198	3_BETAM_FDR6_6 WT16_LVRT	Status	Bad

(A Govt. of India Enterprise)

Southern Regional Load Despatch Centre

29, Race Course Cross Road, Bengaluru - 560009. CIN No: U40105DL2009G0I188682 Phone: 080 22254525, 22204325, 22252612, 22351146, Fax No: 080-22259219

Mobile: 9513243111, 9845782373.

Website: www.srldc.org, www.srldc.in, Email: srldccr@posoco.in, srldccroom@gmail.com



Real Time Telemetry Discrepancy Report

Message No: SRLDC/BT/2022/Feb/1 **Date:** 17-02-2022 12:15 Hrs

SL.No	TimeStamp	Station Name	IEC Address	SCADA Key	Point Name	Point Type	Quality
64	2022-02-17 12:00:00	BETAM WIND	5198	2819199	3_BETAM_FDR6_6 WT35_LVRT	Status	Bad
65	2022-02-17 12:00:00	BETAM WIND	5199	2819200	3_BETAM_FDR6_6 WT108_LVRT	Status	Bad
66	2022-02-17 12:00:00	BETAM WIND	5200	2819201	3_BETAM_FDR6_6 WT54_LVRT	Status	Bad
67	2022-02-17 12:00:00	BETAM WIND	5201	2819202	3_BETAM_FDR6_6 WT31_LVRT	Status	Bad
68	2022-02-17 12:00:00	BETAM WIND	5202	2819203	3_BETAM_FDR6_6 WT34_LVRT	Status	Bad
69	2022-02-17 12:00:00	BETAM WIND	5203	2819204	3_BETAM_FDR6_6 WT9_LVRT	Status	Bad
70	2022-02-17 12:00:00	BETAM WIND	5204	2819205	3_BETAM_FDR6_6 WT40_LVRT	Status	Bad
71	2022-02-17 12:00:00	BETAM WIND	5205	2819206	3_BETAM_FDR6_6 WT3_LVRT	Status	Bad
72	2022-02-17 12:00:00	BETAM WIND	5206	2819207	3_BETAM_FDR6_6 WT12_LVRT	Status	Bad
73	2022-02-17 12:00:00	BETAM WIND	5207	2819208	3_BETAM_FDR6_6 WT38_LVRT	Status	Bad
74	2022-02-17 12:00:00	BETAM WIND	5208	2819209	3_BETAM_FDR6_6 WT29_LVRT	Status	Bad
75	2022-02-17 12:00:00	BETAM WIND	5209	2819210	3_BETAM_FDR6_6 WT185_LVRT	Status	Bad
76	2022-02-17 12:00:00	BETAM WIND	5210	2819211	3_BETAM_FDR6_6 WT48_LVRT	Status	Bad
77	2022-02-17 12:00:00	BETAM WIND	5211	2819212	3_BETAM_FDR6_6 WT191_LVRT	Status	Bad
78	2022-02-17 12:00:00	BETAM WIND	5212	2819213	3_BETAM_FDR7_7 WT86_LVRT	Status	Bad
79	2022-02-17 12:00:00	BETAM WIND	5213	2819214	3_BETAM_FDR7_7 WT66_LVRT	Status	Bad
80	2022-02-17 12:00:00	BETAM WIND	5214	2819215	3_BETAM_FDR7_7 WT102_LVRT	Status	Bad

(A Govt. of India Enterprise)

Southern Regional Load Despatch Centre

29, Race Course Cross Road, Bengaluru - 560009. CIN No: U40105DL2009G0I188682 Phone: 080 22254525, 22204325, 22252612, 22351146, Fax No: 080-22259219

Mobile: 9513243111, 9845782373.

Website: www.srldc.org, www.srldc.in, Email: srldccr@posoco.in, srldccroom@gmail.com



Real Time Telemetry Discrepancy Report

Message No: SRLDC/BT/2022/Feb/1 **Date:** 17-02-2022 12:15 Hrs

SL.No	TimeStamp	Station Name	IEC Address	SCADA Key	Point Name	Point Type	Quality
81	2022-02-17 12:00:00	BETAM WIND	5215	2819216	3_BETAM_FDR7_7 WT77_LVRT	Status	Bad
82	2022-02-17 12:00:00	BETAM WIND	5216	2819217	3_BETAM_FDR7_7 WT74_LVRT	Status	Bad
83	2022-02-17 12:00:00	BETAM WIND	5217	2819218	3_BETAM_FDR7_7 WT36_LVRT	Status	Bad
84	2022-02-17 12:00:00	BETAM WIND	5218	2819219	3_BETAM_FDR7_7 WT65_LVRT	Status	Bad
85	2022-02-17 12:00:00	BETAM WIND	5219	2819220	3_BETAM_FDR7_7 WT25_LVRT	Status	Bad
86	2022-02-17 12:00:00	BETAM WIND	5220	2819221	3_BETAM_FDR7_7 WT184_LVRT	Status	Bad
87	2022-02-17 12:00:00	BETAM WIND	5221	2819222	3_BETAM_FDR7_7 WT71_LVRT	Status	Bad
88	2022-02-17 12:00:00	BETAM WIND	5222	2819223	3_BETAM_FDR7_7 WT139_LVRT	Status	Bad
89	2022-02-17 12:00:00	BETAM WIND	5223	2819224	3_BETAM_FDR7_7 WT68_LVRT	Status	Bad
90	2022-02-17 12:00:00	BETAM WIND	5224	2819225	3_BETAM_FDR7_7 WT6_LVRT	Status	Bad
91	2022-02-17 12:00:00	BETAM WIND	5225	2819226	3_BETAM_FDR7_7 WT7_LVRT	Status	Bad
92	2022-02-17 12:00:00	BETAM WIND	5226	2819227	3_BETAM_FDR1_1 WT119_HVRT	Status	Bad
93	2022-02-17 12:00:00	BETAM WIND	5227	2819228	3_BETAM_FDR1_1 WT124_HVRT	Status	Bad
94	2022-02-17 12:00:00	BETAM WIND	5228	2819229	3_BETAM_FDR1_1 WT125_HVRT	Status	Bad
95	2022-02-17 12:00:00	BETAM WIND	5229	2819230	3_BETAM_FDR1_1 WT95_HVRT	Status	Bad
96	2022-02-17 12:00:00	BETAM WIND	5230	2819231	3_BETAM_FDR1_1 WT96_HVRT	Status	Bad
97	2022-02-17 12:00:00	BETAM WIND	5231	2819232	3_BETAM_FDR1_1 WT118_HVRT	Status	Bad

(A Govt. of India Enterprise)

Southern Regional Load Despatch Centre

29, Race Course Cross Road, Bengaluru - 560009. CIN No: U40105DL2009G0I188682 Phone: 080 22254525, 22204325, 22252612, 22351146, Fax No: 080-22259219

Mobile: 9513243111, 9845782373.

Website: www.srldc.org, www.srldc.in, Email: srldccr@posoco.in, srldccroom@gmail.com



Real Time Telemetry Discrepancy Report

Message No: SRLDC/BT/2022/Feb/1 **Date:** 17-02-2022 12:15 Hrs

SL.No	TimeStamp	Station Name	IEC Address	SCADA Key	Point Name	Point Type	Quality
98	2022-02-17 12:00:00	BETAM WIND	5232	2819233	3_BETAM_FDR1_1 WT117_HVRT	Status	Bad
99	2022-02-17 12:00:00	BETAM WIND	5233	2819234	3_BETAM_FDR1_1 WT103_HVRT	Status	Bad
100	2022-02-17 12:00:00	BETAM WIND	5234	2819235	3_BETAM_FDR1_1 WT144_HVRT	Status	Bad
101	2022-02-17 12:00:00	BETAM WIND	5235	2819236	3_BETAM_FDR1_1 WT169_HVRT	Status	Bad
102	2022-02-17 12:00:00	BETAM WIND	5236	2819237	3_BETAM_FDR1_1 WT176_HVRT	Status	Bad
103	2022-02-17 12:00:00	BETAM WIND	5237	2819238	3_BETAM_FDR1_1 WT147_HVRT	Status	Bad
104	2022-02-17 12:00:00	BETAM WIND	5238	2819239	3_BETAM_FDR2_2 WT136_HVRT	Status	Bad
105	2022-02-17 12:00:00	BETAM WIND	5239	2819240	3_BETAM_FDR2_2 WT137_HVRT	Status	Bad
106	2022-02-17 12:00:00	BETAM WIND	5240	2819241	3_BETAM_FDR2_2 WT131_HVRT	Status	Bad
107	2022-02-17 12:00:00	BETAM WIND	5241	2819242	3_BETAM_FDR2_2 WT133_HVRT	Status	Bad
108	2022-02-17 12:00:00	BETAM WIND	5242	2819243	3_BETAM_FDR2_2 WT135_HVRT	Status	Bad
109	2022-02-17 12:00:00	BETAM WIND	5243	2819244	3_BETAM_FDR2_2 WT138_HVRT	Status	Bad
110	2022-02-17 12:00:00	BETAM WIND	5244	2819245	3_BETAM_FDR2_2 WT134_HVRT	Status	Bad
111	2022-02-17 12:00:00	BETAM WIND	5245	2819246	3_BETAM_FDR2_2 WT166_HVRT	Status	Bad
112	2022-02-17 12:00:00	BETAM WIND	5246	2819247	3_BETAM_FDR2_2 WT164_HVRT	Status	Bad
113	2022-02-17 12:00:00	BETAM WIND	5247	2819248	3_BETAM_FDR2_2 WT187_HVRT	Status	Bad
114	2022-02-17 12:00:00	BETAM WIND	5248	2819249	3_BETAM_FDR2_2 WT159_HVRT	Status	Bad

(A Govt. of India Enterprise)

Southern Regional Load Despatch Centre

29, Race Course Cross Road, Bengaluru - 560009. CIN No: U40105DL2009G0I188682 Phone: 080 22254525, 22204325, 22252612, 22351146, Fax No: 080-22259219

Mobile: 9513243111, 9845782373.

Website: www.srldc.org, www.srldc.in, Email: srldccr@posoco.in, srldccroom@gmail.com



Real Time Telemetry Discrepancy Report

Message No: SRLDC/BT/2022/Feb/1 **Date:** 17-02-2022 12:15 Hrs

SL.No	TimeStamp	Station Name	IEC Address	SCADA Key	Point Name	Point Type	Quality
115	2022-02-17 12:00:00	BETAM WIND	5249	2819250	3_BETAM_FDR2_2 WT52_HVRT	Status	Bad
116	2022-02-17 12:00:00	BETAM WIND	5250	2819251	3_BETAM_FDR2_2 WT123_HVRT	Status	Bad
117	2022-02-17 12:00:00	BETAM WIND	5251	2819252	3_BETAM_FDR2_2 WT53_HVRT	Status	Bad
118	2022-02-17 12:00:00	BETAM WIND	5252	2819253	3_BETAM_FDR3_3 WT110_HVRT	Status	Bad
119	2022-02-17 12:00:00	BETAM WIND	5253	2819254	3_BETAM_FDR3_3 WT153_HVRT	Status	Bad
120	2022-02-17 12:00:00	BETAM WIND	5254	2819255	3_BETAM_FDR3_3 WT188_HVRT	Status	Bad
121	2022-02-17 12:00:00	BETAM WIND	5255	2819256	3_BETAM_FDR3_3 WT150_HVRT	Status	Bad
122	2022-02-17 12:00:00	BETAM WIND	5256	2819257	3_BETAM_FDR3_3 WT100_HVRT	Status	Bad
123	2022-02-17 12:00:00	BETAM WIND	5257	2819258	3_BETAM_FDR3_3 WT152_HVRT	Status	Bad
124	2022-02-17 12:00:00	BETAM WIND	5258	2819259	3_BETAM_FDR3_3 WT167_HVRT	Status	Bad
125	2022-02-17 12:00:00	BETAM WIND	5259	2819260	3_BETAM_FDR3_3 WT140_HVRT	Status	Bad
126	2022-02-17 12:00:00	BETAM WIND	5260	2819261	3_BETAM_FDR3_3 WT171_HVRT	Status	Bad
127	2022-02-17 12:00:00	BETAM WIND	5261	2819262	3_BETAM_FDR3_3 WT132_HVRT	Status	Bad
128	2022-02-17 12:00:00	BETAM WIND	5262	2819263	3_BETAM_FDR3_3 WT149_HVRT	Status	Bad
129	2022-02-17 12:00:00	BETAM WIND	5263	2819264	3_BETAM_FDR3_3 WT121_HVRT	Status	Bad
130	2022-02-17 12:00:00	BETAM WIND	5264	2819265	3_BETAM_FDR3_3 WT126_HVRT	Status	Bad
131	2022-02-17 12:00:00	BETAM WIND	5265	2819266	3_BETAM_FDR3_3 WT29_HVRT	Status	Bad

(A Govt. of India Enterprise)

Southern Regional Load Despatch Centre

29, Race Course Cross Road, Bengaluru - 560009. CIN No: U40105DL2009G0I188682 Phone: 080 22254525, 22204325, 22252612, 22351146, Fax No: 080-22259219

Mobile: 9513243111, 9845782373.

Website: www.srldc.org, www.srldc.in, Email: srldccr@posoco.in, srldccroom@gmail.com



Real Time Telemetry Discrepancy Report

Message No: SRLDC/BT/2022/Feb/1 **Date:** 17-02-2022 12:15 Hrs

SL.No	TimeStamp	Station Name	IEC Address	SCADA Key	Point Name	Point Type	Quality
132	2022-02-17 12:00:00	BETAM WIND	5266	2819267	3_BETAM_FDR3_3 WTG178_HVRT	Status	Bad
133	2022-02-17 12:00:00	BETAM WIND	5267	2819268	3_BETAM_FDR4_4 WT82_HVRT	Status	Bad
134	2022-02-17 12:00:00	BETAM WIND	5268	2819269	3_BETAM_FDR4_4 WT45_HVRT	Status	Bad
135	2022-02-17 12:00:00	BETAM WIND	5269	2819270	3_BETAM_FDR4_4 WT98_HVRT	Status	Bad
136	2022-02-17 12:00:00	BETAM WIND	5270	2819271	3_BETAM_FDR4_4 WT104_HVRT	Status	Bad
137	2022-02-17 12:00:00	BETAM WIND	5271	2819272	3_BETAM_FDR4_4 WT157_HVRT	Status	Bad
138	2022-02-17 12:00:00	BETAM WIND	5272	2819273	3_BETAM_FDR4_4 WT69_HVRT	Status	Bad
139	2022-02-17 12:00:00	BETAM WIND	5273	2819274	3_BETAM_FDR4_4 WT4_HVRT	Status	Bad
140	2022-02-17 12:00:00	BETAM WIND	5274	2819275	3_BETAM_FDR4_4 WT146_HVRT	Status	Bad
141	2022-02-17 12:00:00	BETAM WIND	5275	2819276	3_BETAM_FDR4_4 WT1_HVRT	Status	Bad
142	2022-02-17 12:00:00	BETAM WIND	5276	2819277	3_BETAM_FDR4_4 WT5_HVRT	Status	Bad
143	2022-02-17 12:00:00	BETAM WIND	5277	2819278	3_BETAM_FDR4_4 WT23_HVRT	Status	Bad
144	2022-02-17 12:00:00	BETAM WIND	5278	2819279	3_BETAM_FDR4_4 WT142_HVRT	Status	Bad
145	2022-02-17 12:00:00	BETAM WIND	5279	2819280	3_BETAM_FDR4_4 WT148_HVRT	Status	Bad
146	2022-02-17 12:00:00	BETAM WIND	5280	2819281	3_BETAM_FDR4_4 WT43_HVRT	Status	Bad
147	2022-02-17 12:00:00	BETAM WIND	5281	2819282	3_BETAM_FDR6_6 WT16_HVRT	Status	Bad
148	2022-02-17 12:00:00	BETAM WIND	5282	2819283	3_BETAM_FDR6_6 WT35_HVRT	Status	Bad

(A Govt. of India Enterprise)

Southern Regional Load Despatch Centre

29, Race Course Cross Road, Bengaluru - 560009. CIN No: U40105DL2009G0I188682 Phone: 080 22254525, 22204325, 22252612, 22351146, Fax No: 080-22259219

Mobile: 9513243111, 9845782373.

Website: www.srldc.org, www.srldc.in, Email: srldccr@posoco.in, srldccroom@gmail.com



Real Time Telemetry Discrepancy Report

Message No: SRLDC/BT/2022/Feb/1 **Date:** 17-02-2022 12:15 Hrs

SL.No	TimeStamp	Station Name	IEC Address	SCADA Key	Point Name	Point Type	Quality
149	2022-02-17 12:00:00	BETAM WIND	5283	2819284	3_BETAM_FDR6_6 WT108_HVRT	Status	Bad
150	2022-02-17 12:00:00	BETAM WIND	5284	2819285	3_BETAM_FDR6_6 WT54_HVRT	Status	Bad
151	2022-02-17 12:00:00	BETAM WIND	5285	2819286	3_BETAM_FDR6_6 WT31_HVRT	Status	Bad
152	2022-02-17 12:00:00	BETAM WIND	5286	2819287	3_BETAM_FDR6_6 WT34_HVRT	Status	Bad
153	2022-02-17 12:00:00	BETAM WIND	5287	2819288	3_BETAM_FDR6_6 WT9_HVRT	Status	Bad
154	2022-02-17 12:00:00	BETAM WIND	5288	2819289	3_BETAM_FDR6_6 WT40_HVRT	Status	Bad
155	2022-02-17 12:00:00	BETAM WIND	5289	2819290	3_BETAM_FDR6_6 WT3_HVRT	Status	Bad
156	2022-02-17 12:00:00	BETAM WIND	5290	2819291	3_BETAM_FDR6_6 WT12_HVRT	Status	Bad
157	2022-02-17 12:00:00	BETAM WIND	5291	2819292	3_BETAM_FDR6_6 WT38_HVRT	Status	Bad
158	2022-02-17 12:00:00	BETAM WIND	5292	2819293	3_BETAM_FDR6_6 WT29_HVRT	Status	Bad
159	2022-02-17 12:00:00	BETAM WIND	5293	2819294	3_BETAM_FDR6_6 WT185_HVRT	Status	Bad
160	2022-02-17 12:00:00	BETAM WIND	5294	2819295	3_BETAM_FDR6_6 WT48_HVRT	Status	Bad
161	2022-02-17 12:00:00	BETAM WIND	5295	2819296	3_BETAM_FDR6_6 WT191_HVRT	Status	Bad
162	2022-02-17 12:00:00	BETAM WIND	5296	2819297	3_BETAM_FDR7_7 WT86_HVRT	Status	Bad
163	2022-02-17 12:00:00	BETAM WIND	5297	2819298	3_BETAM_FDR7_7 WT66_HVRT	Status	Bad
164	2022-02-17 12:00:00	BETAM WIND	5298	2819299	3_BETAM_FDR7_7 WT102_HVRT	Status	Bad
165	2022-02-17 12:00:00	BETAM WIND	5299	2819300	3_BETAM_FDR7_7 WT77_HVRT	Status	Bad

(A Govt. of India Enterprise)

Southern Regional Load Despatch Centre

29, Race Course Cross Road, Bengaluru - 560009. CIN No: U40105DL2009G0I188682 Phone: 080 22254525, 22204325, 22252612, 22351146, Fax No: 080-22259219

Mobile: 9513243111, 9845782373.

Website: www.srldc.org, www.srldc.in, Email: srldccr@posoco.in, srldccroom@gmail.com



Real Time Telemetry Discrepancy Report

Message No: SRLDC/BT/2022/Feb/1 **Date:** 17-02-2022 12:15 Hrs

SL.No	TimeStamp	Station Name	IEC Address	SCADA Key	Point Name	Point Type	Quality
166	2022-02-17 12:00:00	BETAM WIND	5300	2819301	3_BETAM_FDR7_7 WT74_HVRT	Status	Bad
167	2022-02-17 12:00:00	BETAM WIND	5301	2819302	3_BETAM_FDR7_7 WT36_HVRT	Status	Bad
168	2022-02-17 12:00:00	BETAM WIND	5302	2819303	3_BETAM_FDR7_7 WT65_HVRT	Status	Bad
169	2022-02-17 12:00:00	BETAM WIND	5303	2819304	3_BETAM_FDR7_7 WT25_HVRT	Status	Bad
170	2022-02-17 12:00:00	BETAM WIND	5304	2819305	3_BETAM_FDR7_7 WT184_HVRT	Status	Bad
171	2022-02-17 12:00:00	BETAM WIND	5305	2819306	3_BETAM_FDR7_7 WT71_HVRT	Status	Bad
172	2022-02-17 12:00:00	BETAM WIND	5306	2819307	3_BETAM_FDR7_7 WT139_HVRT	Status	Bad
173	2022-02-17 12:00:00	BETAM WIND	5307	2819308	3_BETAM_FDR7_7 WT68_HVRT	Status	Bad
174	2022-02-17 12:00:00	BETAM WIND	5308	2819309	3_BETAM_FDR7_7 WT6_HVRT	Status	Bad
175	2022-02-17 12:00:00	BETAM WIND	5309	2819310	3_BETAM_FDR7_7 WT7_HVRT	Status	Bad
176	2022-02-17 12:00:00	BETAM WIND	5324	2819325	3_BETAM_FDR5_5 WT155	Status	Bad
177	2022-02-17 12:00:00	BETAM WIND	5331	2819332	3_BETAM_FDR5_5 WT168	Status	Bad
178	2022-02-17 12:00:00	BETAM WIND	5373	2819374	3_BETAM_FDR5_5 WT168_LVRT	Status	Bad
179	2022-02-17 12:00:00	BETAM WIND	5374	2819375	3_BETAM_FDR5_5 WT101_LVRT	Status	Bad
180	2022-02-17 12:00:00	BETAM WIND	5375	2819376	3_BETAM_FDR5_5 WT165_LVRT	Status	Bad
181	2022-02-17 12:00:00	BETAM WIND	5376	2819377	3_BETAM_FDR5_5 WT141_LVRT	Status	Bad
182	2022-02-17 12:00:00	BETAM WIND	5377	2819378	3_BETAM_FDR8_8 WT11_LVRT	Status	Bad

(A Govt. of India Enterprise)

Southern Regional Load Despatch Centre

29, Race Course Cross Road, Bengaluru - 560009. CIN No: U40105DL2009G0I188682 Phone: 080 22254525, 22204325, 22252612, 22351146, Fax No: 080-22259219

Mobile: 9513243111, 9845782373.

Website: www.srldc.org, www.srldc.in, Email: srldccr@posoco.in, srldccroom@gmail.com



Real Time Telemetry Discrepancy Report

Message No: SRLDC/BT/2022/Feb/1 **Date:** 17-02-2022 12:15 Hrs

SL.No	TimeStamp	Station Name	IEC Address	SCADA Key	Point Name	Point Type	Quality
183	2022-02-17 12:00:00	BETAM WIND	5378	2819379	3_BETAM_FDR8_8 WT91_LVRT	Status	Bad
184	2022-02-17 12:00:00	BETAM WIND	5379	2819380	3_BETAM_FDR8_8 WT28_LVRT	Status	Bad
185	2022-02-17 12:00:00	BETAM WIND	5380	2819381	3_BETAM_FDR8_8 WT30_LVRT	Status	Bad
186	2022-02-17 12:00:00	BETAM WIND	5381	2819382	3_BETAM_FDR8_8 WT63_LVRT	Status	Bad
187	2022-02-17 12:00:00	BETAM WIND	5382	2819383	3_BETAM_FDR8_8 WT75_LVRT	Status	Bad
188	2022-02-17 12:00:00	BETAM WIND	5383	2819384	3_BETAM_FDR8_8 WT109_LVRT	Status	Bad
189	2022-02-17 12:00:00	BETAM WIND	5384	2819385	3_BETAM_FDR8_8 WT33_LVRT	Status	Bad
190	2022-02-17 12:00:00	BETAM WIND	5385	2819386	3_BETAM_FDR8_8 WT27_LVRT	Status	Bad
191	2022-02-17 12:00:00	BETAM WIND	5386	2819387	3_BETAM_FDR8_8 WT106_LVRT	Status	Bad
192	2022-02-17 12:00:00	BETAM WIND	5387	2819388	3_BETAM_FDR8_8 WT161_LVRT	Status	Bad
193	2022-02-17 12:00:00	BETAM WIND	5388	2819389	3_BETAM_FDR8_8 WT79_LVRT	Status	Bad
194	2022-02-17 12:00:00	BETAM WIND	5389	2819390	3_BETAM_FDR8_8 WT81_LVRT	Status	Bad
195	2022-02-17 12:00:00	BETAM WIND	5390	2819391	3_BETAM_FDR8_8 WT20_LVRT	Status	Bad
196	2022-02-17 12:00:00	BETAM WIND	5391	2819392	3_BETAM_FDR8_8 WT78_LVRT	Status	Bad
197	2022-02-17 12:00:00	BETAM WIND	5392	2819393	3_BETAM_FDR9_9 WT2_LVRT	Status	Bad
198	2022-02-17 12:00:00	BETAM WIND	5393	2819394	3_BETAM_FDR9_9 WT43_LVRT	Status	Bad
199	2022-02-17 12:00:00	BETAM WIND	5394	2819395	3_BETAM_FDR9_9 WT14_LVRT	Status	Bad

(A Govt. of India Enterprise)

Southern Regional Load Despatch Centre

29, Race Course Cross Road, Bengaluru - 560009. CIN No: U40105DL2009G0I188682 Phone: 080 22254525, 22204325, 22252612, 22351146, Fax No: 080-22259219

Mobile: 9513243111, 9845782373.

Website: www.srldc.org, www.srldc.in, Email: srldccr@posoco.in, srldccroom@gmail.com



Real Time Telemetry Discrepancy Report

Message No: SRLDC/BT/2022/Feb/1 **Date:** 17-02-2022 12:15 Hrs

SL.No	TimeStamp	Station Name	IEC Address	SCADA Key	Point Name	Point Type	Quality
200	2022-02-17 12:00:00	BETAM WIND	5395	2819396	3_BETAM_FDR9_9 WT97_LVRT	Status	Bad
201	2022-02-17 12:00:00	BETAM WIND	5396	2819397	3_BETAM_FDR9_9 WT85_LVRT	Status	Bad
202	2022-02-17 12:00:00	BETAM WIND	5397	2819398	3_BETAM_FDR9_9 WT94_LVRT	Status	Bad
203	2022-02-17 12:00:00	BETAM WIND	5398	2819399	3_BETAM_FDR9_9 WT46_LVRT	Status	Bad
204	2022-02-17 12:00:00	BETAM WIND	5399	2819400	3_BETAM_FDR9_9 WT18_LVRT	Status	Bad
205	2022-02-17 12:00:00	BETAM WIND	5400	2819401	3_BETAM_FDR9_9 WT42_LVRT	Status	Bad
206	2022-02-17 12:00:00	BETAM WIND	5401	2819402	3_BETAM_FDR9_9 WT8_LVRT	Status	Bad
207	2022-02-17 12:00:00	BETAM WIND	5402	2819403	3_BETAM_FDR9_9 WT17_LVRT	Status	Bad
208	2022-02-17 12:00:00	BETAM WIND	5403	2819404	3_BETAM_FDR9_9 WT60_LVRT	Status	Bad
209	2022-02-17 12:00:00	BETAM WIND	5404	2819405	3_BETAM_FDR9_9 WT22_LVRT	Status	Bad
210	2022-02-17 12:00:00	BETAM WIND	5405	2819406	3_BETAM_FDR5_5 WT186_HVRT	Status	Bad
211	2022-02-17 12:00:00	BETAM WIND	5406	2819407	3_BETAM_FDR5_5 WT156_HVRT	Status	Bad
212	2022-02-17 12:00:00	BETAM WIND	5407	2819408	3_BETAM_FDR5_5 WT151_HVRT	Status	Bad
213	2022-02-17 12:00:00	BETAM WIND	5408	2819409	3_BETAM_FDR5_5 WT155_HVRT	Status	Bad
214	2022-02-17 12:00:00	BETAM WIND	5409	2819410	3_BETAM_FDR5_5 WT154_HVRT	Status	Bad
215	2022-02-17 12:00:00	BETAM WIND	5410	2819411	3_BETAM_FDR5_5 WT180_HVRT	Status	Bad
216	2022-02-17 12:00:00	BETAM WIND	5411	2819412	3_BETAM_FDR5_5 WT173_HVRT	Status	Bad

(A Govt. of India Enterprise)

Southern Regional Load Despatch Centre

29, Race Course Cross Road, Bengaluru - 560009. CIN No: U40105DL2009G0I188682 Phone: 080 22254525, 22204325, 22252612, 22351146, Fax No: 080-22259219

Mobile: 9513243111, 9845782373.

Website: www.srldc.org, www.srldc.in, Email: srldccr@posoco.in, srldccroom@gmail.com



Real Time Telemetry Discrepancy Report

Message No: SRLDC/BT/2022/Feb/1 **Date:** 17-02-2022 12:15 Hrs

SL.No	TimeStamp	Station Name	IEC Address	SCADA Key	Point Name	Point Type	Quality
217	2022-02-17 12:00:00	BETAM WIND	5412	2819413	3_BETAM_FDR5_5 WT172_HVRT	Status	Bad
218	2022-02-17 12:00:00	BETAM WIND	5413	2819414	3_BETAM_FDR5_5 WT99_HVRT	Status	Bad
219	2022-02-17 12:00:00	BETAM WIND	5414	2819415	3_BETAM_FDR5_5 WT158_HVRT	Status	Bad
220	2022-02-17 12:00:00	BETAM WIND	5415	2819416	3_BETAM_FDR5_5 WT168_HVRT	Status	Bad
221	2022-02-17 12:00:00	BETAM WIND	5416	2819417	3_BETAM_FDR5_5 WT101_HVRT	Status	Bad
222	2022-02-17 12:00:00	BETAM WIND	5417	2819418	3_BETAM_FDR5_5 WT165_HVRT	Status	Bad
223	2022-02-17 12:00:00	BETAM WIND	5418	2819419	3_BETAM_FDR5_5 WT141_HVRT	Status	Bad
224	2022-02-17 12:00:00	BETAM WIND	5419	2819420	3_BETAM_FDR8_8 WT11_HVRT	Status	Bad
225	2022-02-17 12:00:00	BETAM WIND	5420	2819421	3_BETAM_FDR8_8 WT91_HVRT	Status	Bad
226	2022-02-17 12:00:00	BETAM WIND	5421	2819422	3_BETAM_FDR8_8 WT28_HVRT	Status	Bad
227	2022-02-17 12:00:00	BETAM WIND	5422	2819423	3_BETAM_FDR8_8 WT30_HVRT	Status	Bad
228	2022-02-17 12:00:00	BETAM WIND	5423	2819424	3_BETAM_FDR8_8 WT63_HVRT	Status	Bad
229	2022-02-17 12:00:00	BETAM WIND	5424	2819425	3_BETAM_FDR8_8 WT75_HVRT	Status	Bad
230	2022-02-17 12:00:00	BETAM WIND	5425	2819426	3_BETAM_FDR8_8 WT109_HVRT	Status	Bad
231	2022-02-17 12:00:00	BETAM WIND	5426	2819427	3_BETAM_FDR8_8 WT33_HVRT	Status	Bad
232	2022-02-17 12:00:00	BETAM WIND	5427	2819428	3_BETAM_FDR8_8 WT27_HVRT	Status	Bad
233	2022-02-17 12:00:00	BETAM WIND	5428	2819429	3_BETAM_FDR8_8 WT106_HVRT	Status	Bad

(A Govt. of India Enterprise)

Southern Regional Load Despatch Centre

29, Race Course Cross Road, Bengaluru - 560009. CIN No: U40105DL2009G0I188682 Phone: 080 22254525, 22204325, 22252612, 22351146, Fax No: 080-22259219

Mobile: 9513243111, 9845782373.

Website: www.srldc.org, www.srldc.in, Email: srldccr@posoco.in, srldccroom@gmail.com



Real Time Telemetry Discrepancy Report

Message No: SRLDC/BT/2022/Feb/1 **Date:** 17-02-2022 12:15 Hrs

SL.No	TimeStamp	Station Name	IEC Address	SCADA Key	Point Name	Point Type	Quality
234	2022-02-17 12:00:00	BETAM WIND	5429	2819430	3_BETAM_FDR8_8 WT161_HVRT	Status	Bad
235	2022-02-17 12:00:00	BETAM WIND	5430	2819431	3_BETAM_FDR8_8 WT79_HVRT	Status	Bad
236	2022-02-17 12:00:00	BETAM WIND	5431	2819432	3_BETAM_FDR8_8 WT81_HVRT	Status	Bad
237	2022-02-17 12:00:00	BETAM WIND	5432	2819433	3_BETAM_FDR8_8 WT20_HVRT	Status	Bad
238	2022-02-17 12:00:00	BETAM WIND	5433	2819434	3_BETAM_FDR8_8 WT78_HVRT	Status	Bad
239	2022-02-17 12:00:00	BETAM WIND	5434	2819435	3_BETAM_FDR9_9 WT2_HVRT	Status	Bad
240	2022-02-17 12:00:00	BETAM WIND	5435	2819436	3_BETAM_FDR9_9 WT43_HVRT	Status	Bad
241	2022-02-17 12:00:00	BETAM WIND	5436	2819437	3_BETAM_FDR9_9 WT14_HVRT	Status	Bad
242	2022-02-17 12:00:00	BETAM WIND	5437	2819438	3_BETAM_FDR9_9 WT97_HVRT	Status	Bad
243	2022-02-17 12:00:00	BETAM WIND	5438	2819439	3_BETAM_FDR9_9 WT85_HVRT	Status	Bad
244	2022-02-17 12:00:00	BETAM WIND	5439	2819440	3_BETAM_FDR9_9 WT94_HVRT	Status	Bad
245	2022-02-17 12:00:00	BETAM WIND	5440	2819441	3_BETAM_FDR9_9 WT46_HVRT	Status	Bad
246	2022-02-17 12:00:00	BETAM WIND	5441	2819442	3_BETAM_FDR9_9 WT18_HVRT	Status	Bad
247	2022-02-17 12:00:00	BETAM WIND	5442	2819443	3_BETAM_FDR9_9 WT42_HVRT	Status	Bad
248	2022-02-17 12:00:00	BETAM WIND	5443	2819444	3_BETAM_FDR9_9 WT8_HVRT	Status	Bad
249	2022-02-17 12:00:00	BETAM WIND	5444	2819445	3_BETAM_FDR9_9 WT17_HVRT	Status	Bad
250	2022-02-17 12:00:00	BETAM WIND	5445	2819446	3_BETAM_FDR9_9 WT60_HVRT	Status	Bad

(A Govt. of India Enterprise)

Southern Regional Load Despatch Centre

29, Race Course Cross Road, Bengaluru - 560009. CIN No: U40105DL2009G0I188682 Phone: 080 22254525, 22204325, 22252612, 22351146, Fax No: 080-22259219

Mobile: 9513243111, 9845782373.

Website: www.srldc.org, www.srldc.in, Email: srldccr@posoco.in, srldccroom@gmail.com



Real Time Telemetry Discrepancy Report

Message No: SRLDC/BT/2022/Feb/1 Date: 17-02-2022 12:15 Hrs

Continued...

SL.No	TimeStamp	Station Name	IEC Address	SCADA Key	Point Name	Point Type	Quality
	2022-02-17				3_BETAM_FDR9_9		
251	12:00:00	BETAM WIND	5446	2819447	WT22_HVRT	Status	Bad
	2022-02-17				3_BETAM_FDR9_9		
252	12:00:00	BETAM WIND	5449	2819450	WT80_LVRT	Status	Bad
	2022-02-17				3_BETAM_FDR9_9		
253	12:00:00	BETAM WIND	5450	2819451	WT190_LVRT	Status	Bad
	2022-02-17				3_BETAM_FDR9_9		
254	12:00:00	BETAM WIND	5451	2819452	WT80_HVRT	Status	Bad
	2022-02-17				3_BETAM_FDR9_9		
255	12:00:00	BETAM WIND	5452	2819453	WT190_HVRT	Status	Bad

Please Note that this is in violation of Indian Electricity Grid Code (IEGC) Clause 4.6.4 "Reliable and efficient speech and data communication systems shall be provided to facilitate necessary communication and data exchange, and supervision/control of the grid by the RLDC, under normal and abnormal conditions. All users, STUs and CTU shall provide Systems to telemeter power system parameter such as flow, voltage and status of switches/ transformer taps etc. in line with interface requirements and other guideline made available by RLDC. The associated communication system to facilitate data flow up to appropriate data collection point on CTU's system, shall also be established by the concerned user or STU as specified by CTU in Connection Agreement. All users/STUs in coordination with CTU shall provide the required facilities at their respective ends as specified in the Connection Agreement"

It is here by requested to take immediate action in order to have complete visibility of the station/developer for reliable and secure System Operation.

-----End of the Message-----