## 5. Packing/Bundling

Material to be adequately dunnaged aboard ship with minimum 100 mm thick timbers to allow easy access for slinging. Ideally vertical gap of 75mm-100mm between every group of 4 bundles.

In bare bundles of approximately one metric tonne for six metre lengths and two Metric Tonnes for each twelve metre & fourteen metre lengths respectively.

Securely tied with adequate wire rod or signode straps with lifting bonds. (Certificate to be provided for the lifting bonds tensile strength)

## 6. Colour code

Each diameter and length to be colour marked – a different colour to be used for each size and specified both in mills packing list and as part of the "marks".

## 7. Labelling

Each bundle to have minimum of 3 securely affixed labels stipulating origin, weight, size, cast no/ heat number, 'RONLY' bearing the Cares Logo. Labels to be sufficiently robust as to remain legible after handling and storage for up to 18 months

O Chimmons