

Texas General Land Office Community Development and Revitalization Form 11.10 Progress Inspection Checklist

| Project Information | | | | |
|---|---|---------------------------------|--|--|
| GLO's Designated Representative ("GDR") Name: Waggoner | | Contract No. and/or WO: 3659466 | | |
| Applicant Name: sdfsd | | Co-Applicant Name: | | |
| Physical Address: | | | | |
| Building Contractor Name: | | Floor Plan: BONSAI (BON) | | |
| **Must be Completed Immediately Prior to Insulation and Drywall** | | | | |
| | General Inspection | | | |
| Yes No x N/A | Confirm which Green Standard applies. | | | |
| Yes No x N/A | Resilient roof photos verified: 1) Taped decking seams 2) Button cap nails used | | | |
| Yes No x N/A | Building permit and green tags in place and visible. | | | |
| Yes No X N/A | Confirm foundation municipal tag and engineer's report is issued (with the plans) and available (if applicable). | | | |
| Yes No X N/A | Verify it's framed according to plans, correct number of rooms, bathrooms, windows and double check elevation (option selection), roof, etc | | | |
| Yes No X N/A | At least one 36-inch entrance door on an accessible route served by no-step entrance or ramp | | | |
| Yes X No N/A | Check finished slab surface complete/plumbing entry points patched and cured | | | |
| X Yes No N/A | No subfloor areas of unevenness exceeding 3/8 inch per 36 inches | | | |
| X Yes No N/A | Confirm rough opening for interior passage doors will accommodate a 32-inch | | | |
| X Yes No N/A | door, unless the door provides access only to closet of less than 15 sq. ft. in area | | | |
| Yes No x N/A | Each hallway has a width of at least 36 inches and is level | | | |
| Yes No x N/A | Anchor bolts, washer, nuts, all tightened (if applicable) | | | |
| Yes No x N/A | 2x6 joist hangers are installed at attic/all areas, with appropriate number of nails | | | |
| Yes No x N/A | Check AC drain installed and visually clear of debris | | | |
| Yes No x N/A | Gas and electric meter location reasonably near home | | | |
| Yes No x N/A | Poly spray foam at slab and roof baffles done as required | | | |
| Yes No x N/A | All trade nail guards in place | | | |
| Yes No x N/A | Framing is free from irregularities such as excessive mud, mildew, knots or flaws notching or scabbing, or overall damage. Note unusual nail patterns/usage | | | |
| Yes No x N/A | Inside of home is free from debris and swept | | | |
| Yes No X N/A | All trash is picked up and placed in trash area/dumpster | | | |
| Inspector Observation Rema | arks: | | | |
| Form 11.10 - Progress Inspection Checklist August 2022 Page 1 | | | | |

Disclaimer: The Texas General Land Office has made every effort to ensure the information contained on this form is accurate and in compliance with the most up-toacte CDBG-DR and or CDBG-MT federal rules and regulations, as applicable. It should be noted that the Texas General Land Office assumes no liability or

responsibility for any error or omission on this form that may result from the interim period between the publication of amended and/or revised federal rules and regulations and the Texas General Land Office's standard review and update schedule.



Texas General Land Office Community Development and Revitalization Form 11.10 Progress Inspection Checklist

| Interior Inspection | | | | |
|---|---|--|--|--|
| Yes No x N/A | Each bathroom is reinforced with blocking for potential grab bar installation as | | | |
| | required. (32- 38" High Minimum, ADA 2010) | | | |
| Yes No x N/A | Verify water source located on a short wall, control is on either long or short wall | | | |
| | of rollin shower when a permanent seat is present (if applicable) ADA 2010. | | | |
| Yes No x N/A | Check plan on sizes of ceiling joists and rafters. Check doubles around openings | | | |
| Yes No x N/A | Studs are installed at 16 inches on center | | | |
| Yes No x N/A | Check windstorm clips are present | | | |
| Yes No x N/A | All receptacles (electric outlets) at least 15 inches above floor | | | |
| Yes No X N/A | Light switches, fan switches and thermostat no higher than 48 inches from floor | | | |
| | Each breaker box is located not higher than 48 inches above the floor inside the | | | |
| Yes No X N/A | building on the first floor in the utility room or garage; unless the applicable | | | |
| | building code or codes do not prescribe another location for the breaker boxes | | | |
| Yes No X N/A | Check all electrical clears door casings, and that it is not behind door swing | | | |
| Yes No X N/A | Smoke detector and carbon monoxide detector locations wired | | | |
| Yes No x N/A | All walls and corners are plumb | | | |
| Yes No X N/A | Toilets at 17-19 inches on center from side wall | | | |
| Yes No X N/A | Space is provided on both sides of doors for casing | | | |
| Inspector Observation Remar | ·ks: | | | |
| | | | | |
| | Windows and Doors | | | |
| Yes No x N/A | Verify windows are compliant with windstorm/Green Standard requirements | | | |
| Yes No x N/A | Door and window headers are sized properly, load-bearing and non load-bearing | | | |
| 105 100 X 10/11 | House wrap is installed in all window and door openings prior to installation of | | | |
| Yes No X N/A | windows/doors | | | |
| Inspector Observation Remarks: | | | | |
| inspector Observation Remarks. | | | | |
| | | | | |
| | Exterior Inspection | | | |
| Yes No x N/A | Exterior walls are plumb and straight (no bows) | | | |
| Yes No x N/A | Lap Siding: 'HZ10' Hardie Plank, 6 1/4", smooth or textured finish, pre-primed. | | | |
| | (Installed measurement 5" visible) | | | |
| Yes No x N/A | All siding is free of deficiencies. Note any cracked, dented, bowed, or chipped | | | |
| | siding that requires replacement | | | |
| Yes No x N/A | All butt-joints are less than 1/8 inch, both siding and trim | | | |
| orm II 10 - Progress Inspection Chec | Klist August 2022 Page 2 Use trim nails on 1x4 Hardie trim (siding) | | | |
| Yes No X N/A | All roof jacks installed | | | |
| Disclaimer: The Texas General Land Office ha. ate CDBG-DR and or CDBC-MI Jederal rule. | made every effort to ensure the information contained on this form is accurate and in compliance with the most up-to- Every and read the supplicance with the most up-to- and regulators, and pyricance with incastical and size each of time of fice assumes no liability or | | | |
| | with that may result from the interim period between the publication of amended and/or revised federal rules and | | | |



Texas General Land Office Community Development and Revitalization Form 11.10 Progress Inspection Checklist

| Yes No x N/A | Sheathing on the house is cut to | tight, straight, without gaps or holes, and nailed per |
|---|---|--|
| | plan specifications | |
| Yes No x N/A | Two exterior hose bibs (front/back). | |
| Yes No x N/A | Verify minimum ½ inch expansion gap: between siding and porch floor, and | |
| | between ramp and siding | |
| Inspector Observation Rema | arks: | |
| | | |
| | Roof/Atti | ic |
| Yes No x N/A | HVAC ductwork in place properly installed, no gaps or openings. | |
| Yes No x N/A | AC intakes/returns are on the main floor | |
| Yes No x N/A | All windstorm/fortified appurtenances are in place | |
| Yes No x N/A | Roof sheathing is flat, no valleys or high places. Radiant barrier installed. | |
| Yes No x N/A | Roof decking is installed with small gap 1/16–1/8 inch on all end joints. | |
| Yes No x N/A | Roof sheathing is nailed per plan and windstorm requirements. | |
| Inspector Observation Rema | arks: | |
| | | |
| | Signature | as . |
| Under papelties of parium, I a | | nted in this document is true and accurate to the |
| | | oviding false representations herein constitutes an |
| | | result in my ineligibility to participate in Programs |
| that will accept this document | - | |
| | | |
| | | or statement to HUD may be subject to civil or |
| criminal penalties under 18 | U.S.C. 287, 1001 and 31 U.S.C. | . 3729 |
| Inspector Printed Name: | | |
| 1 | | 1 |
| | | |
| | | Date: |
| | | |
| Inspector Signature: Image not | found or type unknown | |
| Superintendent Drinted Nam | an fda | |
| Superintendent Printed Nan | ie. rug | 1 |
| | | |
| | | Date: |
| Form 11.10 - Progress Inspection Ch | ecklist August | 2022 Page 3 |
| Superintendent Signature: | | |
| Disclaimer: The Texas General Land Office h | nas made every effort to ensure the information | contained on this form is accurate and in compliance with the most up-to |

dates DBG DBG and Company of the substitution of the substitution