

Texas General Land Office Community Development and Revitalization Form 11.10 Progress Inspection Checklist

	Project Information	
GLO's Designated Representative ("GDR") Name: Waggoner		Contract No. and/or WO: 3659466
Applicant Name: sdfsd		Co-Applicant Name:
Physical Address:		
Building Contractor Name:		Floor Plan: BONSAI (BON)
Must	be Completed Immediately Prior to Insula	tion and Drywall
	General Inspection	
Yes No x N/A	Confirm which Green Standard applies.	
Yes No x N/A	Resilient roof photos verified: 1) Taped of	decking seams 2) Button cap nails used
Yes No x N/A	Building permit and green tags in place a	and visible.
Yes No x N/A	Confirm foundation municipal tag and engineer's report is issued (with the plans and available (if applicable).	
Yes No x N/A	Verify it's framed according to plans, correct number of rooms, bathrooms, windows and double check elevation (option selection), roof, etc	
Yes No x N/A	At least one 36-inch entrance door on an accessible route served by no-step entrance or ramp	
Yes x No N/A	Check finished slab surface complete/plu	imbing entry points patched and cured
X Yes No N/A	No subfloor areas of unevenness exceedi	ing 3/8 inch per 36 inches
X Yes No No N/A	Confirm rough opening for interior passa door, unless the door provides access onl	
Yes No x N/A	Each hallway has a width of at least 36 in	
Yes No x N/A	Anchor bolts, washer, nuts, all tightened	
Yes No x N/A	2x6 joist hangers are installed at attic/all	
Yes No x N/A	Check AC drain installed and visually cle	
Yes No x N/A	Gas and electric meter location reasonable	
Yes No x N/A	Poly spray foam at slab and roof baffles	
Yes No x N/A	All trade nail guards in place	-
Yes No x N/A	Framing is free from irregularities such a notching or scabbing, or overall damage.	
Yes No x N/A	Inside of home is free from debris and sv	
Yes No x N/A	All trash is picked up and placed in trash	*
Inspector Observation Rem		-
Form 11.10 - Progress Inspection Cl	hecklist August 2022	Page 1

Disclaimer: The Texas General Land Office has made every effort to ensure the information contained on this form is accurate and in compliance with the most up-to-atte CDBG-DR and or CDBG-MT federal rules and regulations, as applicable. It should be noted that the Texas General Land Office assumes no liability or

responsibility for any error or omission on this form that may result from the interim period between the publication of amended and/or revised federal rules and regulations and the Texas General Land Office's standard review and update schedule.



Texas General Land Office Community Development and Revitalization Form 11.10 Progress Inspection Checklist

Interior Inspection				
Yes No x N/A	Each bathroom is reinforced with blocking for potential grab bar installation as			
	required. (32- 38" High Minimum, ADA 2010)			
Yes No X N/A	Verify water source located on a short wall, control is on either long or short wall			
	of rollin shower when a permanent seat is present (if applicable) ADA 2010.			
Yes No x N/A	Check plan on sizes of ceiling joists and rafters. Check doubles around openings			
Yes No x N/A	Studs are installed at 16 inches on center			
Yes No x N/A	Check windstorm clips are present			
Yes No x N/A	All receptacles (electric outlets) at least 15 inches above floor			
Yes No X N/A	Light switches, fan switches and thermostat no higher than 48 inches from floor			
	Each breaker box is located not higher than 48 inches above the floor inside the			
Yes No x N/A	building on the first floor in the utility room or garage; unless the applicable			
	building code or codes do not prescribe another location for the breaker boxes			
Yes No X N/A	Check all electrical clears door casings, and that it is not behind door swing			
Yes No X N/A	Smoke detector and carbon monoxide detector locations wired			
Yes No x N/A	All walls and corners are plumb			
Yes No X N/A	Toilets at 17-19 inches on center from side wall			
Yes No X N/A	Space is provided on both sides of doors for casing			
Inspector Observation Remar	·ks:			
	Windows and Doors			
Yes No x N/A	Verify windows are compliant with windstorm/Green Standard requirements			
Yes No x N/A	Door and window headers are sized properly, load-bearing and non load-bearing			
105 100 A 17/11	House wrap is installed in all window and door openings prior to installation of			
Yes No X N/A	windows/doors			
Inspector Observation Remar				
inspector observation remark				
	Exterior Inspection			
Yes No X N/A	Exterior walls are plumb and straight (no bows)			
Yes No X N/A	Lap Siding: 'HZ10' Hardie Plank, 6 1/4", smooth or textured finish, pre-primed.			
	(Installed measurement 5" visible)			
Yes No x N/A	All siding is free of deficiencies. Note any cracked, dented, bowed, or chipped			
	siding that requires replacement			
Yes No x N/A	All butt-joints are less than 1/8 inch, both siding and trim			
orm 1110 - Progress Inspection Che	Use trim nails on 1x4 Hardie trim (siding) Page 2			
Yes No x N/A	All roof jacks installed			
Disclaimer: The Texas General Land Office ha. iate CDBG-DR and or CDBG-MI federal rule.	made every effort to ensure the information contained on this form is accurate and in compliance with the most up-to- Every door and window location and size are confirmed and regulations, as applicable. It should be noted may he reads General Luna office assumes no liability or			
respons bility for any error ar amission on this	whithat may result from the interim period between the publication of amended and/or revised federal rules and			



Texas General Land Office Community Development and Revitalization Form 11.10 Progress Inspection Checklist

Yes No x N/A	Sheathing on the house is cut plan specifications	Sheathing on the house is cut tight, straight, without gaps or holes, and nailed per		
Yes No x N/A		Two exterior hose bibs (front/back).		
Yes No x N/A	Verify minimum ½ inch expa	Verify minimum ½ inch expansion gap: between siding and porch floor, and		
Inspector Observation Re	emarks:			
	Roof/Att	tic		
Yes No x N/A	HVAC ductwork in place pro	operly installed, no gaps or openings.		
Yes No x N/A	AC intakes/returns are on the	AC intakes/returns are on the main floor		
Yes No x N/A	All windstorm/fortified appur	All windstorm/fortified appurtenances are in place		
Yes No x N/A	Roof sheathing is flat, no vall	Roof sheathing is flat, no valleys or high places. Radiant barrier installed.		
Yes No x N/A	Roof decking is installed with	Roof decking is installed with small gap 1/16–1/8 inch on all end joints.		
Yes No x N/A	Roof sheathing is nailed per p	Roof sheathing is nailed per plan and windstorm requirements.		
Inspector Observation Re	emarks:			
	Signatur	es		
Under penalties of perjury,		ented in this document is true and accurate	to the	
	•	oviding false representations herein constitutions		
act of fraud. False, mislead	ing or incomplete information may	y result in my ineligibility to participate in	Programs	
that will accept this docume	ent.			
Warning: Any nerson wh	o knowingly makes a false claim	or statement to HUD may be subject to	civil or	
	18 U.S.C. 287, 1001 and 31 U.S.C		CIVII OI	
Inspector Printed Name:				
		Deter		
		Date:		
Inspector Signature:				
Image not found or type unknown				
Superintendent Printed Name: fdg				
Form 11.10 Pro 7	. Charlet	Date:	~~ 2	
Form 11.10 - Progress Inspection Superintendent Signature		Pag	ge 3	
		on contained on this form is accurate and in compliance with t	the most up-to-	
	2 22 2			

date GREG LPS and complete of the control of the co