

Note: Signal on colored lines is inverted. Mode: PWM default

Input/Output Functions

\Box	Input					Output			
	V _{ref}	IN1	IN2	SB	PWM/OSC	I _O (100%) (typ.)	OUT1	OUT2	Mode
osc	0 to 3 V	Н	Н	Н	Capacitor	_	L	L	Short brake
		L	н	н	Capacitor	Vref 6-RSA	L L	Constant-current chopping	CCW Short brake
		Н	L	н	Capacitor	Vref 6-RSA	Constant-current chopping	L L	CW Short brake
		L	L	Н	Capacitor	_	OFF (Hi-Z)		Stop
		x	х	L	Capacitor	_	OFF (Hi-Z)		Standby
PWM	4.5 to 5.5 V	Н	н	Н	H L		L	L	Short brake
		L	н	Н	Н		L	Н	CCW
					L		L	L	Short brake
		Н	L	Н	н		н	L	CW
					L		L	L	Short brake
		L	L	Н	H L		OFF (Hi-Z)		Stop
		×	x	L	H L		OFF (Hi-Z)		Standby

Note: X = Don't care