

ANNEXURE — Submission Report

District: Guntur | FIR: DEMO/GT/2026/006 | Road: Other

A. Location Details

Place of Accident: Tenali Railway Station Road Crossing
Mandal: Tenali
Police Station: Tenali I Town
FIR Number: DEMO/GT/2026/006
GPS Coordinates: 16.2390, 80.6438
Road Type: Other
Date: 24/1/2026
Time: 09:50

B. Vehicles Involved

#	Registration Number	Class / Type
1	AP26 TA 6631	Passenger Auto
2	AP07 NN 2100	Delivery Van

C. Driver Details

#	Name	D.L Number	Licensing Authority
1	B. Nagesh	AP2620200076542	RTA Bapatla
2	V. Nagaraju	AP0720180062300	RTA Guntur

D. Victim Details

Persons Died: 0
Persons Injured: 5

CAUSATIVE ANALYSIS

A. Driver Related Causes

- Driver made an error of judgment during overtaking.

B. Vehicle Condition Related Causes

- The tyres were not in proper shape / worn out.

C. Road Engineering Related Factors

Junctions

- Railway Crossing.

Nature of Area

- Pilgrim centre / shandy.

Signages and Road Markings

- Signages are erected but not in proper shape / visibility.

Approval Chain

Prepared by (IO/SHO)		Verified by (DSP/CI)	Approved by (SP/Addl. SP)
Name	SI Venkata Suresh	DSP Lakshmi Narayana	SP Arif Hafeez
Designation	Sub-Inspector, Traffic Investigation Wing, Guntur	DSP Traffic, Guntur	Superintendent of Police, Guntur
Date	25/1/2026	26/1/2026	27/1/2026