

PulseCare Field Correction Test Notice FC-2026-04

Synthetic data only. Not for real device operation.

Affected model: VSM-100 Pro

Affected software: 2.5.0 through 2.5.3

Affected lots: L26A01 through L26A07

Target software after correction: 2.5.4

The applicability result must be computed by the deterministic policy tool.