
Engineering stress (MPa)
Engineering strain (%)
0
5
10
15
20
25
0
10
20
30
Pure epoxy
L/L/P
L/P/L
P/L/P
P/P/L