
P/P/L
Engineering stress (MPa)
0
5
10
15
20
0
2
4
6
8
10
Engineering strain (%)
Specimen 1