

CURVA DENIM / WHOLESALE PROGRAM

SUPPLIER QUALITY MANUAL

Quality gates for plus-size denim materials, fit, wash, sewing, inspection, packing, nonconformance and claims. Buyer specifications always take precedence.

Document ID	CD-QM-001
Revision	1.0
Issue date	2026-08-26
Audience	Suppliers, mills, laundries, factories, QC teams and buyers
Market	United States
Status	Buyer review / controlled working document

Contact

wholesale@curvadenim.com | www.curvadenim.com

Commercial terms, measurements, test limits and compliance claims become binding only when confirmed in the signed quotation, purchase order and approved specification.

1. Quality governance

Purpose

Define minimum process controls for Curva Denim wholesale programs while preserving buyer-specific requirements.

Gate	Owner	Required evidence	Release authority
Material approval	Mill / product team	Swatch, lot data, test plan	Buyer / authorized product owner
PP sample	Factory / technical team	Approved measurements, construction, wash, trims and labels	Buyer
Bulk start	Factory	Signed PO, latest tech pack, approved PP sample and BOM	Factory QA + buyer
Final release	Independent or agreed QC	Inspection report, tests and packing records	Buyer / authorized QA

2. Material and fabric control

No single fiber blend is mandatory for every silhouette. Performance targets are selected by style, customer promise and care method.

Control	Required record	Acceptance basis
Fiber composition	Supplier declaration and laboratory verification when required	Approved BOM and truthful label claim
Weight and width	Lot inspection record	Approved swatch/specification
Stretch and growth	Test method, direction, load, recovery time and results	Style-specific target
Dimensional stability	Defined care cycles and measurement method	Buyer-approved limits
Skew / twist	Before-and-after wash result	Buyer-approved limits and visual standard
Crocking and laundering	Method, grade and approved shade reference	Buyer test protocol
Strength	Tear/tensile/seam method and results when required	Risk-based test plan
Restricted substances	Supplier declaration and lab report if required	Buyer RSL and destination law

3. Fit, grading and measurement

Plus-size patterns must be developed and validated for the intended body and silhouette; simple proportional enlargement is not an approval method.

Control point	Minimum requirement
Measurement definition	Diagram, garment state, measuring tool, tension, units, base size and tolerance
Fit sample	Correct fit model(s), movement review and documented comments
Grade validation	Review upper, base and lower sizes; add breakpoint rules when linear grading is unsuitable
Length strategy	Confirm petite/regular/tall or buyer-approved inseam plan
Golden sample	Signed sample and sealed measurement/wash standard retained by factory and buyer
Bulk audit	Measure agreed size distribution; record actual values, not pass/fail only

4. Wash, shade and appearance

Stage	Control
Lab development	Wash recipe, chemicals, water/temperature/time parameters and approved target
Shade approval	Master standard and buyer-approved shade band; identify lot and panel risk
Bulk segregation	Do not mix fabric or wash lots within a garment or retail pack unless approved
Appearance	Review whiskers, abrasion, hand feel, tint, unevenness, stains and local damage
Post-wash measurement	Measure only in the defined conditioning state and after the specified care cycle
Records	Retain recipe version, sample, lot IDs, inspection images and corrective actions

5. Sewing, hardware and workmanship

Area	Control requirement
Seams	Define stitch class, seam type, SPI, thread ticket and reinforcement by operation
Crotch / stress points	Use approved seam construction and bar tacks; verify seam performance
Pockets and loops	Placement templates, reinforcement and symmetry checks
Hardware	Approved finish, attachment method, pull test protocol and sharp-edge check
Needles	Needle control and broken-needle procedure; detection if buyer requires
Visual quality	No open seams, skipped stitches, puckering, contamination, holes or unapproved repairs

6. Inspection and release

Sampling level and AQL are not universal legal values. They must be agreed in the PO/QC plan. No shipment may be released solely because measurements pass.

Inspection	Timing	Scope
Incoming	Before cutting	Fabric lot, shade, width, defects, shrinkage and supporting records
Pilot / first output	Start of sewing and wash	Construction, measurements, appearance and process settings
Inline	During bulk	Workmanship trends, critical operations, shade and corrective action
Pre-final	Before packing completion	Size set, wash, labels, assortment and packing
Final	Finished packed goods	Quantity, sampling, measurements, workmanship, labels, packing and records

7. Packaging and traceability

Requirement	Record
Unit identification	Style, color, size, PO, barcode and country-of-origin data as approved
Packing	Folding/hanger method, protective materials and buyer-required warning text
Cartons	Dimensions, weight, quantity, size ratio, carton marks and carton sequence
Traceability	Fabric, wash, sewing, packing and inspection lot linkage
Retention	Approved samples, test reports, inspections and shipment records retained for the contractual period

8. Nonconformance, CAPA and claims

Step	Required action
Contain	Stop affected process; identify and segregate suspect material or goods
Notify	Report scope, PO, lots, quantities, images and immediate risk
Investigate	Use documented root-cause analysis based on evidence
Correct	Define rework/replacement/disposition; buyer approval required
Prevent	Update process, training, specification or supplier controls
Verify	Confirm effectiveness with repeat inspection or testing
Claims	Handle notice, evidence, mitigation and remedy under signed commercial terms; no automatic acceptance

9. Forms and revision control

Required controlled forms: material approval, wash standard, PP approval, measurement report, inline report, final inspection, packing audit, nonconformance report, CAPA and deviation request.

Revision	Date	Summary	Owner	Approval
1.0	2026-08-26	Initial B2B plus-size denim quality manual	Curva Denim	_____

This manual is a process-control framework, not a product certificate. Buyer specifications, applicable law and signed order terms govern.