Dilapidation Survey Report (SAMPLE)

This is demo data generated by DilapTrack for testing.

Scope: external condition of dwelling, outbuildings, fences, driveway and access.
Method: visual inspection with dated, captioned photographs.

Summary of existing condition:
- Hairline cracking to driveway crossover (approx. 0.5 mm).
- Minor cracking to render on dwelling north wall.
- Boundary fence posts sound; wires slack in places.
- Access track in fair condition, minor rutting.

Refer to the photographic record in DilapTrack.