

PPE Safety Guide

Approved worker rules and site regulations from the SentinelLoop knowledge base. These instructions support factory safety practice. They do not replace trained emergency responders or a competent person's isolation and repair work.

Immediate worker actions

1. Wear the personal protective equipment required for the task and area.
2. Replace damaged helmets, gloves, visors, or hearing protection immediately.
3. Use hearing protection in CNC bays and other high-noise zones.
4. Do not enter a restricted area without the PPE posted at the entry.
5. Keep eye and face protection on when handling chemicals, sparks, or flying debris.
6. Report missing or damaged PPE through the site safety process.
7. Do not share damaged or contaminated PPE with another worker.

Site regulations

1. PPE requirements posted at area entry points are mandatory, not optional.
2. Safety footwear, high-visibility clothing, and head protection apply in designated bays.
3. Eye protection is required in machining, grinding, welding, and chemical handling areas.
4. Hearing protection is required wherever noise signage or high-noise equipment is present.
5. Respiratory protection is used only with fit, training, and the filter specified for the hazard.
6. Damaged, expired, or contaminated PPE must be withdrawn and replaced.
7. Visitors and contractors must wear the same area PPE as site workers.
8. PPE storage must be clean and dry; do not leave helmets or gloves on oily floors.
9. Supervisors must not allow work to start if required PPE is missing.
10. Records of issue and replacement support incident and audit reviews.

Worker duties

1. Inspect PPE before each use for cracks, tears, missing straps, or poor seal.
2. Wear PPE for the whole task, including short jobs and walk-throughs.
3. Clean and store reusable PPE after use according to the area instruction.
4. Ask for the correct size or type if the issued PPE does not fit safely.
5. Report skin irritation, fogged visors, or equipment that prevents safe work.

Prohibited actions

1. Do not enter a PPE-required zone with helmets carried instead of worn.
2. Do not modify PPE by cutting, painting, or drilling holes in it.

3. Do not use another person's contaminated gloves, masks, or ear plugs.
4. Do not treat PPE as a substitute for guarding, ventilation, or isolation.

Always follow instructions from trained safety or emergency personnel.