



PROPVIGIL

Monitor, Maintain, and Report: Trusted Property Care

Site Inspection Report

Vacant site · Scheduled quarterly visit

PROPERTY REFERENCE	PV-2026-0041
SITE	Site No. 00, 0th Cross, [Layout], Bengaluru 5600XX
DIMENSIONS	30 x 40 ft — 1,200 sq ft
OWNER	[Owner name]
VISIT DATE	14 August 2026
TIME ON SITE	10:30 to 11:15 IST
INSPECTED BY	[Inspector name], PropVigil
REPORT ISSUED	14 August 2026
VISIT NUMBER	3 of 4 — current plan year

STATUS AT THIS VISIT:

ACTION RECOMMENDED — see page 5

IN ONE LINE

The site is secure and the boundary is unchanged. Construction waste has been dumped along the northern edge since the last visit, and overgrowth has reached roughly knee height across the site. Neither is urgent. Both are worth clearing before the next monsoon.

CHECKED AT THIS VISIT

● Boundary markers	All four present, positions unchanged
● Compound wall / fencing	Intact. Minor rust on gate hinge
● Encroachment	None observed
● Waste and debris	Construction debris, northern edge — new
● Overgrowth	Knee height across site — action advised
● Access road	Motorable. No obstruction
● Ownership signage	Present and legible
● Standing water	None
● Notices or markings	None on or near the site
● Neighbouring activity	Construction on adjoining plot — monitoring

CHANGED SINCE LAST VISIT — 14 AUGUST 2026

Two changes. Construction debris has appeared along the northern boundary, most likely from the adjoining plot where building work began recently. Overgrowth has increased from ankle to knee height. Everything else is as recorded at the previous visit.

WHAT WE RECOMMEND

Clear the debris and cut back the overgrowth. Quotation on page 5.
Nothing will be carried out until you approve it in writing.

We photograph from the same four positions on every visit, so consecutive reports can be compared directly. Each image carries its GPS coordinates and the date and time it was taken.

**POSITION A****North-east corner, facing south-west**

Wide shot showing full site, visible boundaries and adjoining plot.

Geotag 12.9716 N, 77.5946 E • 14 Aug 2026

**POSITION B****South-west corner, facing north-east**

Opposite wide shot. Together A and B cover the whole site.

Geotag 12.9716 N, 77.5946 E • 14 Aug 2026

**POSITION C****Road frontage, facing the site**

Access, gate, ownership signage and approach condition.

Geotag 12.9716 N, 77.5946 E • 14 Aug 2026

**POSITION D****Centre of site, facing north**

Ground condition, overgrowth height and dumping examination.

Geotag 12.9716 N, 77.5946 E • 14 Aug 2026

BOUNDARY AND MARKERS

**Marker 1 — NE**

Close shot of boundary stone

**Marker 2 — SE**

Same angle each visit

**Gate and hinge**

Detail of noted hinge rust

WASTE AND OVERGROWTH — ACTION ITEMS

**Debris — northern edge**

Dumped construction material along boundary

**Overgrowth — site centre**

Height shown against marked pole

VIDEO WALK-THROUGH

A continuous walk of the site boundary is sent with this report by WhatsApp. Duration approx. 2 minutes.

The same frame, three months apart. One report is a snapshot. Four reports are a record.



WHAT THE COMPARISON SHOWS

Boundary line unchanged. Marker positions unchanged. Debris present in the current frame and absent in the previous one. Overgrowth visibly higher.

RECOMMENDED ACTION AND COST

WORK	WHY	QUOTED
Debris removal and disposal	Bye-law 18(1)(b) obligation	Quoted Separately
Weed and overgrowth cutting	Monsoon, pests, standing water	Quoted Separately
Gate hinge treatment	Preventive anti-rust	Included Free

Quoted separately and approved by you in writing before anything starts. You receive the vendor invoice, the disposal receipt where the facility issues one, and photographs of the completed work.

EVERY PHOTOGRAPH IS VERIFIABLE

Each image in this report carries its original EXIF metadata: GPS coordinates, date, time and device. We have not stripped it. Ask us and we will send you the original files so you can check them yourself.

WHY WE SHOOT FROM FIXED POSITIONS

Photographs taken from the same four positions every visit cannot easily be reused. The light, the season and the ground conditions differ each time, and a repeated image is obvious when the frames are placed side by side. The metadata settles it either way.

WHO VISITED

This visit was carried out by [Inspector name] on 14 August 2026, between 10:30 and 11:15 IST. If you have a question about anything in this report, there is a named person who was there to answer it.

WHAT WE DID NOT DO

- We did not enter or alter the property beyond what is needed to inspect and photograph it.
- We did not carry out any work or spend any money. Nothing is done without your written approval.
- We do not hold Power of Attorney for this property and we do not hold your original documents.
- We do not give legal advice. Where a matter needs a lawyer, we say so.

QUESTIONS ABOUT THIS REPORT**V P Srinivasa · +91 92421 43775 · call or WhatsApp**

PropVigil, a unit of Sai Krupa Associates, Bengaluru. We reply within one working day.