

Deviation Record



Division - Project : Manufacturing and Development - Deviation			TR# : 40713134
Current State	Closed - Done	Date Created	08-Aug-2024 3:29 PM
In State Since	13-Aug-2024 11:00 AM		

Overview

Ownership / Timing Information

Originator	DeWees, Samuel	Reported By	Mapp, Christopher
Date Discovered	08-Aug-2024	Date Occurred	08-Aug-2024
Due Date	07-Sep-2024	Assigned To	Neff, Benjamin
Site	IDAP	Plant	IDAP
Flow Team	Pack	Process Team	Vial Packaging - Line 13

Deviation Information

Title	L13 - Failed Yield Batch D729596D
Title (Non English)	No data entry
Record Type	Quality
Related TRs	No data entry
Description	On 08AUG2024 while finishing batch D729596D a case packer crash pushed a cases on the floor causing the final yield to be 95.18. This is lower than the L13 Lower Limit of 95.89 per 8002-TOOL-04.
Immediate Steps Taken	Christopher Mapp notified David Bowman. Operations cleared the area and per 001-007288 (Product Reintroduction in IDAP Packaging) a dropped vial/case on the floor would be discarded and not forward processed on that batch. There is no impact to product quality because all impacted vials were discarded, accountability reconciled to zero and line clearance and inspection passed. On 09AUG2024, the Vial Packaging process team triaged this event as a Minor Deviation.

Equipment Information Grid

Equipment ID	Equipment Site Description	Equipment Description	Location Code	GxP Impact Classification	Equipment Detail
No data entry	No data entry	No data entry	No data entry	No data entry	No data entry

Product - Material Info

Data Sources/Rationale	Data source includes PMX. The scope of this event is limited to Batch D729596D because this the batch with the crash at the case
------------------------	---

Deviation Record



Division - Project : Manufacturing and Development - Deviation

TR# : 40713134

packer resulting in a failed yield.

Product - Material Info Grid

Batch Number	Material Number	Material Description	Scope
D729596D	HI0310001ZB	HUMULIN N INJ 100IU/ML10MLX 1 VIAL ZB	No data entry

Quality

Quality Details

Deviation Classification Q	Minor	Assessor - Q	Bahena-Garcia, Omar
Classification Rationale - Q	This failed yield event was discovered within the controls in place to protect/assure product quality. There is no product CQA impact and there is no regulatory commitment concern. There is no GMP compliance concern and this event was within the validated state of the process. Per the deviation evaluation questions listed in 001-007747, this is a minor deviation.		

Quality System Grid

Quality Management System	Global Standard
Packaging and Labeling	GQS501 Packaging Operations for Finished Product

Occurrence Type Categorization

Deviation Category	Deviation Type
Product, Component, or Material Property	Yield

Assessment Completed - Q?

Yes

Minor Deviation

Deviation Investigation Details

Assigned To	Neff, Benjamin	Team Members	No data entry
Investigation Summary	Who: Christopher Mapp discovered. What: A case packer crash pushed a case on the floor causing the final yield to be 95.18. This is lower than the L13 Lower Limit of 95.89 per 8002-TOOL-04. When: Deviation identified on 08AUG2024. Deviation occurred on 08AUG2024 Where: Line 13 Vial Packaging Why: The likely root cause was the case was imperfect and did not open correctly when the machine attempted to load bundles. This caused a crash in the case packer and dropped the cases. There is no impact to product quality because all impacted vials were discarded, accountability reconciled to zero and line clearance and inspection passed.		

Document Grid

Document ID	Document Version	Document Title	Sub Process	Reason For Adding
No data entry	No data entry	No data entry	No data entry	No data entry

Deviation Record



Division - Project : Manufacturing and Development - Deviation

TR# : 40713134

Root Cause (RC) Grid

Causal Factor Type	Major Root Cause Category	Near Root Cause	Root Cause
9 Material/Product Problem Issue	79 Material/Parts and Product Issue	N/A	N/A

CAPA Overview

There are no recommended CAPAs for this event.

Effectiveness Check Required?

No

File Attachment(s)

File Attachment(s)

No data entry

Date Information

Date Information

Due Date	07-Sep-2024 12:00 AM	Original Due Date	No data entry
Proposed Due Date	No data entry		
Past Due Date?	No		
Past Due Date Rationale	No data entry		

Date Change Approvers

Date Change Org Unit Approver	No data entry	Date Change Quality Approver	No data entry
Date Change HS Approver	No data entry	Date Change Env Approver	No data entry

Date Change Approvers Grid

Approver Role	Approver Name
No data entry	No data entry

Workflow Date Information

Date Submitted	09-Aug-2024 9:19 AM	Date Approved	13-Aug-2024 10:58 AM
Date AI Complete	No data entry	Date AI Approved	No data entry
Date Assessment Complete	09-Aug-2024 3:40 PM	Date Submitted for Approval	13-Aug-2024 7:59 AM
Date Implementation Complete	No data entry		

Deviation Record



Division - Project : Manufacturing and Development - Deviation

TR# : 40713134

Approver Information

Approvers

Organizational Unit Approver	Kruse, Aaron	Quality Approver	Bahena-Garcia, Omar
Health and Safety Approver	No data entry	Environmental Approver	No data entry

Approvers Grid

Approver Role	Approver Name
No data entry	No data entry

Pvt. Deviation Approvers Grid

Private Approver Role	Private Approver
No data entry	No data entry

Signature Activity

Activity	Activity Summary	Signed By	Date Performed
Approval	13-Aug-2024 09:18 (GMT-4:00) : [Approval] was performed by: Aaron Kruse , PID-183275 Auto Schedule interface scheduled approvers	Kruse, Aaron	13-Aug-2024 9:17 AM
Approval	13-Aug-2024 10:58 (GMT-4:00) : [Approval] was performed by: Omar Bahena-Garcia , PID-176002 Auto Schedule interface scheduled approvers	Bahena-Garcia, Omar	13-Aug-2024 10:58 AM

Deviation Action Child Record(s)

No Deviation Action Child Record Found

Test Plan Child Record(s)

No Test Plan Child Record Found

Impact Analysis Child Record(s)

Impact Assessment	No data entry
-------------------	---------------

No Impact Analysis Child Record Found

Deviation Record



Division - Project : Manufacturing and Development - Deviation

TR# : 40713134

Addendum Child Record(s)

No Addendum Child Record Found

Private Deviation Child Record(s)

No Private Deviation Child Record Found