

SIZE SET INSPECTION REPORT

STYLE NO# 7270

DIVISION AEO

Date: 07/30/26

DESCRIPTION: SHORT SLEEVE BUTTON UP MONICA

COLOUR: SNOW FLAK

ACCESSORIES CHECKLIST

ACCESSORIES	MIS	ALT	ACT	PLA	ACCESSORIES	MIS	ALT	ACT	PLA	ACCESSORIES	MIS	ALT	ACT	PLA	ACCESSORIES
MAIN LABEL					POLY BAG					BUTTON			✓		PRINT
SIZE LABEL					POLY BAG STICKER					HOOK EYE BAR					LAYOUT
SECURITY CODE					LOT STICKER					LACE					EMB THREAD COLOR
HANG TAG					PREPACK STICKER					BUCKLE					PLACEMENT
HANGER					CARTON MARKINGS					SNAP					BEADS/SEQUINS
WASHCARE					FOLDING					THREAD			✓		BEADS/SEQUINS LAYOUT
INTERLINING			✓		PLACEMENT UPC/PACK					LINING					AFTER TREATMENT
TUSSLE					SPARE BUTTON POSITION					ZIPPER					PH
BEADS					RING ADJUSTER					ELASTIC			✓		
BUGAL BEADS															
ELASTANE															

* MAIN LABEL: Pending - needs to be printed
* BUTTON (OK*): Fox shell buttons confirmed, but flagged: needs shanking added (gaping at buttonholes)
* ELASTIC (OK*): 1/4in White confirmed, but flagged: width narrower/tighter than reference sample

PATTERN CHECK LIST

Grain Line: -
Notches: -
Nested Nest: -
Sections Implemented: -
Mini Marker: OK - confirmed two-way marker, YY
0.76

MEASUREMENT (SPEC ATTACHED)

Result: PASS
Graded Nest: OK
Corrections To Be Done:
Side seam tie length flagged (read 23 3/4, momentary confusion with 21 3/4) - resolved to 23 3/4, re-verify on next size set
Bring Back To Specs: -

Planned Size Set Submission Date: -
Actual Submission Date: -
PCD: -
Cut Quantity: -

Cutting Check: -
Seam Allowance: -
Corrections Implemented: -

Size Set Inspection Result: Pass with comment

SHRINKAGE SHELL: L = 2.4% - 2.8% W = 0.8%
3 rows tested, under 3% threshold - Acceptable

LINING: -

DETAILED COMMENTS (WORKMANSHIP)

(1) Color tone difference between fit sample and PP/bulk fabric, despite lot being called 'approved'

ACTION TO BE TAKEN BY VENDOR

Needs clarification/re-approval from NY / Gaurav on correct fabric tone before bulk

(2) Placket sewn flat; fit sample carried a crinkle effect onto the placket

Match placket construction to approved fit sample (carry crinkle effect)

(3) Elastic width narrower/tighter than reference sample

Correct elastic width to match approved spec

(4) No shanking on buttons - causing gaping at buttonholes

Add shanking to all buttons

(5) Main label not yet printed

Print and attach main label per spec

OVERALL: Approved to proceed - production/cutting to begin

I AGREE WITH THE ABOVE COMMENTS AND WILL INCORPORATE ALL ABOVE COMMENTS

VENDOR SIGNATURE

SENT VIA MAIL