

SIZE SET INSPECTION REPORT

STYLE NO# -

DIVISION -

Date: -

DESCRIPTION: -

COLOUR: -

ACCESSORIES CHECKLIST

ACCESSORIES	MIS	ALT	ACT	PLA	ACCESSORIES	MIS	ALT	ACT	PLA	ACCESSORIES	MIS	ALT	ACT	PLA	ACCESSORIES	MIS	ALT	ACT	PLA
MAIN LABEL				✓	POLYBAG					BUTTON					PRINT				
BOOK FOLD					POLY BAG STICKER					HOOK EYE/BAR					LAYOUT				
FCTY CODE					LOT STICKER					LACE					EMB THREAD COLOR				
HANG TAG					PRE PACK STICKER					BUCKLE					PLACEMENT				
HANGER					CARTON MARKINGS					SNAP					BEADS/SEQUINS				
WASHCARE			✓		PLACEMENT UPC/P.PACK					THREAD					BEADS/SEQUINS LAYOUT				
INTERLINING			✓		FOLDING					LINING					AFTER TREATMENT				
					SPARE BUTTON POSITION					ZIPPER					PH				

* MAIN LABEL: Placement and codes incorrect; close with New York

PATTERN CHECK LIST

Grain Line: -
Notches: OK
Graded Nest: -
Corrections Implemnted: -
YY/ Mini Marker: OK

Planned Size Set Submission Date: 29th
Actual Submission Date: 8/7/26
PCD: -
Cut Quantity: 6 pieces
Size Set Inspection Result: Pass with comment

SHRINKAGE SHELL: -

DETAILED COMMENTS

- (1) Front body shirring length is uneven.
- (2) Main label placement and codes are incorrect.
- (3) High-low on seersucker fabric.
- (4) Joint stitching at armhole is unacceptable.
- (5) Stain at center front placket.
- (6) Uncut threads at tie ends.

OVERALL: Passed with comments

I AGREE WITH THE ABOVE COMMENTS AND WILL INCORPORATE ALL ABOVE COMMENTS

VENDOR'S SIGNATURE

MEASUREMENT (SPEC ATTACHED)

Result: -
Graded Nest: -
Corrections To Be Done: Spread front body gathering evenly by following pattern notches; correct main label placement and codes after closing with New York; take approval on fabric trim approvals; rectify armhole joint stitching; remove center front placket stain and rewash; cut all uncut threads
Bring Back To Specs: -

Cutting Check: -
Seam Allowance: -
Corrections Implemented: -

LINING: -

ACTION TO BE TAKEN BY VENDOR

- Follow pattern notches and spread gathering evenly.
- Close with New York.
- Take approval on the fabric trim approvals.
- Open up all the stitches and close again.
- Remove stain and rewash the garment.
- Cut all uncut threads properly.

MEASUREMENT DETAIL (ATTACHED SPEC SHEET)

Pass with comment · Source: WhatsApp Audio 2026-08-18 at 16.54.52 · 6 rows · 0 need review (shown in red)

Construction

No	Item	Value	Note	Conf
4	Armhole joint stitching		Unacceptable; open all stitches and close again.	1.00

Comments and vendor actions

No	Item	Value	Note	Conf
1	Front body shirring length		Uneven; follow pattern notches and spread gathering evenly.	1.00
2	Main label placement and codes		Incorrect; close with New York.	1.00
3	Seersucker fabric		High-low; take approval on fabric trim approvals.	1.00
5	Center front placket		Stain; remove and rewash garment.	1.00
6	Tie ends		Uncut threads; cut properly.	1.00