Keel & Plumb Surveyors

3 Quay Lane, Port Example

12 March 2026

Dear Ada Example,

Thank you for asking us to inspect the bathroom floor at 9 Sample Street ahead of the remodel. We visited on 10 March and found the following.

1. The joists under the bath are sound, with no sign of rot or past leaks.
2. The subfloor by the window is soft over about two square metres and should be replaced before any tile is laid.
3. The waste pipe has adequate fall and needs no alteration.

Our fee for this inspection is 180.00, reference KP-0457.

Yours sincerely,

Marco Bell

Synthetic test fixture. Every name, address and amount on this page is invented.