Frame Development Cycle

Command	Parameters	Description
help	n/a	Show help menu.
pickcolour	Pick from list of tints.	Preset tints/colours.
pickmode	Pick from list of modes.	Change mode.
tint	Percentage	Sets tint of lenses.
image	n/a	Shows most recent image.
up	n/a	See if the system is up.
temp	n/a	See CPU temp.
start	n/a	Starts shades.
stop	n/a	Stops shades.
exit	Admin only	Exits program.
reboot	Admin only	Reboots system.
halt	Admin only	Shutdown system.
uprecords	n/a	See up time.
debug	n/a	Toggles debug.
colourset	fore/back@0/255,0/255,0/255	Set specific colour.
allowallids	Admin only	Toggles if admin id is required.

PiOto
Chromic