COMMAND NEXUS · CIT 140 · WEEK 1

Problem Brief

Meridian Forge Robotics · The Process Below

LEARNER	ARTIFACT	STATUS
Destiny Johnson	Problem Brief	Working document

SECTION 01

Visible Failure

Nia Ross QA supervisor, reports M-17 was acting normal before incident.

Based on Nia Voss's account and the incident log, MR-17 accepted TEST_K44_START at 02:13:07 and started repeating the cycle two seconds later. When the operator tried to stop it at 02:14:02, the system returned ACTIVE_INSTRUCTION_PENDING, and the machine kept going. From the evidence available, I can describe what happened, but I still need more information to determine why.

SECTION 02

Verified Facts

According to the incident log, MR-17 accepted the TEST_K44_START command at 02:13:07.
The incident log shows that MR-17 started repeating the same task at 02:13:09.
When the operator tried to stop MR-17 at 02:14:02, the incident log recorded the response ACTIVE_INSTRUCTION_PENDING

SECTION 03

Assumptions and Open Questions

Open question: Why did MR-17 start a test that wasn’t listed in its current assignment?
Open question: Why did the machine keep repeating the task after the operator tried to stop it?

SECTION 04

System Environment Map

SECTION 04A

People and Roles

Nia Voss is the night QA supervisor who reported what happened. The operator tried to stop MR-17, and Elias Chen provided information about its commands.

SECTION 04B

Processes and Rules

The current test assignment identifies which tests MR-17 is supposed to perform. I need to check how test commands are approved and how stop requests should be handled.

SECTION 04C

Information and Data

The incident log, current test assignment, and Nia Voss's account help explain what happened. The log includes the start command, when the task began repeating, and the response to the stop request.

SECTION 04D

Technology and Tools

MR-17 and the system used to send its commands are involved. The operator used that system to request a stop, but it returned ACTIVE_INSTRUCTION_PENDING.

SECTION 04E

Environment and Constraints

The incident happened during the night shift in the QA lab. Since MR-17 kept repeating its task after the stop request, I would need to consider worker safety while gathering more information.

SECTION 05

Investigation Boundary

Inside the Investigation

I will focus on the command MR-17 accepted, why it kept repeating the task, and what happened when the operator tried to stop it. I will compare the incident log with its current test assignment.

Outside for Now

I will leave other machines and unrelated systems outside the investigation for now because the evidence provided focuses on MR-17.

SECTION 06

Organizational Impact

Mara Illyan production manager says QA cell was affected. She needs help to continue safely.

SECTION 07

Problem Statement

According to production manager Mara Illyan, the QA cell was affected. Her team needs help figuring out how to continue working safely.

SECTION 08

Next Investigation Step

Nia Voss says saving evidence before restart is recommended because restarting will delete useful information. Elias Chen says controlled restart may clear active state but cannot verify.

SHARED ARTIFACT

Working Document Link

Not entered

WEEK 1 STOPPING RULE

Define before designing.

This Problem Brief records the problem that requires investigation. It does not recommend a solution.