INTERCHANGE

Volume 12, Number 1

Fall 1997

Covet your Culverts

Build Your Own Culvert Pipe End Reshaper

A common problem that restricts drainage in rural areas is the crushed ends of metal culvert pipes. Replacing the whole pipe just to eliminate the crushed end is expensive and a waste of taxpayer money. Yet anyone who has tried to fix them using a standard jack knows how ineffective that method is.


Shop Built Reshaper Does the Job

A great solution is this hydraulic reshaper, designed by Douglass Wright at The Center for Local Government Technology in Oklahoma. It was designed to be made from common off-the-shelf components with a minimum amount of machining and welding involved. Several have been built by people working in maintenance shops for around \$270.

The collapsed jack is placed in the end of the crushed pipe. As the cylinder is retracted, the jack expands and the pipe is reshaped. According to Wright, this process takes about as long as it takes to read this paragraph.

A materials list and complete set of plans are available from Baystate Roads by calling (413) 545-2604 to request your set.

Reprinted with permission from Oklahoma LTAP Center from the Fall 1993 Oklahoma Local Government News.



This device was designed for use with a solenoid controlled, 12 or 24 volt, DC, hydraulic power unit.

LocalTechnicalAssistance/TechnologyTransferCenter (800)374-ROAD or (413)545-2604

Design, Monitoring, Evaluation & Repair of Culverts

An Ohio Department of Transportation study of durability problems with precast reinforced concrete box culverts resulted in the following recommendations:

- External joint wrap should be required on the tops and sides of precast reinforced concrete box culvert joints. If full membrane waterproofing of the top is provided, it need only extend 1 foot down the sides of the culvert.
- Surface sealer (either full membrane waterproofing or clear sealant) should be required on the external top slab of precast reinforced concrete box culverts, especially those with less than 3 feet of cover. The sealer should extend approximately 1 foot down the sides of the culvert.
- A minimum cover of 1/2 inch over both circumferential and longitudinal reinforcement should be required at the mating surfaces of precast reinforced concrete box culvert joints.
- Lift holes should not be permitted unless full membrane waterproofing is provided over the precast box sections or approved joint wrap material is applied over the lift hole.
- Where guardrail posts must be mounted to the precast box culvert tops, through-bolting should not be permitted.
- Additional joint material should not be placed in the inside of the joint on the top and sides of the box culvert.
- The manufacturer's name and required product information should be placed on the inside of the precast box culvert section within the top half of the culvert.

Reprinted with permission from Oregon LTAP Center from the Fall 1993 issue of Oregon Roads newsletter and originally excerpted from an article on "Field Performance of Precast Reinforced Concrete Box Culverts" by John Owen Hurd, Ohio Department of Transportation, published in the Transportation Research Record 1315, Washington, DC, 1991.

Culvert Publications and Videos

Baystate Roads Library

VIDEO

MO-147

Cleaning of Lined Ditches, Culverts and Catch Basins

DC-110

The Importance of Roadway Drainage

ST-102

Safety Features for Local Roads & Streets, Part 1

PUBLICATION DRA-07

Culvert Inspection Manual -Supplemental to the Bridge Inspector's Manual

DRA-18

Class Handout for a Course on Culvert Inspection

DRA-21

Concrete Culverts and Conduits

D&C-57

Culvert Design Aids

CDROM-6

Hydraulic Design of Highway Culverts - Version 1 (with user's manual)

MTAP

Culvert Design - An Engineering Training Course

Wayland Utilizes a Two-Paver Method...

Why didn't we think of this before?

Toma Duhani, Superintendent of the Highway Department, is now utilizing a two-paver method of laying asphalt in the Town of Wayland. This process, mainly used on primary arterial roads, paves the entire width of the road utilizing two pavers at once. This process eliminates cold joints and allows pavers to do the job correctly, utilizing ample time to pave and roll at the proper speed. The process also prohibits traffic prematurely on the road, thus ensuring quality and a long lasting road.

An additional benefit, which made the town especially happy, is the cost-effectiveness of the process. By utilizing this method, the average 3-day job can be done in a single day, eliminating extra costs for police details and traffic control. This method is also beneficial to the contractor because he can place down a large volume in a single day. As he gets paid on a perton basis, the method increases his productivity and lowers his costs.


Review of some benefits with uitilization of the two-paver sytem for laying asphalt:

- Minimizes traffic distributions.
- Lowers traffic control costs.
- Increases quality of paving.
- Provides large area for queuing trucks which minimizes wait time for loading pavers.
- Increases construction productivity which may result in lower unit cost for the municipalities.

-Danielle Carriveau (edited by Toma Duhani)



Trucks wait their turn at the paver.



Two pavers eliminate cold joints.

How Long Should the Culvert Be?

When you plan to replace a culvert, use the following formula to calculate how long a culvert to order:

Length (L) of culvert = 2 times the Slope (S) times (D). Add the product to the Width (W) of the road including the shoulders.

For example:

- S Slope (no. of feet horizontal run per one foot drop) is 4:1.
- w Width (with shoulders) is 26 feet.
- D Culvert depth (from shoulder edge to flow line of culvert) is 4 feet.

--or--

for a slope of 4:1 (the minimum acceptable for safety without guardrails) use this table

Width of road at culvert location "W" (ft.)

1	6	18	20	22	24	26	28	30	
4(0	42	44	46	48	50	52.	. 54	3 8
48	8	50	52	54	56	58	60	62	epth
.50	6	58	60	62	64	66	68	70	for of
64	4	66	68	70	72	74	76	78	6 6
7	2	74	76	78	80	82	84	86	1vert
80	0	82	84	86	88	90	92	94	•
8	8	90	92	94	96	98	100	102	
9	6	98	100	102	104	106	108	110	10

The number where width and depth intersect indicates the length of the culvert.

Culvert Capacities

If a 15" diameter culvert is considered to have a capacity of 1, then other sizes have a relative capacity, as shown below:

CATALOG SERVICE SERVIC		Part of the second		#1866
CHARLES AND	Section 1	PETERSON OF STREET	STATE OF THE PARTY	
CONTRACTOR OF THE PARTY OF THE	A COLUMN TO SERVER STORY	1000		
12"	19 X 10 C 20 C	0.6	STORY STATE OF	
GENERAL SERVICES	10-11-10-11-10-11-10-11-10-11-10-11-11-1	55 FLS 8000 Au	THE RESERVE OF THE PARTY OF THE	
SERVICE THE PROPERTY OF THE PR	Facility Commenced	000 No. 6524 000	The second second	
STEERS AND STREET		and the second second		
经发现的产品的企业。				200
15.5 % TO THE RESPONSE THE TANK THE	AND SHEET SHEET	The state of the s		
The state of the s	Sec. 657 Vice Section Co.	1.0	100	
15"	CATHAM SACAR SALAR	The second second	EN THE RESIDENCE	MC277
CANCELL SEASON THE		A	5 45 K W W W W	45 ILE
1.1 (a) (b) (c) (c) (c) (c) (c) (c) (c) (c) (c) (c	Charles St. See Life	CONTRACTOR OF THE PARTY	AND DESCRIPTION OF THE PARTY OF	U.S.P.K
AND DESCRIPTION OF THE PERSON	THE RESERVE OF THE RE	A THE PARTY OF THE	mg 1 5 5 11 2 3	
STREET, STREET			大学 はない かんかん	2000
300 000 000 000		4 / X / Y / Y	and believes the same of	
18"	TAC 150	1.4	The Market Tolo	-3200
		CONTRACTOR AND ADDRESS.	The section of the	e e
100 CONTRACTOR (100 CONTRACTOR)		COLUMN DE PARTIES	Section 15 Section 18	P. 31
24-973	100	Marie Broggins Committee	3 W. Or. 13 F. 16	100
THE RESERVE OF THE PERSON NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN		200.4	THE PARTY OF	14.40
0.000			20 T. D. A. C. C. L.	2000
21"	A		1 2 2 1 1 2 3 3 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5	15.00
THE PERSON NAMED OF THE PERSON	STATE OF THE PARTY	1.9	X X X X X	-503
A STATE OF THE PARTY OF THE PAR	200	- 10 10 0	Service Control	" 6" J
And the second second	The state of the s	200	50 2 2 1 Vinction	A
Section 18 Section 20 Section 20		THE RESERVE OF THE PARTY OF THE	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	100
	No. of Part of the Control of the Co	A	150000000000000000000000000000000000000	196.962
	CC CONTRACTOR		4 7 April 10 - 3 to 1 A	W. T. W.
24"		2.5		Sec. 10.
Section 2012		100	Se can produce	2.76
	75.0		ALTO MENSE	Parker B
THE RESERVE OF THE PARTY OF THE		Street, Same	A. 11 Section 2 11 2 2 2 1	3.00
T127 1 4 4 4 5 5 6 5 6 7 1 4 5 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6		Section 2 Section 14	Control of the last	
				STATE OF THE PARTY OF
APPROXIMATE OF THE RESERVE OF THE PARTY OF T	A STATE OF THE STA	100,000	Street Sections	
AMERICAN CONTROL OF CHARACTER		Ann 1911 1912	10 miles	
30"	100	4.0	A CO AND RES	
Target a complete	A PART OF STREET	N. Street House, Street	STATE OF THE PARTY	688
	10 mg 20 mg 20 mg		STATE OF THE PARTY OF	
	THE R. P. LEWIS CO., LANSING	200000		200
36	AN ELECTRICAL PROPERTY.	5.7	All properties	
THE REAL PROPERTY AND ADDRESS OF THE PARTY AND				483.19
有多数性类型的,使用多数的	Charles a way			178
CARLES OF THE RESERVE OF	The state of the state of	Control House, Sec.	Contract Con	100
STEEL STREET,	200 200 200 200	The second second		
STATE OF THE PARTY			100	KRA C
42"	Cat STATE OF A SHEET	to the section of		
SET STREET, AND THE STREET, MAN			ATTENDED TO	
Control of the Control	200	ALC: UNKNOWN AND	The second second	
CHAIR PROPERTY AND ADDRESS.		7.8		115000
ESTADIO SE		200 CHARLES		
		THE RESERVE AND ADDRESS.		100
			\sim	10.0
PECHALA COLUMN	200			
48"		The state of the s	.23	\$385H
Contract of the Contract of th	ALL TURES	SCHOOL SEC. ST	100 miles	distribution.
Company of the Company of the		A STATUTE OF THE PARTY OF	STATE OF THE OWNER, OWN	083W8
REPARED VALUE OF THE	THE RESERVE		40.00	400
CANADA SERVICE SERVICE BEING	1000年 有 生物的基础	b	2011	To the last
2000 C 100 C	200	STATE OF THE REAL PROPERTY.	SE AND THE RESERVE	200
54'	VI. 10. 10. 10. 10. 10. 10. 10. 10. 10. 10	341 W. W. W. W. W.	.95	
TO THE THE LETT SEE	STATE OF STREET			Sept. W
などでは76時間は日本時間		200000000000000000000000000000000000000	SMACH TOXAGE	
103000000000000000000000000000000000000	The same of the sa	Maria Carl A	WALKER TOWN	
		Marie Control	\$1705 BY 55.7	Mile Sal
Secretary and the second	A STATE OF THE STATE OF	Section 1		# 7. T.
		100	1. 1. 3 Pr. 1. 3	25.00
60'		建筑企业的	.98	16.7
TO STREET, STR	200	NEW WORLDS	100	01572
A STATE OF THE STA		A STATE OF THE PARTY OF THE PAR		300
CHARLES OF THE STATE OF THE STA		CHILD DO NOT THE	Charles and the second	144

For example, a 24" pipe will carry *four times* the capacity of a 12" pipe.

Remember:

For the same type of pipe, CAPACITY QUADRUPLES each time the pipe DIAMETER DOUBLES.

Source: Georgia Roads,Georgia Technology Center, Spring 1993

Remove old culvert headwalls for safety

Many old-style culvert headwalls still exist on local roads. They are rigid and strong and could abruptly stop or roll a vehicle. Simply breaking them off at ground level will make them much safer. New culverts should be made so vehicles can run over them (traversable) by shaping the ground around the culvert.

For old headwalls remove the headwall and extend the culvert,

or use a traversable opening such as a grate. To achieve a safe grade on the sideslope around the culvert, you may have to lengthen the culvert and fill around it. The culvert end slope should match the embankment slope.

If there will be no guardrail along the slope it should be no steeper than 4:1 which is considered nonrecoverable but transversable. This means the vehicle is not likely to overturn but most motorists will be unable to stop or return to the road easily. Ideally slopes should be flatter than 4:1 and without obstacles that can interfere with the vehicle such as trees or erosion

This article was reprinted with permission from the Wisconsin LTAP Center.

Two 12" culverts must carry more than one 18"...Right?

As intuitive as this seems, it is wrong. In fact, it would take three 12" concrete pipes to equal one 18" diameter culvert.

Here's the calculation:

$$Q = 1.486/n \frac{D^{\frac{8}{3}} S^{\frac{1}{2}}}{n}$$


where:

Q= Flow in cubic feet per minute

n = roughness coefficient (assumed to be 0.010 for this calculation)

D = inside diameter of the pipe in feet

S = Slope of the pipe (assumed to be 2% for this case)



Williamstown uses 60" HDPE pipe

PROJECT:

Forty feet of 60" annular corregated high density polyethylene pipe (HDPE) to replace 60" corroded "boiler shell" culvert under high traffic primary gravel road in Williamstown, MA.

CONDITIONS:

Trench installation with shallow burial depths of one to two feet. Stone bedding and backfill was placed immediately around pipe to springline. Processed gravel with recycled asphalt content used from springline to grade. Rammer-type compactors achieved Std. Proctor densities near ninety percent.



RESULT:

According to Fran Bush. Williamstown highway crew completed the HDPE pipe installation in one day, with traffic passing on the road by the end of the day. The town's maintenance shop constructed a 20' spreader to keep the lifting points 20" apart, and old headwalls were rammed out to prepare the bed for the HDPE pipe. The pipe was lifted by the town's JD 495 rubber tire excavator and set in the trench.

"We were pleased with the installation; this job went extrememely well with everyone working together. The road supports heavy farm traffic and also high vehicular loading for a gravel road."

-Fran Bush

Our thanks to Fran Bush, Highway and Landfill Superintendent for Town of Williamstown and Frank Mailhot, formerly of Hancor. If you would like a copy of the complete article on this installation, please contact Baystate Roads Program.



CALENDAR

TRAFFIC SIGNALS

November 25, 1997 December 11, 1997 January 15, 1998

Hotel Northampton, Northampton Holiday Inn, Taunton Nichols College, Southborough

SNOW AND ICE

October 31, 1997 November 19, 1997 November 20, 1997 Hotel Northampton, Northampton Holiday Inn, Taunton Wyndham Garden, Burlington

STORMWATER MANAGEMENT

December 9, 1997 December 10, 1997 December 16, 1997 December 17, 1997 Hotel Northampton, Northampton Crowne Plaza Hotel, Worcester Westford Regency, Westford Holiday Inn, Taunton

MASSACHUSETTS HIGHWAY ENVIRONMENTAL TRAINING

November 5-6, 1997 November 12-13, 1997 Sheraton Springfield Monarch Place, Springfield Bank of Boston Conference Center, Boston



innovative instruction.

Congratulations!!

to our newest grads in the Baystate Roads Program!!

Thomas Allan
Michael Ball
Roger A. Bisbee
Paul Corrieri
F. Thom Donahue
Fred LaPiana
John C. Modzelewski
John W. Moultrie
Kati Murphy
James Riccio
Paul Riccio
Stephen Seymour
David Small
Charles Souza
Robert Weeks

MA Highway Department
Town of Great Barrington
Town of Williamsburg
Town of Bedford
Town of Somerville
Town of Vineyard Haven
Town of Holden
Town of Georgetown
Town of Douglas
Town of Watertown
Town of Watertown
Town of Barnstable
MDC Watershed Mgt.
MA Highway Department
Town of Bourne

Congratulations to this class of Massachusetts Roads Scholars whose names and town affiliations are listed above. These fifteen dedicated employees attended a minimum of seven training workshops, five of which had to be intensive core courses. The one-day seminars allowed the scholars to improve their skills and knowledge with recognized experts who provided practical, up-to-date and



Baystate Roads, Chris has pushed me out of the nest. On September 22, I became a proud member of the engineering staffat a Connecticut engineering firm. Amy Bisbee, Pavement Support Engineer; I like the sound of that.

So here I am on my last day at work (a day for which I actually showed up on time) and what does Chris say? He expects me to work! "Write an article about yourself for the newsletter," he demands. And he thinks I'll miss this place. Who am I kidding, I was the

in this issue

Build a Culvert Pipe End Reshaper	Page 1
Design/Evaluation & Repair & Culvert Videos	Page 2
Wayland Uses Two-Paver Method	Page 3
How Long Should the Culverts Be?	Page 4
Removing Headwalls & Culvert Capacity	Page 5
Williamstown Uses 60" HDPE Pipe	Page 6
Calendar & Baystate Scholars	Page 7

luckiest student on campus to have the opportunity to work for the Baystate Roads Program. It's been a great job. I got to work with fun, interesting, and knowledgeable people, and every now and then Chris would let me out of the office...

But as much as I will miss everyone here, I am really excited to move on. Thanks to everyone and look out Connecticut, here I come!

Amy Bisbee

The Baystate Roads Program, which publishes Mass Interchange each quarter, is a Technology Transfer (T2) Center created under the Federal Highway Administration's (FHWA) Local Technical Assistance Program (LTAP). FHWA is joined by the Massachusetts Highway Department, the Department of Civil and Environmental Engineering at the University of Massachusetts/Amherst, and local public works departments in an effort to share and apply the best in transportation technologies.

In addition to publishing Mass Interchange, the Baystate Roads Program facilitates information exchange by conducting workshops, providing reports and publications and videotapes on request, and offering one-to-one technical assistance on specific roadway issues. Because the program relies on input from many sources, inquiries, articles, and ideas are encouraged.

Local Technical Assistance/Technology Transfer Center To contact the Baystate Roads Program, call (800) 374-ROAD (in state) or (413) 545-2604.

5

Ø

MASS INTERCHANGE

SUMMER 1997

BAYSTATE ROADS PROGRAM

Department of Civil & Environmental Engineering University of Massachusetts 214 Marston Hall Amherst, MA 01003-5205 Non-ProfitOrganization U.S. PostagePaid PermitNo.2 Amherst, MA 01002







Massachusetts Highway Department Federal Highway Administration University of Massachusetts/Amherst

