

Savannah River Site

Salt Waste Processing Facility
Construction Turnover to Testing and
Commissioning Oversight

SWPF-15-DI-001, Rev. 1

September, 2015

SIGNATURE PAGE

Prepared by:

Jeffery Howell DOE SWPF Contractor

Date

9/14/2015

Endorsed by: _

Kenneth Guay Date
DOE SWPF Construction / Startup Director

Endorsed by:

Robert K. Leugemors DOE SWPF Chief Engineer

Approved by:

Pamela A. Marks

SWPF Federal Project Director

REV A	Internal Review by DOE Construction and Turnover Group
REV B	SWPF Project Office Review
REV C	Comments incorporated from SWPF Project Office Review
REV 0	Initial Issue
Rev 1	Changed Affidavit to Affirmation throughout document
	• Updated section 5 to reflect improvements (use of OneNote) and process additions (after turnover reviews/LMRB) to the process
	• Updated Attachment 1 to delete redundancies, and provide more detail in some sections
	• Updated Attachments 2 and 3 to reflect actual templates being used.
	All others were minor editorial changes.

1.0		PURPOSE5
2.0		SCOPE5
3.0		TURNOVER OVERSIGHT ORGANIZATION5
4.0		DOCUMENTING THE TURNOVER OVERSIGHT PROCESS9
5.0		INSTRUCTIONS
	5.1	Approximately two months prior to initial walkdown, perform the following 10
	5.2	Beginning approximately two months prior to and up to initial walkdown, perform the following:
	5.3	At initial walkdown perform the following:
	5.4	Punchlist Management
	5.5	Between Initial Walkdown and Final Walkdown, perform the following:11
	5.6	At the Final Walkdown:
	5.7	After system is turned over:
	5.8	Systemic or open issues after or during a system turnover:
	5.9	Document handling and communications instructions:
6.0		REFERENCES14
7.0		ACRONYMS
8.0		ATTACHMENTS 15

1.0 PURPOSE

This procedure establishes an oversight process for the Salt Waste Processing Facility Project Office (SWPFPO) Integrated Project Team (IPT) personnel assigned to perform oversight of system turnover from Construction to Commissioning and Testing. The turnover oversight process provides the mechanisms, and documentation requirements to ensure the Parsons' performance of system turnovers and the subsequent declaration of Construction Complete (CC) was performed satisfactorily by the Salt Waste Processing Facility (SWPF) contractors and meets the requirements of Modification 116, Attachment 3 to Contract DE-AC09-02SR22210.

2.0 SCOPE

The construction complete project milestone will be achieved once all systems identified in PP-CM-8103, SWPF System Turnover from Construction to Commissioning, Appendix A are turned over to Parsons' Commissioning and Testing (C&T). Construction complete and Type A and B Items are defined in SWPF Contract Mod 116, Attachment 3. Per SPD-SWPF-P-0018, SWPF Certification and Verification Plan, (CVP), the SWPFPO IPT will review 100% of the Construction Turnover Packages to validate completeness of each system turnover. This review will consist of participation in the initial and final walk downs, and a review of the 18 sections of each of the turnover packages.

DOE's approach is to utilize the different skill sets within the SWPFPO IPT which include Construction and Startup (C&SU), and Engineering and Quality Assurance (QA) personnel. The systems were divided among different resources based on expertise in the prevalent discipline required for that system. The turnover package sections have been divided between the IPT personnel to align with their areas of expertise.

3.0 TURNOVER OVERSIGHT ORGANIZATION

The systems were logically assigned into one of 12 areas. Each area was then assigned a Department Of Energy (DOE) IPT Turnover System Lead (SL), and a DOE IPT Engineering System Lead (ENG). Alternates were assigned for both leads. (See Table 1)

Table 1. Area/System Responsibility Matrix provides the Detailed System Assignments

	System		DOE IP	T Turnover	DOE Des	ign Authority
Area	Turnover	Title	System Lead		System Lead	
	ID		Primary	Alternate	Primary	Alternate
Electrical	ELEC-00	Electrical	SL	SL	ENG	ENG
	DG-00	Standby Diesel Generator				
	UPS-00	Uninterruptable Power Supply				
	PMS-00	Power Monitoring System				
BPCS/SIS	ICP-00	Instrument Control Panels	SL	SL	ENG	ENG
	BPCS-00	Basic Process Control System				
	CTV-00	CCTV				
	RPS-00	Radiation Monitoring				
	SIS-00	Safety Instrumented System				
HVAC	HV-00	Process Building Ventilation	SL	SL	ENG	ENG
	HV-01	Alpha Finishing Facility				
		Ventilation				
	HV-03	Control Room Ventilation				
	HV-04	Cold Chemical Area Ventilation				
	HRS-00	Heat Recovery System				
	PVV-00	Process Vessel Ventilation				
	PVV-01	Process Vessel Ventilation – AFF				
		Segments				
	PMV-00	Pulse Mixer Vent				
Plant	AIR-00	Plant Air	SL	SL	ENG	ENG
Air/Gas/Dilution	AIR-01	Plant Air – AFF Segments				
	ADS-00	Air Dilution				
Material Handling	MHD-00	Material Handling Equipment	SL	SL	ENG	ENG
Lab Sample	AL-00	Sample Pumps	SL	SL	ENG	ENG
	AL-01	Hot Cells, Lab Glove boxes &				
		Radio Hoods]			
	LC-00	Laboratory Collection				

Area	System Turnover	Title	_	T Turnover em Lead		ign Authority em Lead
	ID		Primary	Alternate	Primary	Alternate
ASP/AFF Process	AFP-00	Alpha Finishing Process	SL	SL	ENG	ENG
	MSTT-00	MST & Sludge Transfer Tank				
	SSR-00	Sludge/Solids Receipt & Wash				
		Water Hold Tanks				
	ASP-00	Alpha Sorption Process				
	DSS-00	Decontaminated Salt Solution				
		Hold Tank				
	IST-00	Interim Storage Tank				
	CHW-02	Chilled Water Secondary – ASP			ENG	ENG
	CHW-03	Chilled Water Secondary - AFF				
CSSX Process	SSF-00	Salt Solution Feed Tank	SL	SL	ENG	ENG
	CON-00	CSSX Contactors				
	CTW-00	CSSX Tempered Water				
	SHT-00	Solvent Hold Tank				
	CWT-00	Caustic Wash Tank				
	SHE-00	Strip Effluent				
	BA-00	Barium Decay				
	SFD-00	Solvent Strip Feed Tank				
	VMS-00	Vibration Monitoring System				
Diagnostic/Flush	CTS-00	CSSX Drains	SL	SL	ENG	ENG
	AFD-00	Alpha Finishing Drains	1			
	ASD-00	Alpha Sorption Drains				
	LD-00	Laboratory Drain				
	LLD-00	Low Level Drains				
	FLS-00	Flush Water				
	FLS-01	Flush Water – AFF Segments				

Area	System Turnover	Title		Γ Turnover em Lead		ign Authority em Lead
7 1100	ID	Title	Primary	Alternate	Primary	Alternate
Cold Chemical	CMU-00	Caustic	SL	SL	ENG	ENG
	FCS-00	Filter Cleaning Acid System]			
	MST-00	MST				
	NIT-00	Nitric Acid				
	NEU-00	Neutralization				
	SMU-00	Solvent Makeup				
Facilities	ACS-00	Access Control	SL	SL	ENG	ENG
	COM-00	Radio & Public Address				
	BLD-02	Compressor Building				
	BLD-03	Process Building				
	OOA-01	Other Outside Areas				
	FD-00	Fire Detection			ENG	ENG
	FS-00	Fire Suppression System				
Utilities	CHW-00	Chilled Water, Primary	SL	SL	ENG	ENG
	CHW-01	Chilled Water – Building				
		Ventilation				
	CHW-04	Chilled Water, Primary –				
		Control Room				
	CHW-05	Chilled Water – Building				
		Ventilation – AFF Segments				
	CHW-06	Chilled Water, Primary – AFF				
		Segments				
	DOM-00	Domestic Water				
	DOM-01	Domestic Water – AFF Segments				
	DIW-00	De-ionized Water Package	1			
	PSL-00	Seal Flush	_			
	PSL-01	Seal Flush – AFF Segments				

Each system's Turnover Package consists of 18 sections as denoted in PP-CM-8103. The sections have been divided among the three IPT disciplines as follows:

DOE IPT Turnover System Lead: Sections 1-4, 15-18

DOE Engineering System Lead: Sections 5-11
Construction and Start Up: Sections 12-14

Attachment 1, DOE Turnover Oversight Guidance, provides the detailed section breakdown including the responsible discipline, and guidance for the depth and breadth of the sections review.

4.0 DOCUMENTING THE TURNOVER OVERSIGHT PROCESS

To provide consistent and effective system turnover oversight, a streamlined documentation process is utilized. The process consists of three documents:

- Attachment 2: SWPF DOE Turnover to Commissioning and Testing Checklist
- Attachment 3: SWPF DOE Turnover to Commissioning and Testing Affirmation of System Construction Complete
- Attachment 4: Site Tracking Analysis and Reporting System (STAR) Assessment report for Turnover Oversight

These Attachments are described in more detail below:

SWPF DOE Turnover to Commissioning and Testing Checklist

The checklist is the working level document. This document will capture all the activities performed by the reviewers, and their comments. The data entered in this document will need to support the declarations made in the Affirmation of System Construction Complete, and STAR Assessment.

SWPF DOE Turnover to Commissioning and Testing Affirmation

The Affirmation of System Construction Complete is the document that provides the reviewers' declaration to the SWPFPO Federal Project Director (FPD), and the Contracting Officer (CO), and subsequently the Line Management Review Board (LMRB) that the system is CC.

STAR Assessment Report for Turnover Oversight

The assessment report summarizes the system turnover oversight effort and provides a records repository for the checklist and Affirmation of System Construction Complete.

NOTE: The intent of the process is to have an assessment for each turnover system with an attached checklist and Affirmation of System Construction Complete with no open findings. This assessment will clearly declare that the system is CC as defined in Contract DE-AC09-02SR22210 Mod 0116, Attachment 3.

5.0 INSTRUCTIONS

- 5.1 Approximately two months prior to initial walkdown, perform the following
 - 5.1.1 (SL) Prepare the SWPF DOE Turnover to Commissioning and Testing Checklist for the scheduled system in Microsoft OneNote (OneNote).
 - 5.1.2 (SL) Initiate STAR assessment.
- 5.2 Beginning approximately two months prior to and up to initial walkdown, perform the following:
 - 5.2.1 (ALL) Begin reviews of assigned sections per Table 1 as documents are available.
 - 5.2.2 (ALL) Document system related turnover oversight activities in the checklist.
 - 5.2.3 (SL) Ensure that all parties involved with the system are notified and updated on the initial walkdown dates.
- 5.3 At initial walkdown perform the following:
 - 5.3.1 (SL) Participate in the scheduled walk down observing Parsons' performance.
 - 5.3.2 (ENG/C&SU) Perform a walkdown either with the scheduled walkdown or independently.
 - 5.3.3 (ALL) Document performance of walkdown in the checklist.
- 5.4 Punchlist Management
 - 5.4.1 (ALL) Ensure that all punchlist items from DOE are sent to the DOE IPT System Turnover Lead using Parsons Form SWPF-437, Turnover Punchlist Item Identification Form.
 - 5.4.2 (SL) Ensure that punchlist items identified by DOE are listed on form SWPF-437, and sent to Cheri Defigh-Price or designee and copy the SWPF Document Control Administrator (SWPFDCA).
 - 5.4.3 (SL) Verify that all Punchlist A items are validated by Parsons C&T, and documented properly in the Parsons' punchlist database.
 - 5.4.4 (SL) Ensure that Punchlist B items that are turned over are at a manageable level.
 - 5.4.5 (SL) Continue to monitor Punchlist B items.


- 5.4.6 (SL) After CC is declared, monitoring of the Punchlist B items will be turned over to the SWPFPO IPT Testing Lead.
- 5.5 Between Initial Walkdown and Final Walkdown, perform the following:
 - 5.5.1 (ALL) Complete reviews of turnover package sections as assigned in Table 1.
 - 5.5.2 (ALL) Document Table 1 activities in the checklist.
- 5.6 At the Final Walkdown:
 - 5.6.1 (SL) Participate in the scheduled walkdown observing Parsons' performance.
 - 5.6.2 (ENG/C&SU) Perform a walkdown either with the scheduled walkdown, or independently.
 - 5.6.3 (ALL) Document performance of walkdown in the checklist.
- 5.7 After system is turned over:
 - 5.7.1 (ALL) Review and finalize checklist entries in OneNote.
 - 5.7.2 (ALL) Provide input into the assessment in STAR.
 - 5.7.3 (SL) Review the checklist for completeness and accuracy.
 - 5.7.4 (SL) Ready the Assessment for review with a draft status in STAR.
 - 5.7.5 (SL) Present the Assessment to SWPFPO Engineering & QA, and C&SU Directors.
 - 5.7.6 (SL) If there are no findings, then continue to next step; else perform section 5.8 and return to this step.
 - 5.7.7 (SL) Complete the Affirmation of System Construction Complete including obtaining all signatures.
 - 5.7.8 (SL) Present the Assessment to SWPFPO FPD and CO. Resolve any issues identified.
 - 5.7.9 (SL) Present the Assessment to the LMRB.

- 5.7.10 (SL) Once the LMRB accepts the system turnover, then submit the assessment for approval in STAR.
- 5.7.11 (SL) Send approved STAR Assessment to SWPFDCA.
- 5.7.12 (SWPFDCA) Transmit the completed STAR Assessment to Parsons.
- 5.7.13 (SL) Update Turnover Metrics in SWPF's Daily Activity Report.
- 5.8 Finding(s) on the system after Parsons has turned over:
 - 5.8.1 (SL) Submit the assessment for approval in STAR with Finding(s).
 - 5.8.2 (SWPFDCA) Transmit the completed STAR Assessment to Parsons.
 - 5.8.3 (SL) When the findings are closed by Parsons, then validate that the closure of the finding(s) is satisfactory.
 - 5.8.4 (SL) Close the finding(s) in STAR
 - 5.8.5 (SL) Update the checklist and Affirmation as applicable.
 - 5.8.6 (SL) Present the Assessment to SWPFPO Engineering and QA and C&SU Directors.
 - 5.8.7 (SL) If the closure of the Finding(s) is acceptable, then return to the previous section as applicable, else repeat this section.

- 5.9 Document handling and communications instructions:
 - 5.9.1 The forms used in this process are all located in OneNote, any other documents used for review or objective evidence shall be saved (i.e. objective evidence of finding closure) in a common folder on the X Drive noted below.
 - 5.9.2 Electronic folders are set up for each of the 12 areas in Table 1, the individual system folders will be set up as the turnover process progresses (See Illustration below):



Illustration 1: Screen Shots showing File Path



File Path: X:\SWPF\!Construction Division\SWPF Testing Turnover\Turnover

6.0 REFERENCES

Contract DE-AC09-02SR22210 Mod 0116, Attachment 3

SPD-SWPF-P-0018, SWPF Certification and Verification Plan (CVP)

PP-CM-8103, SWPF System Turnover from Construction to Commissioning

PP-CM-8104, Turnover Punchlist Item Processing

DI-CM-026, System Boundary Documents

DI-CM-027, Turnover Walkdown Guidelines

DI-EN-043, System Turnover

7.0 ACRONYMS

ALL Represents the grouping of (SL, ENG, and C&SU)

BPCS Basic Plant Control System

CAT Construction Acceptance Testing

CC Construction Complete

C&SU Construction and Start Up reviewer

C&T Commissioning and Testing CO SWPF Contracting Officer

CRFI Construction Requests For Information

CSE Cognizant System Engineer

CVP Certification and Verification Plan

DOE Department of Energy

ENG DOE IPT Engineering System Lead

EQ Environmental Qualification FPD Federal Project Director

HVAC Heating Ventilation and Air Conditioning

IPT Integrated Project Team ITP Inspection Test Plan

LMRB Line Management Review Board

LO/TO Lock Out/Tag Out

M&TE Measuring and Test Equipment NCR Non Conformance Report NPH Natural Phenomena Hazard

OIM Operations Instruction Manual (Vendor Manual)

P&ID Piping and Instrumentation Diagram
PDSA Preliminary Documented Safety Analysis
PRDVR Pressure Relief Device Verification Record

PM Preventative Maintenance

PVVR Process Vessel Verification Record QCIR Quality Control Inspection Report

QA Quality Assurance SIL Safety Integrity Level SIS Safety Instrumented System
SL DOE IPT System Turnover Lead

SS Safety Significant

STAR Site Tracking Analysis, and Reporting System

SWPF Salt Waste Processing Facility

SWPFDCA Salt Waste Processing Facility Document Control Administrator

SWPFPO Salt Waste Processing Facility Project Office

TOB Turnover Boundary Drawings

8.0 ATTACHMENTS

Attachment 1: DOE Turnover Oversight Guidance for Completion of the System Checklist

Attachment 2: SWPF DOE Turnover to Commissioning and Testing Checklist

Attachment 3: SWPF DOE Turnover to Commissioning and Testing Affirmation of System

Construction Complete

Attachment 4: STAR Assessment Report Template for Turnover Oversight

Below is a list of the 18 sections per PP-CM-8103, SWPF System Turnover from Construction to Commissioning that will be part of each of the turnover packages. For the purpose of a complete oversight review other reviews may be added after Section 18 in this Table. As part of the CVP plan, each of these turnover packages will be reviewed by the DOE SWPF IPT. The table below lists each of the sections and guidance on reviewing of each section.

Any section identified as not applicable to a specific turnover will be identified in the Turnover Package.

Note: In general, all verifications listed below are intended to be by sampling reviews. The review should consider including all SS items as part of the sampling scope.

T/O	Reviewer	Description	Depth and Breadth of Review
Section		_	
1	SL	SWPF-590,	· Cursory review
		Turnover	
		Package Index	
2	SL	SWPF-436,	· Cursory review
		Turnover	
		Package	
		Acceptance	
		Form	
3	SL	Turnover	Detailed review of Punchlist A items and disposition/validation adequacy
		System Punch	Punchlist B items entered and assigned correctly
		list	
4	SL	System Scoping	Detailed review of Drawings
		Index and	• Attention to boundaries (sampling of checking other TOB boundaries)
		Drawings	

Below is a list of the 18 sections per PP-CM-8103, SWPF System Turnover from Construction to Commissioning that will be part of each of the turnover packages. For the purpose of a complete oversight review other reviews may be added after Section 18 in this Table. As part of the CVP plan, each of these turnover packages will be reviewed by the DOE SWPF IPT. The table below lists each of the sections and guidance on reviewing of each section.

Any section identified as not applicable to a specific turnover will be identified in the Turnover Package.

Note: In general, all verifications listed below are intended to be by sampling reviews. The review should consider including all SS items as part of the sampling scope.

T/O Section	Reviewer	Description	Depth and Breadth of Review
Section			
5	ENG	Cable List	 Cross-check the cables listed versus the system TOB drawings and the source design documents (single lines [E-E2-J-xxxxx] and schematics [E-E4-J-xxxxx]) to verify that cables within the boundary are listed Verify that the other information associated with the cables is correct (cable 'to' component and drawing, cable 'from' component and drawing, one-line drawing) Cross-check the Cable List with the Equipment List (section 6) to verify that cables associated with electrical equipment in the system scope are included in this section Verify that supporting electrical calculations (load studies, sizing, arc-flash, etc.) are complete and consistent with final design and installation state (e.g. arc flash labels, fuse sizes, etc.)

Below is a list of the 18 sections per PP-CM-8103, SWPF System Turnover from Construction to Commissioning that will be part of each of the turnover packages. For the purpose of a complete oversight review other reviews may be added after Section 18 in this Table. As part of the CVP plan, each of these turnover packages will be reviewed by the DOE SWPF IPT. The table below lists each of the sections and guidance on reviewing of each section.

Any section identified as not applicable to a specific turnover will be identified in the Turnover Package.

Note: In general, all verifications listed below are intended to be by sampling reviews. The review should consider including all SS items as part of the sampling scope.

T/O	Reviewer	Description	Depth and Breadth of Review
Section			
6	ENG	Equipment List	 Cross-check the equipment listed versus the system TOB drawings to verify that equipment within the boundary is listed Verify that the other information associated with the equipment is correct (Electrical One Line, Equip. Schedule Drawingg, P&ID, Schematic, Functional Class, Room) For pressure vessels (tanks, filters, etc.), verify supporting calculations are complete and consistent with final design (ASME Boil & Pressure Vessel Code calculations, PVVR, tank sizing calculations, etc.) For pumps, agitators, heat exchangers, verify supporting calculations are complete and consistent with final design (sizing calculations, etc.) For vendor-supplied equipment verify that equipment installation is consistent with vendor recommendations (See Turnover Section 15 for Vendor Manuals)

Below is a list of the 18 sections per PP-CM-8103, SWPF System Turnover from Construction to Commissioning that will be part of each of the turnover packages. For the purpose of a complete oversight review other reviews may be added after Section 18 in this Table. As part of the CVP plan, each of these turnover packages will be reviewed by the DOE SWPF IPT. The table below lists each of the sections and guidance on reviewing of each section.

Any section identified as not applicable to a specific turnover will be identified in the Turnover Package.

Note: In general, all verifications listed below are intended to be by sampling reviews. The review should consider including all SS items as part of the sampling scope.

T/O	Reviewer	Description	Depth and Breadth of Review
Section			
7	ENG	Instrument List	 Cross-check the instrumentation listed versus the system TOB drawings to verify that instruments within the boundary are listed Verify that the other information associated with the instrument is correct (Tag class, Service, Location drawing, Location, Datasheet, P&ID, Wiring diagram, Line number, Functional Class) Verify that scaling sheets have been developed for the instrument as appropriate (instruments with alarms to BPCS/SIS should have scaling as a minimum) Verify that in-line instruments meet ASME B31.3 requirements Verify that supporting instrument calculations (control valve sizing, relief valve sizing, PRDVR, etc.) are complete and consistent with final design Verify that design documentation captures instrument specific-software or hard switch settings For SS instruments, review NPH/EQ documentation and any associated SIL calculations for consistency with the final design and construction of the system. Note: These documents may not be final at system turnover for testing: SIL calculations Documentation of NPH/EQ Active SS instruments are denoted with a 'Z' symbol on the P&ID

Below is a list of the 18 sections per PP-CM-8103, SWPF System Turnover from Construction to Commissioning that will be part of each of the turnover packages. For the purpose of a complete oversight review other reviews may be added after Section 18 in this Table. As part of the CVP plan, each of these turnover packages will be reviewed by the DOE SWPF IPT. The table below lists each of the sections and guidance on reviewing of each section.

Any section identified as not applicable to a specific turnover will be identified in the Turnover Package.

Note: In general, all verifications listed below are intended to be by sampling reviews. The review should consider including all SS items as part of the sampling scope.

T/O	Reviewer	Description	Depth and Breadth of Review
Section			
8	ENG	Line List	• Cross-check the lines listed versus the system TOB drawings to verify that lines within the boundary are listed
			• Verify that the other information associated with the line is correct (Pipe size and
			schedule, Fluid description, 'To' and 'From' information, P&ID, Room, Isometric)
			• Use the isometric drawings to verify that either:
			- Piping does not require stress analysis per the criteria given in G-ESR-J-00002 and Table 7-1 of P-CLC-J-00616, or
			- The required stress analysis calculation is complete and consistent with final design
			• Use the isometric drawings to verify that either:
			- Supports are standard supports evaluated in standard support calculations (P-CLC-J-00141, -00144, etc.), or
			- The required special support calculation is complete and consistent with final design
			 Walkdown a sampling of isometric drawings to verify that the field matches the design
			 Verify that any non-standard piping components meet ASME B31.3 requirements
			(unlisted component evaluation)

Below is a list of the 18 sections per PP-CM-8103, SWPF System Turnover from Construction to Commissioning that will be part of each of the turnover packages. For the purpose of a complete oversight review other reviews may be added after Section 18 in this Table. As part of the CVP plan, each of these turnover packages will be reviewed by the DOE SWPF IPT. The table below lists each of the sections and guidance on reviewing of each section.

Any section identified as not applicable to a specific turnover will be identified in the Turnover Package.

Note: In general, all verifications listed below are intended to be by sampling reviews. The review should consider including all SS items as part of the sampling scope.

		1 0	as related to total size (i.e. 4 of 10 QCIRS reviewed) include the reviewed document numbers
T/O	Reviewer	Description	Depth and Breadth of Review
Section			
9	ENG	Manual Valve	· Cross-check the manual valves listed versus the system TOB drawings to verify that
		List	valves within the boundary are listed
			· Verify that the other information associated with the valve is correct (valve code, size,
			type, service, line indentification, datasheet, P&ID, Room)
10	ENG	HVAC	· Cross-check the HVAC equipment listed versus the system TOB drawings to verify that
		Equipment List	dampers within the boundary are listed
			· Verify that the other information associated with the damper is correct (service, damper
			type, operator type, function, failure position, P&ID, Room)
11	ENG	Specialty Items	· Cross-check the specialty items listed versus the system TOB drawings to verify that
		List	specialty items within the boundary are listed
			· Verify that the other information associated with the specialty item is correct
			(description, size, line number, service, location, data sheet, P&ID, isometric, room)
			· Verify that the specialty item installation is consistent with vendor recommendations (see
			Turnover Section 15 for Vendor Manuals)
			• Verify that specialty items that constitute a piping pressure boundary meet ASME B31.3
			requirements
12	C&SU	Work Package	These three sections are closely related and as such one review of the three sections will be
		List	performed
13	C&SU	CAT (As defined	SS items will be included in the sampling scope
		by ITPs)	· Mechanically

Below is a list of the 18 sections per PP-CM-8103, SWPF System Turnover from Construction to Commissioning that will be part of each of the turnover packages. For the purpose of a complete oversight review other reviews may be added after Section 18 in this Table. As part of the CVP plan, each of these turnover packages will be reviewed by the DOE SWPF IPT. The table below lists each of the sections and guidance on reviewing of each section.

Any section identified as not applicable to a specific turnover will be identified in the Turnover Package.

Note: In general, all verifications listed below are intended to be by sampling reviews. The review should consider including all SS items as part of the sampling scope.

Reviewer should indicate sampling size as related to total size (i.e. 4 of 10 QCIRs reviewed) include the reviewed document numbers

T/O	Reviewer	Description	Depth and Breadth of Review
Section			
14	C&SU	QCIR list	 Sampling of completed portions of work packages identified in list Electrically: Sampling of completed portions of work packages identified in list Required CAT testing during construction as well as those not done at site were completed and are consistent with requirements and the acceptance criteria were met. Ensure all M&TE was within periodicity when used, and was appropriate for application.
15	SL	Vendor Manual List	· Sampling that all of the equipment has an OIM manual as applicable
16	SL	Construction LO/TO list	· Cursory Review
17	SL	Preventative Maintenance and Status	· Asset Preservation PM's were performed and documented ·
18	SL	Other	Formulate review plan for this section based on the content of this section and document in the checklist. ENG/C&SU may be asked to review all or part of this section.

Other Oversight Activities/Reviews added by SWPFPO:

Additional turnover review items not explicitly covered in PP-CM-8103

Below is a list of the 18 sections per PP-CM-8103, SWPF System Turnover from Construction to Commissioning that will be part of each of the turnover packages. For the purpose of a complete oversight review other reviews may be added after Section 18 in this Table. As part of the CVP plan, each of these turnover packages will be reviewed by the DOE SWPF IPT. The table below lists each of the sections and guidance on reviewing of each section.

Any section identified as not applicable to a specific turnover will be identified in the Turnover Package.

Note: In general, all verifications listed below are intended to be by sampling reviews. The review should consider including all SS items as part of the sampling scope.

T/O	Reviewer	Description	Depth and Breadth of Review
Section			
ENG-1	ENG	General	 Verify that any permits required for testing of the system are in-place Obtain a copy of the completed System Turnover CSE Review Checklist (form SWPF-643) from the Parsons CSE and review the CSE confirmations (design documents, NCRs, CRFIs, Engineering Open Items, and installed equipment configuration) to verify no open items against system or open items are captured appropriately in the Punchlist Safety basis (required for every turnover): For "PDSA: System Description", review the design and installation of the system to ensure they are consistent with the description of the system in the PDSA and make a statement attesting to this. The applicable PDSA section should be referenced. For "PDSA Safety Attributes of the system", describe the credited safety attributes of the system as described in the PDSA (with reference to the applicable PDSA sections) and discuss the system design/installation characteristics demonstrating compliance with the required attributes. If the system has no credited safety functions, this should be stated explicitly (as opposed to marking the section "N/A")
N/A	ALL	Initial Walkdown	 Oversight: Attendees per PP-CM-8103 Electrical Scope: Verify cables and terminations are consistent with design drawings Verify labeling of cables and other electrical equipment Verify presence of arc-flash labels and information consistent with arc-flash calculation (where labels are required)

Below is a list of the 18 sections per PP-CM-8103, SWPF System Turnover from Construction to Commissioning that will be part of each of the turnover packages. For the purpose of a complete oversight review other reviews may be added after Section 18 in this Table. As part of the CVP plan, each of these turnover packages will be reviewed by the DOE SWPF IPT. The table below lists each of the sections and guidance on reviewing of each section.

Any section identified as not applicable to a specific turnover will be identified in the Turnover Package.

Note: In general, all verifications listed below are intended to be by sampling reviews. The review should consider including all SS items as part of the sampling scope.

T/O	Reviewer	Description	Depth and Breadth of Review
Section			
			- Verify fuses are per design
			 Installation and grounding per required codes/standards
			• Equipment:
			 Verify installed per manufacturer's recommendations
			- Verify configuration is consistent with the P&ID (M-M6-J-xxxxx) or Operating
			Diagram (M-MA-J-xxxxx)
			- Verify labeling
			- For pressure relief valves, verify that the device has been tested within the
			required frequency
			· Instrumentation
			- Verify installed per manufacturer's recommendations
			- Verify configuration is consistent with the P&ID and other design drawings
			- Verify labeling
			· Lines, Supports, and Manual Valves
			- Verify configuration is consistent with the P&ID
			- Verify configuration is consistent with isometric drawings
			· HVAC
			- None
			• Specialty Items
			- Verify specialty items are installed consistent with the P&ID and other design

Below is a list of the 18 sections per PP-CM-8103, SWPF System Turnover from Construction to Commissioning that will be part of each of the turnover packages. For the purpose of a complete oversight review other reviews may be added after Section 18 in this Table. As part of the CVP plan, each of these turnover packages will be reviewed by the DOE SWPF IPT. The table below lists each of the sections and guidance on reviewing of each section.

Any section identified as not applicable to a specific turnover will be identified in the Turnover Package.

Note: In general, all verifications listed below are intended to be by sampling reviews. The review should consider including all SS items as part of the sampling scope.

T/O	Reviewer	1 0	Depth and Breadth of Review
Section			
			drawings - Verify installed in accordance with manufacturer's instructions (e.g. correct orientation relative to flow)
N/A	ALL	Final Walkdown	· Verify 'A' Punchlist items have been appropriately addressed

ATTACHMENT 2: SWPF DOE Turnover to Commissioning and Testing Checklist									
SWPF DOE Turnover to Commissioning and Testing Checklist									
SPD-SWPF-P-0018, Certification and Verification Plan									
System [Name] System (XXX-XX)									
System Lead									
Assessment #	‡	2015-S	A-00X	XXX					
Walk Down Ad	ctivit								
Activity	DC	DE Partici	ipate	Comments			Resolutions		Notes
Initial									
Walkdown									
Final									
Walkdown									
Schedule							1		
					_	Actual			
A . 1	33 77 /3	D D .		Scheduled		Turnover			
Actual Initial	. W/J	D Date		Turnover I	Jate	Date	Comments		omments
Final									
PDSA: System									
Description PDSA Safety A	***: h								
the system:	ttrib	utes or							
Turnover Pack	000 I	Povriovy							
	age r			D 1.:			NT .		
Section 1 – Index		Comments		Resolutions			Notes		
2 – Accp Frm 3 – PL							X A items. X B items, X remain open		
J-1L								A II Itt	ins. A b items, A temam open
4 – TOB								Reviewed X of X TOB documents.	
5 – Cable									
6 – Eqpt									
7 – Inst.									
8 – Line									
9 – Man Vlv									
10 – HVAC									
11 – Spec Item								<u> </u>	
12 – WP	•							X Work	x Packages (WPs) Listed –
13 – CATs									ed the following X:
14 – QCIR									s/ITPs Listed – Reviewed all of
									owing X:
								X QCIRs Listed – Reviewed the	
							following X:		
									welding, etc.
15 – O/M									
16 – LOTO									
17 – PM									
18 – Other									
Other Issues:									
Attachments:									
Document ID Document Title Notes/Comments									

ATTACHMENT 3: SWPF DOE Turnover to Commissioning and Testing Affirmation of System Construction Complete

SWPF DOE Turnover to Commissioning and Testing Affirmation of System Construction Complete									
SPD-SWPF-P-00	118, Certification and Verification Plan								
System									
System Lead									
Assessment #									
Activity	Oversight Activities/Reviews	Validation Y/N	Initials / Date						
Summary									
Initial	Participate in initial system walkdown per PP-CM-								
Walk down	8103. Ensure contract requirements are implemented								
	to ensure proper classification of punchlist items.								
	Verify punchlist items are input into applicable data								
	base and classification approved by the Parsons C&T								
	Director.								
Final	Participate in final system walk down per PP-CM-								
Walk down	8103. Ensure that all Punchlist A items are properly								
	validated- and that Punchlist B items are at a								
	manageable level.								
Turn over	Ensure all documentation required in Form 590,								
Package	Turnover Package Index and Form 436, Turnover								
Review (SALT	Package Acceptance Form is completed.								
PCP)									
Turnover Date									
Notes/Comments	:								
Attachments:									
Attachments:									
DOE SWIDEDO I	PT System Lead performed oversight in accordance with S	SDD SWDE D 0018	Cartification						
	Plan. Supporting documentation is attached. The System								
turned over from Parsons Construction to Parsons C&T per PP-CM-8103 and the system is installed and all required checks and tests are completed to the degree necessary for SOT activities to begin.									
required effects t	and tests are completed to the degree necessary for 501 de	tivities to begin.							
Print Name	Signature		Date						
	~1 g	_							
SWPFPO IPT Engineering Lead Concurrence:									
Print Name Signature Date									
SWPFPO IPT Construction and Start Up Director recommends to the SWPF Federal Project Director and the									
Contracting Officer that this system is construction complete.									
Print Name	Print Name Signature Date								
1									

ATTACHMENT 4: STAR Assessment Report for Turnover Oversight

Assessment Summary

Assessment No. 2015-SA-003648 SWPF Project Linked to: 2015-PLAN-000301

Show applicable STAR Actions INITIATION 2015-SA-003648 Assessment Unit: Facility Assessed: Schd: Status: (Management Directed) DOE:SWPFPO Sub:PARSONS 12/31/2018 SCHEDULED Title: Program Doc No: System Name (XXX-XX) System Turnover to Commissioning SWPF-15-DI-00 Assessment Type: Activity Type: Project: Evaluation Date(s): Operational Awareness SWPF FR 🗌 SSO 🗹 MFO Functional Area Mgr/Approver: Assessment Coordinator/Delegate: Guay, Kenneth (H0504) Davis, Doris (A3372) Assessor/Team Members: Functional Area: 1 Kriley, Cynthia (I7656) Construction Activities 2 Maak, Siegfried (Y6571) 3 Howell, Jeffery (I7268) 4 Boyd, Robert (06458) 5 Ryan, Paul (B7816) 6 Bell, Melissa (E8633) Personnel Contacted: Documents Reviewed: None None Purpose/Scope Purpose: This surveillance was conducted to document the oversight and review performed for System Turnover from Construction to Commissioning. This surveillance is part of DOE's plan, SPD-SWPF-P-0018, Certification and Verification Plan, and upon completion will declare that the contractor adequately provided a turnover package, and completed the turnover process per PP-CM-8103. Scope: XXX-XX, [System Description], System to verify installation and construction complete with no outstanding 'A' punch list items such that SOT activities on this system are ready to begin. Assessment Results: This surveillance was conducted by the DOE SWPFPO IPT members assigned to this system and/or their designated alternates. Each turnover goes through a process and each step of this process is captured in the attached SWPF DOE Turnover to Commissining and Testing Checklist. All comments, document reviews, personnel interviews, and oversight activities are documented in the attached SWPF DOE Turnover to Commissioning and Testing Checklist. The checklist will show that DOE participated in the system initial and final walkdowns, performed reviews at some level of sampling for each of the applicable sections of the turnover package, and observed the contractors' performance and execution of PP-CM-8103 System Turnover from Parsons Construction to Parsons Commissioning. DOE LEAD Summary Statement: DOE DESIGN AUTHORITY Summary Statement: Noteworthy Practices: **DOE-SR Assessment Information Contractor Notification** External Assessment Contact Info: Sent By: Sent Dt: CAS Elements: ___ Assessment CAS Effectiveness: Management Lessons Learned Event Reporting Measures Worker Feedback Criterion / LOIs No. Grade Description Topic Cursory review. SWPF-590, Turnover Package Index Results: . Finding 1 Contact: Kriley, Cynthia (17656) Spec. Reqt.: No OFIs Identified No. Grade Description Topic Cursory review. SWPF-436, Turnover Package

Acceptance Form

ATTACHMENT 5: SWPF Construction Turnover to Testing and Commissioning Oversight Process Flow Diagram

