

Date: September 10, 2026

To National Stock Exchange of India Ltd Exchange Plaza, 5th Floor, C-1, Block G, Bandra Kurla Complex, Bandra (E), Mumbai 400051 Symbol: REGAAL	To BSE Limited 1 st Floor, Phiroze Jeejeebhoy Towers Dalal Street Mumbai – 400001 Scrip Code: 544485
---	---

Subject: Disclosure with respect to disruption of operations pursuant to Regulation 30 read with Para B of Part A of Schedule III of SEBI (Listing Obligations and Disclosure Requirements) Regulations 2015

Dear Sir/ Madam,

In accordance with Regulation 30 read with Schedule III of the SEBI (Listing Obligations and Disclosure Requirements) Regulations, 2015 ("LODR Regulations"), we wish to inform you that there has been some damage detected in the rotor and fan of one of our turbines ("The Turbine") having capacity of 10 MW. The Turbine was part of the newly commissioned manufacturing facility of 825 TPD, commissioned on 26th May, 2026 located at Bhatgaon, Galgalia Check Post, Thakurganj Block, District- Kishanganj, Bihar- 855106. The Company's other manufacturing operations continue to operate normally and remain unaffected.

On 26th August, 2026, damage was detected in the rotor and fan of The Turbine, which was immediately sent for inspection. At the time of preliminary assessment, it was indicated that the repair would be completed within a couple of days and was not expected to be material. However, on detailed assessment during the actual repair process, it is now anticipated that The Turbine should be fixed, installed and recommissioned within approximately 35 days from the date of initial discovery of damage, i.e approximately by 30th September, 2026.

The requisite details as per the SEBI Master Circular No. HO/49/14/14(7)2025-CFD-POD2/I/3762/2026 dated January 30, 2026 is enclosed as **Annexure A**.

This disclosure shall also be made available on the website of the Company at <https://regaalresources.com/>.

Kindly take the same on record.

Yours faithfully

For Regaal Resources Limited

TINKU
KUMAR
GUPTA

Digitally signed by
TINKU KUMAR GUPTA
Date: 2026.09.10
19:07:54 +05'30'

Tinku Kumar Gupta

Company Secretary and Compliance Officer

ANNEXURE – A

Particulars	Disclosures
Expected quantum of loss/damage caused	The expected cost to repair the rotor and fan of The Turbine is approximately INR 90 lakhs. The Company is currently assessing the extent of operational and financial damage pursuant to such damage.
Whether loss/damage covered by insurance or not including amount	The loss/damage is covered by insurance.
Estimated impact on the production/operations in case of strikes/lock outs	The newly commissioned 825 TPD, was running at approximately 50% capacity utilization. For the said period during which The Turbine will be under repair, this additional capacity will not be operational. However, the Company has requisite stock to service its existing and ongoing orders which remain unaffected.
Factory/unit where the strike/lock-out disruption has taken place including reasons for such strike disruption	Bhatgaon, Galgalia Check Post, Thakurganj Block, District- Kishanganj, Bihar- 855106. Reason of disruption is mentioned above.
Reason for delay	On 26th August, 2026, damage was detected in the rotor and fan of The Turbine, which was immediately sent for inspection. At the time of preliminary assessment, it was indicated that the repair would be completed within a couple of days and was not expected to be material.

	However, on detailed assessment during the actual repair process, it is now anticipated that The Turbine should be fixed, installed and recommissioned within approximately 35 days from the date of initial discovery of damage i.e approximately by 30 th September, 2026.
--	---

The Company will continue to keep the Stock Exchanges informed of any material developments in accordance with the applicable provisions of the SEBI (Listing Obligations and Disclosure Requirements) Regulations, 2015.

For Regaal Resources Limited

TINKU
KUMAR
GUPTA

Digitally signed by
TINKU KUMAR GUPTA
Date: 2026.09.10
19:08:34 +05'30'

Tinku Kumar Gupta
Company Secretary & Compliance Officer