

1. Pressure Transmitter PRS-4410

Parameter	Value	Unit
Measuring range	0 to 10	bar
Accuracy (total error)	±0.10	bar (±0.075% FS)
Repeatability	±0.025	bar
Long-term stability	±0.05/year	bar
Media temperature	-10 to +80	°C

Application Note — Alarm Threshold Setting: With a total accuracy of ±0.10 bar, alarm thresholds should be set at least **5× the accuracy** (0.50 bar) from the nominal operating point to avoid nuisance alarms. Thresholds closer than 3× accuracy (0.30 bar) are not recommended for process control.

2. Electromagnetic Flowmeter FLW-4450

Parameter	Value	Unit
Measuring range	0 to 500	L/min
Accuracy	±0.5% of reading	—
Max fluid temp	+80	°C

3. Piezoelectric Accelerometer VIB-4480

Parameter	Value	Unit
Measuring range	0 to 50	mm/s RMS
Frequency range	10 to 1000	Hz
Accuracy	±3%	of reading
Resonant frequency	≥ 18	kHz

4. Inductive Speed Encoder SPD-4490

Parameter	Value	Unit
Speed range	0.1 to 10	m/s
Resolution	0.001	m/s
Max amb. temp	80	°C