






NOT RECOMMENDED TO USE THE BACK COVER M4 TAPPED HOLES, DOING SO WILL CAUSE STRUCTURAL DAMAGE TO THE BACK COVER.

