

$$Pri(A) = t_A^{hw} + (C_{AD} + Pri(D))$$

$$Pri(B) = 5 + (2 + 4) = 11$$

$$Pri(B) = t_B^{hw} + (C_{BD} + Pri(D))$$

$$Pri(B) = 1 + (2 + 4) = 7$$

$$Pri(C) = t_C^{hw} + (C_{CE} + Pri(E))$$

$$Pri(C) = 4 + (2 + 6) = 12$$

$$Pri(D) = t_D^{hw} + (C_{DF} + Pri(F))$$

$$Pri(E) = 2 + (0 + 2) = 4$$

$$Pri(E) = t_E^{hw} + (C_{EF} + Pri(F))$$

$$Pri(E) = 4 + (0 + 2) = 6$$

$$Pri(F) = 2$$

