
LSC excess over calibration-predicted decay: not redundant with gate count
(a) Excess ratio per instance
(b) Mean by architecture
Excess ratio (LSC-implied rate / calibration CZ error)
Mean excess ratio (cross-architecture instances)
Heron r2
Heron r3
Nighthawk
ratio = 1
12hv
12lv
16hv
16lv
6var
6var
6var
8lv
8lv
8lv
8tsla
8tsla
8tsla
Heron r2
Heron r3
Nighthawk