




** Drc report for /Users/m1m1024/Desktop/bme290/oneShotBlinking/oneShotBlinking.kicad_pcb **

** Created on 2023-02-18 14:05:38 **

** Found 9 DRC violations **

[clearance]: Clearance violation (netclass 'Power' clearance 0.8500 mm; actual 0.8400 mm)

Rule: netclass 'Power'; Severity: error

@(129.2225 mm, 101.6000 mm): Through hole pad 1 [+6V] of J103

@(129.2225 mm, 104.1400 mm): Through hole pad 2 [/SW-to-D1] of J103

[clearance]: Clearance violation (netclass 'Power' clearance 0.8500 mm; actual 0.8400 mm)

Rule: netclass 'Power'; Severity: error

@(124.4600 mm, 101.6000 mm): Through hole pad 1 [+6V] of J104

@(124.4600 mm, 104.1400 mm): Through hole pad 2 [GND] of J104

[clearance]: Clearance violation (netclass 'Default' clearance 0.8500 mm; actual 0.8400 mm)

Rule: netclass 'Default'; Severity: error

@(144.7800 mm, 127.0000 mm): Through hole pad 1 [/Light_Out] of J102

@(144.7800 mm, 129.5400 mm): Through hole pad 2 [Net-(D102-Pad1)] of J102

[clearance]: Clearance violation (netclass 'Power' clearance 0.8500 mm; actual 0.8400 mm)

Rule: netclass 'Power'; Severity: error

@(140.0175 mm, 96.8375 mm): Through hole pad 1 [/Button_Press] of J101

@(140.0175 mm, 99.3775 mm): Through hole pad 2 [GND] of J101

[clearance]: Clearance violation (netclass 'Default' clearance 0.8500 mm; actual 0.8400 mm)

Rule: netclass 'Default'; Severity: error

@(158.1150 mm, 137.1000 mm): Through hole pad 1 [/Light_Out2] of J105

@(155.5750 mm, 137.1000 mm): Through hole pad 2 [Net-(D103-Pad1)] of J105

[clearance]: Clearance violation (netclass 'Power' clearance 0.8500 mm; actual 0.6350 mm)

Rule: netclass 'Power'; Severity: error

@(149.8600 mm, 109.2200 mm): Through hole pad 1 [Net-(C101-Pad1)] of U101

@(149.8600 mm, 106.6800 mm): Through hole pad 2 [GND] of U101

[clearance]: Clearance violation (netclass 'Power' clearance 0.8500 mm; actual 0.6350 mm)

Rule: netclass 'Power'; Severity: error

@(149.8600 mm, 106.6800 mm): Through hole pad 2 [GND] of U101

@(149.8600 mm, 104.1400 mm): Through hole pad 3 [VCC] of U101

[clearance]: Clearance violation (netclass 'Default' clearance 0.8500 mm; actual 0.7400 mm)

Rule: netclass 'Default'; Severity: error

@(127.0000 mm, 109.2200 mm): Through hole pad 1 [Net-(C101-Pad1)] of D101

@(129.5400 mm, 109.2200 mm): Through hole pad 2 [/SW-to-D1] of D101

[silk_overlap]: Silkscreen overlap

Rule: board setup constraints silk; Severity: warning

@(183.2150 mm, 80.8404 mm): Line on F.Silkscreen

@(191.0500 mm, 80.8200 mm): Line on F.Silkscreen

** Found 0 unconnected pads **

** Found 0 Footprint errors **

** End of Report **

