



Method of Joints — Step by Step Examples Engineering Statics


Last revision on September 29, 2025





































































Example 1









This is to verify that we haven't made an error in our member force calculations.




$$\sum F_x = 2.3340 \,\mathrm{kN} + 1.6910 \,\mathrm{kN} - 4.8282 \cos 33.524^\circ \,\mathrm{kN}$$


= $-0.000050918 \,\mathrm{kN} \approx 0$

$$\sum F_y = 2.6667 \,\mathrm{kN} - 4.8282 \sin 33.524^\circ \,\mathrm{kN}$$

= 0.00015160 kN ≈ 0


It only remains to convert the results back to the precision given by the input values.






Method of Joints: Example 2

Solve for the internal forces in each of the truss members. Specify whether they are in tension or in compression. Then use the reactions at ${\cal C}$ and ${\cal D}$ to verify your results.








$$\angle BAE = \tan^{-1} \left[\frac{2.25}{3.00} \right]$$
$$= 36.870^{\circ}$$


$$\angle DAE = \tan^{-1} \left[\frac{3.75}{3.00} \right]$$





$$\angle BAE = \tan^{-1} \left[\frac{2.25}{3.00} \right]$$
$$= 36.870^{\circ}$$

$$\angle DAE = \tan^{-1} \left[\frac{3.75}{3.00} \right]$$
$$= 51.340^{\circ}$$






$$\angle BAE = \tan^{-1} \left[\frac{2.25}{3.00} \right]$$
$$= 36.870^{\circ}$$

$$\angle DAE = \tan^{-1} \left[\frac{3.75}{3.00} \right]$$
$$= 51.340^{\circ}$$

$$\angle BCD = \tan^{-1} \left[\frac{6.00}{3.00} \right]$$







$$\angle BAE = \tan^{-1} \left[\frac{2.25}{3.00} \right]$$
$$= 36.870^{\circ}$$


$$\angle DAE = \tan^{-1} \left[\frac{3.75}{3.00} \right]$$
$$= 51.340^{\circ}$$

$$\angle BCD = \tan^{-1} \left[\frac{6.00}{3.00} \right]$$
$$= 63.435^{\circ}$$







Joint ADraw the unknown forces in tension, pointing away from the joint they are acting upon. Then a positive result means the member is in tension and a negative result implies compression. 2.25 m F_{AB} 36.870° A3.75 m 51.340° 1650 N F_{AD} 1650 N




Draw the unknown forces in tension, pointing away from the joint they are acting upon. Then a positive result means the member is in tension and a negative result implies compression.




 $\sum F_x = F_{AB} \cos 36.870^\circ + F_{AD} \cos 51.430^\circ = 0$




Draw the unknown forces in tension, pointing away from the joint they are acting upon. Then a positive result means the member is in tension and a negative result implies compression.



$$\begin{split} \sum F_X &= F_{AB}\cos 36.870^\circ + F_{AD}\cos 51.430^\circ = 0 \\ \sum F_Y &= F_{AB}\sin 36.870^\circ - F_{AD}\sin 51.340^\circ - 1650\,\mathrm{N} = 0 \end{split}$$




Draw the unknown forces in tension, pointing away from the joint they are acting upon. Then a positive result means the member is in tension and a negative result implies compression.




$$\begin{split} \sum F_x &= F_{AB}\cos 36.870^\circ + F_{AD}\cos 51.430^\circ = 0 \\ \sum F_y &= F_{AB}\sin 36.870^\circ - F_{AD}\sin 51.340^\circ - 1650\,\mathrm{N} = 0 \end{split}$$

Now, use the **system-solver** on your calculator to solve these two equations for F_{AB} and F_{AD} .



$\mathsf{Joint}\ A$


Draw the unknown forces in tension, pointing away from the joint they are acting upon. Then a positive result means the member is in tension and a negative result implies compression.




$$\begin{split} \sum F_x &= F_{AB}\cos 36.870^\circ + F_{AD}\cos 51.430^\circ = 0 \\ \sum F_y &= F_{AB}\sin 36.870^\circ - F_{AD}\sin 51.340^\circ - 1650\,\mathrm{N} = 0 \end{split}$$

Now, use the system-solver on your calculator to solve these two equations for F_{AB} and F_{AD} .

 $F_{AB} = 1031.3 \,\mathrm{N}$ and $F_{AD} = -1320.6 \,\mathrm{N}$.



Draw the unknown forces in tension, pointing away from the joint they are acting upon. Then a positive result means the member is in tension and a negative result implies compression.





$$\begin{split} \sum F_x &= F_{AB}\cos 36.870^\circ + F_{AD}\cos 51.430^\circ = 0 \\ \sum F_y &= F_{AB}\sin 36.870^\circ - F_{AD}\sin 51.340^\circ - 1650\,\mathrm{N} = 0 \end{split}$$


Now, use the system-solver on your calculator to solve these two equations for F_{AB} and F_{AD} .


$$F_{AB} = 1031.3 \, \text{N}$$
 and $F_{AD} = -1320.6 \, \text{N}$.


 F_{AB} is positive, so member AB is in tension. F_{AD} is negative, so AD is in compression.












Joint D


Note that we have to include the reaction from the rocker at D in the free body diagram since it also acts on the joint.



$$\sum F_x = F_{CD} \cos 63.435^\circ + 1320.6 \cos 51.340^\circ \text{ N} = 0$$


$$\Rightarrow F_{CD} = -\frac{1320.6 \cos 51.340^\circ \text{ N}}{\cos 63.435^\circ}$$

$$\Rightarrow F_{CD} = -1844.7 \text{ N}$$



Joint D

Note that we have to include the reaction from the rocker at D in the free body diagram since it also acts on the joint.




$$\sum F_x = F_{CD} \cos 63.435^{\circ} + 1320.6 \cos 51.340^{\circ} \text{ N} = 0$$

$$\Rightarrow F_{CD} = -\frac{1320.6 \cos 51.340^{\circ} \text{ N}}{\cos 63.435^{\circ}}$$


$$\Rightarrow F_{CD} = -1844.7 \text{ N}$$


All the internal forces in the truss have now been found.



There are some checks we can make to ensure there are no errors in our calculations. We use moments and the summing of the reactions.


First, determine R_{Dy} , the *y*-component of the reaction at D (D is supported by a rocker and has no *x*-component):






There are some checks we can make to ensure there are no errors in our calculations. We use moments and the summing of the reactions.

First, determine R_{Dy} , the *y*-component of the reaction at D (D is supported by a rocker and has no *x*-component):




$$\begin{split} \sum & F_y = R_{Dy} - 1320.6 \sin 51.340^\circ \text{ N} - 618.78 \text{ N} \\ & - 1844.7 \sin 63.435^\circ \text{ N} = 0 \\ \Rightarrow & R_{Dy} = 3299.9 \text{ N} \end{split}$$



There are some checks we can make to ensure there are no errors in our calculations. We use moments and the summing of the reactions.

First, determine R_{Dy} , the *y*-component of the reaction at D (D is supported by a rocker and has no *x*-component):




$$\sum F_y = R_{Dy} - 1320.6 \sin 51.340^\circ \text{ N} - 618.78 \text{ N}$$

$$- 1844.7 \sin 63.435^\circ \text{ N} = 0$$

$$\Rightarrow R_{Dy} = 3299.9 \text{ N}$$


If we calculate R_{Dy} by taking moments about C of the external forces acting the truss, we get:

$$\begin{split} \sum M_{\text{C}} &= (1650 \text{ N}) \cdot (6.00 \text{ m}) - R_{Dy} \cdot (3.00 \text{ m}) = 0 \\ &\Rightarrow R_{Dy} = 3300 \text{ N} \quad \checkmark \end{split}$$



There are some checks we can make to ensure there are no errors in our calculations. We use moments and the summing of the reactions.

First, determine R_{Dy} , the y-component of the reaction at D (D is supported by a rocker and has no x-component):



$$\sum F_y = R_{Dy} - 1320.6 \sin 51.340^{\circ} \text{ N} - 618.78 \text{ N}$$


$$-1844.7 \sin 63.435^{\circ} \text{ N} = 0$$

$$\Rightarrow R_{Du} = 3299.9 \text{ N}$$

If we calculate R_{Dy} by taking moments about C of the external forces acting the truss, we get:


$$\begin{split} \sum & M_{C} = (1650 \, \mathrm{N}) \cdot (6.00 \, \, \mathrm{m}) - R_{Dy} \cdot (3.00 \, \, \mathrm{m}) = 0 \\ \Rightarrow & R_{Dy} = 3300 \, \mathrm{N} \quad \checkmark \end{split}$$

Note: This is as expected from our previous calculation
— apart from some rounding error in the fifth digit.



Notice that results from members AC, AB, BD and CD were incorporated into this check (since AB was used in the calculation of BD) so it is safe to assume that these results are correct.

But we have not checked member *BC*. We do that by summing all the external forces, and then investigating joint *C*.



Notice that results from members AC, AB, BD and CD were incorporated into this check (since AB was used in the calculation of BD) so it is safe to assume that these results are correct.


But we have not checked member *BC*.

We do that by summing all the external forces, and then investigating joint *C*.

$$\sum F_x = R_{Cx} = 0$$

$$\sum F_y = R_{Cy} + 3299.9 \text{ N} - 1650 \text{ N}$$

$$\Rightarrow R_{Cy} = -1649.9 \text{ N}$$



Notice that results from members AC, AB, BD and CD were incorporated into this check (since AB was used in the calculation of BD) so it is safe to assume that these results are correct.

But we have not checked member *BC*.

We do that by summing all the external forces, and then investigating joint *C*.


$$\sum F_x = R_{Cx} = 0$$

$$\sum F_y = R_{Cy} + 3299.9 \text{ N} - 1650 \text{ N}$$

$$\Rightarrow R_{Cy} = -1649.9 \text{ N}$$

Now, examine joint C for equilibrium:





Notice that results from members AC, AB, BD and CD were incorporated into this check (since AB was used in the calculation of BD) so it is safe to assume that these results are correct.

But we have not checked member *BC*. We do that by summing all the external forces, and then investigating joint *C*.


$$\sum F_x = R_{Cx} = 0$$

$$\sum F_y = R_{Cy} + 3299.9 \text{ N} - 1650 \text{ N}$$

$$\Rightarrow R_{Cy} = -1649.9 \text{ N}$$

Now, examine joint C for equilibrium:

$$\sum F_x = 1844.7 \cos 63.435^{\circ} \text{ N} - 825.04 \text{ N}$$
$$= -0.066554 \text{ N} \approx 0 \quad \checkmark$$



Notice that results from members AC, AB, BD and CD were incorporated into this check (since AB was used in the calculation of BD) so it is safe to assume that these results are correct.

But we have not checked member BC. We do that by summing all the external forces, and then investigating joint C.

$$\sum F_x = R_{Cx} = 0$$

$$\sum F_y = R_{Cy} + 3299.9 \text{ N} - 1650 \text{ N}$$

$$\Rightarrow R_{Cy} = -1649.9 \text{ N}$$


Now, examine joint C for equilibrium:




$$\sum F_x = 1844.7 \cos 63.435^{\circ} \text{ N} - 825.04 \text{ N}$$
$$= -0.066554 \text{ N} \approx 0 \quad \checkmark$$

$$\sum F_y = 1844.7 \sin 63.435^{\circ} - 1649.9 \text{ N}$$

= 0.05057 N \approx 0





The Results


AB = 1030 N (Tension)


AC = 1320 N (Compression)


BC = 825 N (Tension)


BD = 619 N (Compression)


CD = 1840 N (Compression)


























Find the angles


$$\angle DEF = \tan^{-1} \left[\frac{2.50}{3.00} \right]$$
$$= 39.806^{\circ}$$

$$\theta = \tan^{-1} \left[\frac{1.50}{3.00} \right]$$
$$= 26.565^{\circ}$$

$$\angle CAG = \tan^{-1} \left[\frac{4.00}{3.00} \right]$$
$$= 53.130^{\circ}$$

Notice:

- 1. By inspection, truss member DF is a **zero-force** member. (Consider the y-components acting at F.)
- 2. We can start at joint E and analyze the truss joints $E \to F \to D \to G \to C$, without calculating the reactions at A and B.



Find the angles

$$\angle DEF = \tan^{-1} \left[\frac{2.50}{3.00} \right]$$
$$= 39.806^{\circ}$$


$$\theta = \tan^{-1} \left[\frac{1.50}{3.00} \right]$$
$$= 26.565^{\circ}$$

$$\angle CAG = \tan^{-1} \left[\frac{4.00}{3.00} \right]$$
$$= 53.130^{\circ}$$

Notice:


- 1. By inspection, truss member DF is a zero-force member. (Consider the y-components acting at F.)
- 2. We can start at joint E and analyze the truss joints $E \to F \to D \to G \to C$, without calculating the reactions at A and B.
- Finding the reactions at A and B is useful, however, to verify our results; if we have not made
 mistakes, then the sum of all forces acting at A (including the reaction) will equal 0. Similarly, the
 sum of all forces acting at B will equal 0.





Considerations:

- 1. Draw a free body diagram (FBD) for each joint!
- Draw all unknown FBD forces (F_{DE} and F_{DE} in this case) in tension, pointing away from the joint. Then, a positive result indicates tension and a negative result indicates compression.



Joint E




$$\sum F_y = F_{DE} \sin 39.806^{\circ} - 3.50 \text{ kN} = 0$$

 $\Rightarrow F_{DE} = 5.4671 \text{ kN}$

Considerations:

- 1. Draw a free body diagram (FBD) for each joint!
- Draw all unknown FBD forces (F_{DE} and F_{DE} in this case) in tension, pointing away from the joint. Then, a positive result indicates tension and a negative result indicates compression.
- 3. Sum the y-components first, so that we have only one variable (F_{DE}) and can find it directly.



Joint E



$$\sum F_y = F_{DE} \sin 39.806^{\circ} - 3.50 \text{ kN} = 0$$

$$\Rightarrow F_{DE} = 5.4671 \text{ kN}$$


$$\sum F_x = -F_{DE} \cos 39.806^{\circ} - F_{EF} = 0$$

$$\Rightarrow F_{EF} = -5.4671 \cos 39.806^{\circ} \text{ kN}$$

$$= -4.1999 \text{ kN}$$

Considerations:

- 1. Draw a free body diagram (FBD) for each joint!
- Draw all unknown FBD forces (F_{DE} and F_{DE} in this case) in tension, pointing away from the joint. Then, a positive result indicates tension and a negative result indicates compression.
- 3. Sum the y-components first, so that we have only one variable (F_{DE}) and can find it directly.



Joint E



$$\sum F_y = F_{DE} \sin 39.806^{\circ} - 3.50 \text{ kN} = 0$$

 $\Rightarrow F_{DE} = 5.4671 \text{ kN}$


$$\sum F_x = -F_{DE}\cos 39.806^\circ - F_{EF} = 0$$


$$\Rightarrow F_{EF} = -5.4671\cos 39.806^\circ \text{ kN}$$


$$= -4.1999 \text{ kN}$$


Considerations:


- 1. Draw a free body diagram (FBD) for each joint!
- Draw all unknown FBD forces (F_{DE} and F_{DE} in this case) in tension, pointing away from the joint. Then, a positive result indicates tension and a negative result indicates compression.
- 3. Sum the y-components first, so that we have only one variable (F_{DE}) and can find it directly.
- Maintain all 5 working significant digits (or more) for now to reduce the accumulation of rounding errors.


















Joint D





$$\begin{split} \sum F_x &= 5.4671\cos 39.806^\circ \text{ kN} \\ &- F_{CD}\cos 26.565^\circ \\ &- F_{DG}\cos 39.806^\circ \end{split}$$

Now, use the system-solver on your calculator to solve these two equations for F_{CD} and F_{DG} .

= 0

$$F_{CD} = 5.8696 \, \mathrm{kN}, \, F_{DG} = -1.3668 \, \mathrm{kN}$$





$$\sum F_x = 5.4671\cos 39.806^\circ \text{ kN} \\ -F_{CD}\cos 26.565^\circ$$

$$-F_{DG}\cos 39.806^{\circ}$$
$$=0$$


$$\sum F_y = F_{CD} \sin 26.565^{\circ}$$


$$-F_{DG} \sin 39.806^{\circ}$$


 $-5.4671 \sin 39.806^{\circ}$ kN


Now, use the system-solver on your calculator to solve these two equations for F_{CD} and F_{DG} .


$$F_{CD} = 5.8696 \, \mathrm{kN}, \, F_{DG} = -1.3668 \, \mathrm{kN}$$
































Inputs (lengths and the load at E) were accurate to 3 significant digits so our results can be no more accurate than this:

AB = 0.795 kN (Compression)

 $AG = 5.25 \,\mathrm{kN}$ (Compression)

 $BC = 6.40 \,\mathrm{kN}$ (Tension)

 $CD = 5.87 \, \mathrm{kN}$ (Tension)

 $CG = 0.875 \,\mathrm{kN}$ (Tension)


 $DE = 5.47 \,\mathrm{kN}$ (Tension)

DF = 0

 $DG = 1.37 \, \mathrm{kN}$ (Compression)

 $EF = 4.20 \, \text{kN} \, \text{(Compression)}$

 $FG = 4.20 \,\mathrm{kN}$ (Compression)



Inputs (lengths and the load at E) were accurate to 3 significant digits so our results can be no more accurate than this:

AB = 0.795 kN (Compression)

 $AG = 5.25 \,\mathrm{kN}$ (Compression)

 $BC = 6.40 \, \text{kN} \, \text{(Tension)}$

 $CD = 5.87 \,\mathrm{kN}$ (Tension)

 $CG = 0.875 \,\mathrm{kN}$ (Tension)

 $DE = 5.47 \, \text{kN} \, \text{(Tension)}$

DF = 0

 $DG = 1.37 \, \mathrm{kN}$ (Compression)


 $EF = 4.20 \, \text{kN} \, \text{(Compression)}$

 $FG = 4.20 \,\mathrm{kN}$ (Compression)

But are these correct?

We could easily have made an error in a truss member calculation, causing most or all subsequent results to be incorrect.

Let's do a check. We can calculate the reactions at A and B, then check that all external forces acting on the truss do actually sum to zero in the x and y directions.



Inputs (lengths and the load at E) were accurate to 3 significant digits so our results can be no more accurate than this:

AB = 0.795 kN (Compression)

 $AG = 5.25 \,\mathrm{kN}$ (Compression)

 $BC = 6.40 \,\mathrm{kN}$ (Tension)

 $CD = 5.87 \, \text{kN} \, \text{(Tension)}$

 $CG = 0.875 \,\mathrm{kN}$ (Tension)

 $DE = 5.47 \, \text{kN} \, \text{(Tension)}$

DF = 0

 $DG = 1.37 \, \mathrm{kN}$ (Compression)


 $EF = 4.20 \, \text{kN} \, \text{(Compression)}$

 $FG = 4.20 \,\mathrm{kN}$ (Compression)

But are these correct?

We could easily have made an error in a truss member calculation, causing most or all subsequent results to be incorrect.

Let's do a check. We can calculate the reactions at A and B, then check that all external forces acting on the truss do actually sum to zero in the x and y directions.



Inputs (lengths and the load at E) were accurate to 3 significant digits so our results can be no more accurate than this:

AB = 0.795 kN (Compression)

 $AG = 5.25 \,\mathrm{kN}$ (Compression)

 $BC = 6.40 \, \mathrm{kN}$ (Tension)

 $CD = 5.87 \,\mathrm{kN}$ (Tension) $CG = 0.875 \,\mathrm{kN}$ (Tension)


 $DE = 5.47 \, \text{kN} \, \text{(Tension)}$

DF = 0

 $DG = 1.37 \, \mathrm{kN}$ (Compression)

 $EF = 4.20 \, \text{kN} \, \text{(Compression)}$

 $FG = 4.20 \,\mathrm{kN}$ (Compression)



Inputs (lengths and the load at E) were accurate to 3 significant digits so our results can be no more accurate than this:

$$AB = 0.795$$
 kN (Compression)

$$AG = 5.25 \,\mathrm{kN}$$
 (Compression)

$$BC = 6.40 \, \mathrm{kN}$$
 (Tension)

$$CD = 5.87 \,\mathrm{kN}$$
 (Tension)

$$CG = 0.875 \, \mathrm{kN}$$
 (Tension)


$$DE = 5.47 \, \text{kN} \, \text{(Tension)}$$

$$DF = 0$$

$$DG = 1.37 \,\mathrm{kN}$$
 (Compression)

$$EF = 4.20 \, \text{kN} \, \text{(Compression)}$$

$$FG = 4.20 \, \mathrm{kN}$$
 (Compression)



Inputs (lengths and the load at E) were accurate to 3 significant digits so our results can be no more accurate than this:

$$AB = 0.795$$
 kN (Compression)

$$AG = 5.25 \,\mathrm{kN}$$
 (Compression)

$$BC = 6.40 \, \mathrm{kN}$$
 (Tension)

$$CD = 5.87 \,\mathrm{kN} \,\,\mathrm{(Tension)}$$

$$CG = 0.875 \,\mathrm{kN}$$
 (Tension)
 $DE = 5.47 \,\mathrm{kN}$ (Tension)

$$DF = 0$$

$$DG = 1.37 \,\mathrm{kN}$$
 (Compression)

$$EF = 4.20 \, \text{kN} \, \text{(Compression)}$$

$FG = 4.20 \, \mathrm{kN}$ (Compression)

Reaction at A

$$\sum F_x = R_{Ax} - 0.79546\cos 53.130^\circ \text{ kN} - 5.2499 \text{ kN} = 0$$

$$\Rightarrow R_{Ax} = 5.7272 \text{ kN}$$


$$\sum F_{y} = R_{Ay} - 0.79546 \sin 53.130^{\circ} \text{ kN} = 0$$

$$\Rightarrow R_{Ay} = 0.63637 \text{ kN}$$

Reaction at B

$$\sum F_x = R_{Bx} + 6.4032 \cos 26.565^{\circ} \text{ kN} = 0$$

$$\Rightarrow R_{Bx} = -5.7272 \text{ kN}$$



Inputs (lengths and the load at E) were accurate to 3 significant digits so our results can be no more accurate than this:

$$AB = 0.795$$
 kN (Compression)

$$AG = 5.25 \,\mathrm{kN}$$
 (Compression)

$$BC = 6.40 \, \mathrm{kN}$$
 (Tension)

$$CD = 5.87 \,\mathrm{kN}$$
 (Tension)

$$CG = 0.875 \, \mathrm{kN}$$
 (Tension)

$$DE = 5.47 \,\mathrm{kN}$$
 (Tension)

$$DF = 0$$

$$DG = 1.37 \,\mathrm{kN}$$
 (Compression)

$$EF = 4.20 \, \text{kN} \, \text{(Compression)}$$

$$FG = 4.20 \, \mathrm{kN}$$
 (Compression)

Reaction at A

$$\sum F_x = R_{Ax} - 0.79546\cos 53.130^\circ \ {\rm kN} - 5.2499 \ {\rm kN} = 0$$

$$\Rightarrow R_{Ax} = 5.7272 \ {\rm kN}$$

$$\sum F_y = R_{Ay} - 0.79546 \sin 53.130^\circ \text{ kN} = 0$$

$$\Rightarrow R_{Ay} = 0.63637 \text{ kN}$$


Reaction at B


$$\sum F_x = R_{Bx} + 6.4032 \cos 26.565^{\circ} \text{ kN} = 0$$

 $\Rightarrow R_{Bx} = -5.7272 \text{ kN}$

$$\sum F_y = R_{By} - 6.4032 \sin 26.565 \text{ kN} = 0$$

$$\Rightarrow R_{By} = 2.8636 \text{ kN}$$





Inputs (lengths and the load at E) were accurate to 3 significant digits so our results can be no more accurate than this:

$$AB = 0.795$$
 kN (Compression)

$$AG = 5.25 \,\mathrm{kN}$$
 (Compression)

$$BC = 6.40 \, \text{kN} \, \text{(Tension)}$$

$$CD = 5.87 \, \text{kN} \, \text{(Tension)}$$

$$CG = 0.875 \, \text{kN}$$
 (Tension)

$$DE = 5.47 \, \text{kN} \, \text{(Tension)}$$

$$DF = 0$$

$$DG = 1.37$$


$$DG = 1.37 \,\mathrm{kN} \,\, (\mathsf{Compression})$$

$$\mathit{EF} = 4.20\,\mathrm{kN}$$
 (Compression)

$FG = 4.20 \,\mathrm{kN}$ (Compression)

$$\sum F_x = R_{Ax} + R_{Bx} = 5.7272 \,\text{kN} - 5.7272 \,\text{kN} = 0$$

$$\sum F_y = R_{Ay} + R_{By} - 3.50 \text{ kN} = 0.63637 \text{ kN} - 2.8636 \text{ kN} - 3.50 \text{ kN} = -0.00003 \text{ kN}$$



Inputs (lengths and the load at E) were accurate to 3 significant digits so our results can be no more accurate than this:

AB = 0.795 kN (Compression)

 $AG = 5.25 \,\mathrm{kN}$ (Compression)

 $BC = 6.40 \, \text{kN} \, \text{(Tension)}$

 $CD = 5.87 \,\mathrm{kN}$ (Tension)

 $CG = 0.875 \, \mathrm{kN}$ (Tension)

 $DE = 5.47 \, \mathrm{kN}$ (Tension)

DF = 0

 $DG = 1.37 \,\mathrm{kN}$ (Compression)

 $\mathit{EF} = 4.20\,\mathrm{kN}$ (Compression)


 $FG = 4.20 \,\mathrm{kN}$ (Compression)

The final check!

$$\sum F_x = R_{Ax} + R_{Bx} = 5.7272 \,\text{kN} - 5.7272 \,\text{kN} = 0$$

$$\sum F_y = R_{Ay} + R_{By} - 3.50 \text{ kN} = 0.63637 \text{ kN} - 2.8636 \text{ kN} - 3.50 \text{ kN} = -0.00003 \text{ kN}$$

Note: We could also check by taking moments about C or D. (Taking moments about E,F,G or A would not pick up any errors in R_{Ax} . Moments about A or B would not pick up errors in R_{By} or R_{Ay} .)



Inputs (lengths and the load at E) were accurate to 3 significant digits so our results can be no more accurate than this:

AB = 0.795 kN (Compression)

 $AG = 5.25 \,\mathrm{kN}$ (Compression)

 $BC = 6.40 \, \text{kN} \, \text{(Tension)}$

 $CD = 5.87 \,\mathrm{kN}$ (Tension) $CG = 0.875 \,\mathrm{kN}$ (Tension)

DE = 5.47 kN (Tension)

DF = 0

 $DG = 1.37 \,\mathrm{kN}$ (Compression)

 $\mathit{EF} = 4.20\,\mathrm{kN}$ (Compression)

 $FG = 4.20 \,\mathrm{kN}$ (Compression)

The final check!

$$\sum F_x = R_{Ax} + R_{Bx} = 5.7272 \,\text{kN} - 5.7272 \,\text{kN} = 0$$

$$\sum F_y = R_{Ay} + R_{By} - 3.50 \text{ kN} = 0.63637 \text{ kN} - 2.8636 \text{ kN} - 3.50 \text{ kN} = -0.00003 \text{ kN}$$

Note: We could also check by taking moments about C or D. (Taking moments about E, F, G or A would not pick up any errors in R_{Ax} . Moments about A or B would not pick up errors in R_{By} or R_{Ay} .)

