

supply the reference

activity coefficient — better

1.75 → **0.77**

solubility — worse

1.85 → **2.25**