
Build Guide:


All parts:




After unpacking and inspecting your PCB. It should look like this. (Colour may differ).




Solder the diodes and resistors





Solder the Buttons



Solder the headers


- long (teensy) headers on the bottom-side
- short (audio-shield) headers on the top side
- header for display on the top side

Solder the Encoders !!snip off the left (from top view) snap-in-Leg

Solder the jacks on the bottom side


Solder Teensy 4.1 headers

- pay attention to the orientation of the headers
- dont forget the usb host pins (right angled)



Solder Audio shield Headers

• pay attention to the pin length



tbc