







| |
|---|
| PWM0 |
| PWM1 |
| PWM2 |
| **PWM3 : PWMR (60kHz)** |
| **PWM4 : PWMA (60kHz)** |
| **PWM5 : PWMB (60kHz)** |
| PWM6 : PWM_ADC (240kHz) |
| PWM7: PWM_LOOP (20kHz) |
| **PWM8 : PWMC** |


DMAs: ADC is too fast and needs to be fed via DMA, but PWM can be updated from IRQ

| DMA0 : ADC trigger |
|---|
| triggered by: PWM_ADC |
| RINGBUF[8] -> ADC.CS |
| count: infinite |
| chain to: self |


| ~~DMA1 : ADC readout~~ |
|---|
| ~~triggered by: ADC~~ |
| ~~ADC.RESULT -> RINGBUF[8]~~ |
| ~~count: 4~~ |
| ~~chain to: self~~ |

| ~~DMA2 : PWMA.CC~~ |
|---|
| ~~DMA3 : PWMB.CC~~ |
| ~~DMA4 : PWMC.CC~~ |
| DMA1 : PWM.WRAP TIMER1 sample |

| DMA2 : AS5047D TX |
|---|
| DMA3 : AS5047D RX |




| IRQ Priorities |
|---|
| 0: DMA0, PWM0 |
| 1: SPAREIRQ |




reducing latency by doing ADC gathering before PWM interrupt