SO:	S ₅ :
RF_7_Dout \rightarrow Mem.A, T ₁	$T_3 \rightarrow RF.D_3$
Mem.D → IR	$IR_{5-3} \rightarrow RF.A_3$
S1:	S ₇ :
T1 → Alu.A	$T_1 \rightarrow Alu.A$
+1 → Alu.B	$IR_{5-0} \rightarrow SE-6 \rightarrow Alu.B$
Alu.C → T3	Alu.C → T ₃
S2:	S ₈ :
"111" → RF.A3	$T_3 \rightarrow RF.D_3$
T3 → RF.D3	IR ₈₋₆ → RF.A ₃
S3:	S ₉ :
$ R_{11-9} \rightarrow RF.A_1 $	$T_3 \rightarrow Mem.A$
$RF.D_1 \rightarrow T_1$	$T_1 \rightarrow Mem.D$
$ R_{8-6} \rightarrow RF.A_2 $	11 7 Welli.D
$ \begin{array}{c} RF.D_2 \to T_2 \\ T_3 \to T_4 \end{array} $	
S ₄ :	S ₁₁ :
· ·	
$T_1 \rightarrow Alu.A$	"111" → RF.A ₃
$T_2 \rightarrow Alu.B$	$T_2 \rightarrow RF.D3$
Alu.C \rightarrow T ₃	
S _{L3} :	S ₁₃ :
$T_4 \rightarrow T_3$	$T_1 \rightarrow Alu.A$
	$IR_{8-0} \rightarrow SE-9 \rightarrow Alu.B$
	Alu.C → T ₃
S _{L4} :	S _{k'} :
$T_3 \rightarrow RF.D_3$	$T_4 \rightarrow RF.D_3$
$IR_{11-9} \rightarrow RF.A_3$	"111" → RF.A ₃
S _u :	S ₂₀ :
$IR_{8-0} \rightarrow LS$	$ R_{11-9} \rightarrow RF.A_1 $
LS → RF.D ₃	$RF.D_1 \rightarrow T_3$
IR ₁₁₋₉ → RF.A ₃	1 → HW Reset
	IR ₇₋₀ → HW_read
S ₂₁ :	S ₂₂ :
$T_3 \rightarrow Mem.A, T_1$	$T_1 \rightarrow Alu.A$
Mem.D \rightarrow T ₄	+1 → Alu.B
	Alu.C → T ₃
	$T_4 \rightarrow TRF.D_3$
	HW_Add → RF.A3
S _{ro} :	
S_{23} :	S_{24} :
HW_add → RF.A ₂	$T_4 \rightarrow Mem.D$
$RF.D_2 \rightarrow T_4$	$T_3 \rightarrow Mem.A, T_1$
S_{25} :	S ₂₆ :
$T_1 \rightarrow Alu.A$	$T_2 \rightarrow Alu.A$
+1 → Alu.B	$IR_{5-0} \rightarrow SE-6 \rightarrow Alu.B$
Alu.C \rightarrow T ₃	Alu.C → T ₃
S _{2'} :	
"111" → RF.A3	
T3 → RF.D3	