



Main component schematic




Sensors

All the sensors have full boards with their own stepdown modules, so we give 5V to all of them. The working voltage is 3.3V



Power providing
Where input is about 7.5 (2x 18650 batteries)
voltage output is 5V



In our robot the components are soldered on a perf board
Shows the schematics needed for our robots electronics

Sheet: /
File: Wro_customPCBs.kicad_sch

Title: Pinkies electronics

Size: A3 Date: 2026-04-19
KiCad E.D.A. 9.0.3

Rev:
Id: 1/1