General – Additional Information for Stairwell Signage



NY Fire Consultants, Inc.

481 Eighth Avenue, Suite 618 New York, NY 10001 (212) 239 9051 (212) 239 9052 fax





REQUIRED

SIGNAGE ON RESIDENTIAL SIDE OF STARWAY DOORS



Stair Identification Letter

Standpipe Outlet Sign

Close Door Notice

Emergency Markings

<u>Stair Identification Letter</u> is required on both sides of the Door

<u>Standpipe Outlet Sign</u> is required as per Building Code 905.4

Close Door Notice shall be posted and maintained on the public hallway corridor

side of each stairwell door in the building

Emergency Marking Each stainwell door shall be identified as a stainwell door by

placing the fire emergency marking.