



Internet of Things

Don Coleman
Chariot Solutions







<https://goo.gl/eBlkuw>



<http://adafru.it/2282>



University of Michigan Micro Mote <https://flic.kr/p/qUBijw>



<https://flic.kr/p/do5ZHW>







<https://flic.kr/p/6P8dhM>




PROJECT FUNDED BY AMERICAN
RECOVERY AND REINVESTMENT ACT

Spons

RECOVERY.GOV

Project: Investigation and Removal Action
Contractor: Leaking Underground Storage Tan
 TIDEWATER INC



PLUS!

VEEDER-ROOT



MAY 4, 2017 4:12:24 PM
T 2:PROBE OUT

ALARM



WARNING





POWER






VEEDER-ROOT

UST Monitoring System





[Alarms](#)[Monthly Compliance](#)[Exports](#)[Customer ▾](#)[alarmmgr ▾](#)

[New](#) [Drafts](#) [Awaiting Approval](#) [Pending Resolution](#) [Resolved](#) [Create](#)

Priority	Station ID	Alarm(s)	Date	Label
●	SID-FL0016	T1: Tank Invalid Fuel Level Alarm	05/03/17 at 04:11 PM EDT	

Don Coleman

 don@chariotsolutions.com

 github.com/don

 [@doncoleman](https://twitter.com/doncoleman)

