	Key Combin	ations
Command	,	
Extrude	Е	
Hole	Н	
Press Pull	Q	
Fillet	F	
Move	M	
Toggle Visibility	V	
Toggle Component Color Cy	ycling Shift + N	
Model Toolbox	S	
Appearance	Α	
Compute All	Crtl + B (Wind	ows) or Command + B (Mac)
Joint	J	
As-built Joint	Shift + J	
Line	L	
2-point Rectangle	R	
Center Diameter Circle	С	
Trim	Т	
Offset	0	
Measure	I	
Project	Р	
Normal / Construction	Χ	
Sketch Dimension	D	
Scripts and Add-ins	Shift + S	
Window Selection	1	
Freeform Selection	2	
Paint Selection	3	
Delete	Del	
System Keyboard Shortc	uts Windows Ke Combinatior	
Create Version	Ctrl + S	Command + S
Recovery Save	Ctrl + Shift + S	S Command + Shift + S
Canvas Selection	Windows Key Combinations	Mac Key Combinations
Pan	Hold Middle Mouse Butto	n Hold Middle Mouse Button

Canvas Selection	Windows Key Combinations	Mac Key Combinations
Zoom	Roll Middle Mouse Button	Roll Middle Mouse Button
Orbit	Hold Shift + Hold Middle Mouse Button	Hold Shift + Hold Middle Mouse Button
Orbit around point	Hold Shift + Click then Hold Middle Mouse Button	Hold Shift + Click then Hold Middle Mouse Button
Undo	Ctrl + Z	Command + Z
Redo	Ctrl + Y	Command + Y
Сору	Ctrl + C	Command + C
Paste	Ctrl + V	Command + V
Cut	Ctrl + X	Command + X
Sculpt Workspace Selection	Windows Key Combinations	Mac Key Combinations
Grow selection	Shift + Up Arrow	Shift + Up Arrow
Shrink selection	Shift + Down Arrow	Shift + Down Arrow
Loop selection	Alt + P	Control + P
Loop grow selection	Alt + O	Control + O
Ring selection	Alt + L	Control + L
Ring grow selection	Alt + K	Control + K
Ring shrink selection	Alt + J	Control + J
Previous U	Alt + Left Arrow	Control + Command + Left Arrow
Next U	Alt + Right Arrow	Control + Command + Right Arrow
Previous V	Alt + Down Arrow	Control + Command + Down Arrow
Next V	Alt + Up Arrow	Control + Command + Up Arrow
Range selection	Alt + M	Command + M
Invert selection	Alt + N	Command + N
Toggle box mode	Alt + 1	Control + 1
Toggle control frame mode	Alt + 2	Control + 2
Toggle smooth mode	Alt + 3	Control + 3
Select edge ring	Double-click an edge	Double-click an edge
Select face ring	Select two faces then double-click a third face	Select two faces then double-click a third face

Edit Form Command	Windows Key Combinations	Mac Key Combinations
Add geometry	Alt + Drag	Alt + Drag
Add geometry and keep creases	Alt + Ctrl + Drag	Alt + Command + Drag
Render Workspace Command	Windows Key Combinations	Mac Key Combinations
Appearance	A	A
Animate Workspace Command	Windows Key Combinations	Mac Key Combinations
Transform Components	M	M
Auto Explode All Levels	U	U
Manual Explode	E	E
View	U	U
Publish Video	Р	Р
Simulate Workspace Command	Windows Key Combinations	Mac Key Combinations
New Simulation Study	N	N
Structural Constraint	С	С
Structural Loads	L	L
Force	F	F
Model View	Ctrl + L	Command + L
DOF View	Ctrl + D	Command + D
Groups View	Ctrl + G	Command + G
Results View	Ctrl + R	Command + R
Settings	Е	Е
Drawing Workspace Command	Windows Key Combinations	Mac Key Combinations
Projected View	Р	Р
Move	M	M
Delete	Delete	Delete
Center Mark	С	С
Dimension	D	D
Text	Т	Т
Balloon	В	В

CAM Workspace Command	Windows Key Combinations	Mac Key Combinations
Generate Toolpath	Ctrl + G	Command + G
Duplicate	Ctrl + D	Command + D
Show Log	Ctrl + L	Command + L
Scripts and Add-Ins	Shift + S	Shift + S

Shortcuts for switching workspaces

You can now switch workspaces with CTRL + Leftbracket and CTRL + Rightbracket key combos. This will take you through the next and previous workspace in the order it is listed in the workspace switcher.

