2006 Honda Insight

2000-06 ENGINE Intake Manifold & Exhaust System - Insight

2000-06 ENGINE

Intake Manifold & Exhaust System - Insight

INTAKE MANIFOLD REMOVAL AND INSTALLATION

NOTE: Use new O-rings and gaskets when reassembling.




Fig. 1: Exploded View Of Intake Manifold Courtesy of AMERICAN HONDA MOTOR CO., INC.

EXHAUST PIPE AND MUFFLER REPLACEMENT

NOTE: • Use new gaskets and self-locking nuts when

2006 Honda Insight

2000-06 ENGINE Intake Manifold & Exhaust System - Insight

reassembling.

 When the secondary HO2S or the third HO2S is replaced, replace them as a set.




Fig. 2: Exploded View Of Exhaust Pipe And Muffler Courtesy of AMERICAN HONDA MOTOR CO., INC.