	LENDER 5 COP 1							
Vida	Mortgage Valuation Repor							
Homeloans	Lender Ref: 9a5d8beb-67e2-422c-b182-4b14eebd7731 Mr Bill Reed							
Applicant Name(3)	Test House							
Property Address	32380							
	Second Street Solihull							
	Postcode B40 8SS If New, Plot Number							
Was the address provide	ed in the instructions correct (if no, provide correct address above) Y/N Y							
Purchase price/estimate	ed value (as stated in instruction, or to the valuer) £ 150000							
Property Type	House X Bungalow Flat Studio flat Maisonette Other							
Property Style	Detached X Semi Mid Terrace End Terrace							
	Details if other:							
	Purpose Built Y/N Appears to be ex-LA/HA/MOD or similar? Y/N N							
Flat/Maisonette	No. floors in block Subject flat on floor (Street level = 0) Lift to this floor? Y/N							
Location	Above commercial property? Y/N N Adjacent to commercial property? Y/N N If yes, to either							
	of above, details							
Accommodation (No.)	Floors 2 Living Rooms Kitchens Bedrooms Bathrooms							
	Total Internal WCs Other 1 Garages 0 Parking 2							
	Garages or private parking outside curtilage?							
	If yes, details							
Gardens	Private Communal None X							
Area as stated to valuer	Likely to be over 1 Acre? Y/N If yes, approx. area							
(not measured) Approx. year built	1995 New Property Y/N N Sufficiently completed for mortgage purposes Y/N							
Stage completed	Land purchase Wallplate Roofed in Plastered out							
Name of Builder	Self Build Y/N							
If New or <10 years	NHBC BLP Build Assure Build Zone Castle 10 CRL							
	Premier Prof. Consultant. LABC Other None None N/K							
	Details if PC or other							
Construction:	Are the walls of standard construction? Y/N N							
(refer to guidance notes)	If no, details							
	Is the roof of standard construction? Y/N N Is any part thatched Y/N N							
	Details Test.							
	Property converted, extended or evidence of significant alterations?							
	If yes, details & The property appears to have been converted from a single dwelling (e.g. house) in approximately 2004. It is assumed that the necessary consents have been obtained and complied with.							
	approx. date(s)							
Services	Does the property have mains water, electricity and drainage? Y/N N If no, details There is no.							
	If no, details							
Tenure	Freehold X Scottish Leasehold If Leasehold, remaining term (years)							
As stated to or assumed by								
the valuer, legal advisor to verify in report on title.	Flying Freehold Y/N N If yes, details and approx. %							
	Details of ground rent and maintenance charges if known							
	Is there any evidence of tenancy?							
	Is there any evidence of tenancy? If yes, details							
	If yes, details							
	, <u> </u>							

Matters considered esse	Matters considered essential for mortgage purposes											
	Is there any evidence of structural movement, landslip or heave in the property or in the immediate vicinity?						Y/N N					
المراجع	If yes, does it		Y/N									
If no,details												
					f flooding/coastal erosion		Y/N N					
If yes, details	(NB The value	er nas not c	arried out	any researcn)			T/IN [IN]					
0	Otrosatornal											
Specialist reports Y/N Details/Other	Structural Arboricultural	N N	Wall tie	Timber & damp N	Mundic N	Electric Other	al N N					
Betaile/Ctrief												
Legal Enquiries	la thora avida	nee of any r	iahta of w	ay abarad assass ar asl	ar nanala?		Y/N Y					
If yes, details There may be some energy efficient mea				ay, shared access or sol s to investigate.	ar paneis?		Y/N[Y]					
Are any essential repairs	required for	mortgage p	ourposes?	?								
If yes, details A functional bathroom should be installe	d.						Y/N Y					
Are there any further ma	tters consider	ed essenti	al for mor	tgage purposes?								
If yes, details The instructed EV/PP of the property has	s been amended beca	use Test.					Y/N Y					
General Remarks (please	provide a brief	general desc	cription of th	ne overall appearance of t	he property and general sur	roundings	s)					
u u					, .	J	,					

Valuation	IMPORTANT - PLEASE READ	THE ATTACHED NOT	ES CAREFULLY	
Recommendation	mply with Lender's Guidelines to Valuers	2		
If No, please provide		ſ		Y/N Y
	If new, the valuer has seen the Dis	sclosure of Incentives Form	dated	
	and taken into account in valuation			Y/N N
Valuation	Present condition (for incomplete i	new property, enter zero)	£ 350000	
	With essential repairs / construction	n completed	£ 400000	
	Is a retention required?	No X	Part	Full 🗌
	If part, enter amount, min. £2000	(This is not an estimate of o	costs) £	
	Is a reinspection necessary			Y/N N
Buildings Insurance	(If the property is outside of the BCIS	S calculation method, ent	er 0 and explain in essential	matters.
Approximate gross ex	kternal floor area (square metres)	2300 Insurance Reins	statement (BCIS) £ 1200000	
I confirm I have atta	ched photos of the Front, Rear, Kitch	en. Bathroom and Street.		Y/N Y
If No, please provide	•	,		
	ed in this report has been inspected by me in accordance with report and that I am not subject to any conflict of interest or su			
a lending decision.		_		
Name of Valuer	Tom Grisley	Qualifications	VRS	Y/N N
RICS No.	Sign	nature or Security Code		
Firm Name	Bansal Surveyors Ltd	Telephone	01215554444	
Address	Bansal Street			
5	Bansal Heath	B90 4SS		
Date of Inspection	2019-01-07	Date of Report		
Mortgage Va	aluation, Supplement	al Questions (Non-disclosed)	
wortgage ve	aidation, oupplement	ai wacstions (i	Mon-disclosed)	
The Lender needs to	be aware of properties which unde	r normal or good market	conditions resell satisfactor	ily, but
	arket conditions due to location, envi			one of
	ready have been reflected in your cu on is to establish the valuer's view of			ns at
(NB Refer to Guidan		, , , , , , , , , , , , , , , , , , , ,		
Dloggo indicato whi	ch category this property falls into	and if the "weree" enti	on is solocted please pro	vido
	lverse factors leading you to this cor		on is selected, please pro	vide
	f this property is likely to rise and fall		market conditions.	
The location	i, environmental factors or individual ter than the general market condition		may cause the value to	
The location	, environmental factors or individual	features of this property	may cause the value to	
•	rse than the general market conditio	ns		
If worse, co	mments			
Above Commercial	(Category for MI only - refer to lend	er guidance)		
Restaurant		<u> </u>	aunderette Othe	er 🖂
	rty is a flat, approximately how many	_	_	
	Let board present at the time of the	•		Y/N N
inspection If yes, pl	ease provide agent name and askin	g price.		
inspection If yes, pl	ease provide agent name and askin	g price.		