# Sitenotes

Address:	1 ARNHILL ROAD, GRETTON, CORBY, NN17 3DN
Customer:	Test Name
Assesment Date:	30/11/2018
Surveyor:	unotest unotest
Company:	Bansal Surveyors Ltd
Forms Version:	VidaReleaseUnique

# 480 - Vida General Details


5401 - Circumstance			
658342 - Amended EV/PP is %%q(61016). Please provide explanation. EV/PP amended because	Test		
61001 - Is address correct? %%adr(61001)	Yes		
61004 - Time of Arrival	14:46		
61005 - Time of Departure	14:46		
61006 - Person Present/Access:	Agent		
61013 - Mortgage Purpose:	Not Known		
61009 - Is the EV/PP provided on the instruction correct? £%%i(EstimatedPrice)	No		
61016 - Record amendments:	£150000		
61003 - Date of inspection	30/11/2018		
61007 - Occupancy Status:	Vacant		
658086 - Do you want to answer the owner occupier questions?	No		
61010 - Weather	Dry		
61011 - Furnishings:	Unfurnished		
61012 - Floor coverings:	Uncarpeted		
677384 - Property Location:	England		
704119 - Are there any significant limitations to inspection over and above normal occupation?	No		
5402 - Property Type and Style			
61020 - Property Type	House		
678810 - Is the property a listed building?	No		
61021 - Property Style	Detached		
61022 - Build Format	Converted		
61023 - Is the property of public sector origins?	No		
685475 - Is the property adjacent to commercial premises?	No		
5403 - Location			
61040 - Area predominantly	Residential		
61041 - Location Type	City		
61024 - Property/Location details:	Private		
61042 - Level of Local Amenities	None		


61044 - Are there any Adverse Locational Factors?	No
658274 - Is there pedestrian access only?	No
61047 - Status of Roads and Pavements abutting the property	Private / Unadopted
61048 - Condition of Roads and Pavements abutting the property	Unmade
5404 - Tenure and Legal	
61050 - Record Tenure	Freehold
61075 - Source of Tenure Information	Owner
61057 - Is there any evidence of commercial or agricultural use?	No
61061 - Are you aware of, or suspect there to be any occupancy restrictions?	No
61064 - Are you aware of any low cost home ownership schemes?	No
61067 - Are there any other legal matters needing further investigation?	No
5410 - Risk Matters	
61120 - Site topography is:	Level
61121 - Any trees within influencing distance of the property?	No
61127 - Is there evidence of structural movement, landslip or heave to the property?	No
61132 - Is there any reason to believe the property may be at risk of flooding?	No
677555 - Coastal erosion. Are you aware of any significant risk within influencing distance of the property?	No
61140 - Any adverse site/risk factors?	None
5412 - Property Age	
61160 - Original year of construction:	1995
61161 - The property has been converted from an existing building, which originally comprised of	a single dwelling (e.g. house)
61162 - Approximate year of conversion:	2005
61163 - Is the property awaiting first occupation in its current form (e.g. new build/conversion)	No
61173 - Is original year of construction/conversion less than 10 years?	No
61174 - Signs of significant alterations/extensions to the property over and above the conversion works?	No
5413 - Construction Classification	


#### 5413 - Construction Classification

Solid Brick		
brickwork, blockwork or insubstantial material?  61214 - Is the roof of standard construction?  61909 - Please give details of roof construction:  685484 - Please provide approximate percentage of flat roof (Approx. % over habitable areas excluding garages and outbuildings):  677043 - Does the roof appear to be of acceptable type and condition for mortgage purposes?  704428 - Please state the gross external floor area (GEA):  704428 - Please state the gross external floor area (GEA):  7044363 - Are there solar panels at the property?  70570467 - Will the property be affected by HS2?  7057469 - Are there any further comments you would like to report in the General Remarks section of the report?  7057472 - Have you taken the required photos? (Front, Rear, Bathroom, Kitchen, Street)  70576750 - Is an electrical report required?  7057677 - Is an electrical report required?  705777781 - Re there any further comments you would like to report in the Further Matters Considered Essential section of the report?  7057781 - Please select the most appropriate statement that the property falls into.		Solid Brick
No   Test		No
6999 - Please give details of roof construction:  685484 - Please provide approximate percentage of flat roof (Approx. % over habitable areas excluding garages and outbuildings):  677043 - Does the roof appear to be of acceptable type and condition for mortgage purposes?  704428 - Please state the gross external floor area (GEA):  704428 - Please state the gross external floor area (GEA):  677463 - Are there solar panels at the property?  No  677469 - Are there any further comments you would like to report in the General Remarks section of the report?  677472 - Have you taken the required photos? (Front, Rear, Bathroom, Kitchen, Street)  704018 - Do any of the following circumstances apply  677657 - Are you aware of any energy efficient measures that have been added to the property?  677677 - Is an electrical report required?  677478 - Are there any further comments you would like to report in the Further Matters Considered Essential section of the report?  6776780 - Other than drainage, are you aware of any other shared services?  677581 - Please select the most appropriate statement that the property falls into.	61214 - Is the roof of standard construction?	No
685484 - Please provide approximate percentage of flat roof (Approx. % over habitable areas excluding garages and outbuildings):  677043 - Does the roof appear to be of acceptable type and condition for mortgage purposes?  704428 - Please state the gross external floor area (GFA):  677463 - Are there solar panels at the property?  677467 - Will the property be affected by HS2?  677469 - Are there any further comments you would like to report in the General Remarks section of the report?  677472 - Have you taken the required photos? (Front, Rear, Bathroom, Kitchen, Street)  704018 - Do any of the following circumstances apply  677475 - Are you aware of any energy efficient measures that have been added to the property?  677507 - Is an electrical report required?  677478 - Are there any further comments you would like to report in the Further Matters Considered Essential section of the report?  677480 - Other than drainage, are you aware of any other shared services?  677581 - Please select the most appropriate statement that the property falls into.	677040 - Is any part thatched?	No
roof (Approx. % over habitable areas excluding garages and outbuildings):  677043 - Does the roof appear to be of acceptable type and condition for mortgage purposes?  70428 - Please state the gross external floor area (GEA):  677463 - Are there solar panels at the property?  70467 - Will the property be affected by HS2?  70469 - Are there any further comments you would like to report in the General Remarks section of the report?  704712 - Have you taken the required photos? (Front, Rear, Bathroom, Kitchen, Street)  704018 - Do any of the following circumstances apply  704018 - Do any of the following circumstances apply  707765 - Are you aware of any energy efficient measures that have been added to the property?  707778 - Are there any further comments you would like to report in the Further Matters Considered Essential section of the report?  707780 - Other than drainage, are you aware of any other shared services?  707781 - Please select the most appropriate statement that the property falls into.	61909 - Please give details of roof construction:	Test
and condition for mortgage purposes?  39550 - Lender Specific  704428 - Please state the gross external floor area (GEA):  677463 - Are there solar panels at the property?  677467 - Will the property be affected by HS2?  677469 - Are there any further comments you would like to report in the General Remarks section of the report?  677472 - Have you taken the required photos? (Front, Rear, Bathroom, Kitchen, Street)  704018 - Do any of the following circumstances apply  677465 - Are you aware of any energy efficient measures that have been added to the property?  677478 - Are there any further comments you would like to report in the Further Matters Considered Essential section of the report?  677480 - Other than drainage, are you aware of any other shared services?  677581 - Please select the most appropriate statement that the property falls into.	roof (Approx. % over habitable areas excluding garages	25 %
1500 m²   1500	· · · · · · · · · · · · · · · · · · ·	Yes
GEA :	39550 - Lender Specific	
677467 - Will the property be affected by HS2?  677469 - Are there any further comments you would like to report in the General Remarks section of the report?  677472 - Have you taken the required photos? (Front, Rear, Bathroom, Kitchen, Street)  704018 - Do any of the following circumstances apply  677465 - Are you aware of any energy efficient measures that have been added to the property?  677507 - Is an electrical report required?  677478 - Are there any further comments you would like to report in the Further Matters Considered Essential section of the report?  677480 - Other than drainage, are you aware of any other shared services?  677581 - Please select the most appropriate statement that the property falls into.		1500 m <sup>2</sup>
G77469 - Are there any further comments you would like to report in the General Remarks section of the report?  G77472 - Have you taken the required photos? (Front, Rear, Bathroom, Kitchen, Street)  704018 - Do any of the following circumstances apply  F77465 - Are you aware of any energy efficient measures that have been added to the property?  F77507 - Is an electrical report required?  F77478 - Are there any further comments you would like to report in the Further Matters Considered Essential section of the report?  F77480 - Other than drainage, are you aware of any other shared services?  F77581 - Please select the most appropriate statement that the property falls into.	677463 - Are there solar panels at the property?	No
like to report in the General Remarks section of the report?  677472 - Have you taken the required photos? (Front, Rear, Bathroom, Kitchen, Street)  704018 - Do any of the following circumstances apply  677465 - Are you aware of any energy efficient measures that have been added to the property?  677507 - Is an electrical report required?  No  677478 - Are there any further comments you would like to report in the Further Matters Considered Essential section of the report?  677480 - Other than drainage, are you aware of any other shared services?  677581 - Please select the most appropriate statement that the property falls into.  The value of this property is likely to rise and fall in line with general market conditions.	677467 - Will the property be affected by HS2?	No
Rear, Bathroom, Kitchen, Street)  704018 - Do any of the following circumstances apply  677465 - Are you aware of any energy efficient measures that have been added to the property?  677507 - Is an electrical report required?  No  677478 - Are there any further comments you would like to report in the Further Matters Considered Essential section of the report?  677480 - Other than drainage, are you aware of any other shared services?  677581 - Please select the most appropriate statement that the property falls into.  The value of this property is likely to rise and fall in line with general market conditions.	like to report in the General Remarks section of the	General condition satisfactory and consistent with age
677465 - Are you aware of any energy efficient measures that have been added to the property?  677507 - Is an electrical report required?  677478 - Are there any further comments you would like to report in the Further Matters Considered Essential section of the report?  677480 - Other than drainage, are you aware of any other shared services?  677581 - Please select the most appropriate statement that the property falls into.  No  No  The value of this property is likely to rise and fall in line with general market conditions.	C77472 II	
measures that have been added to the property?  677507 - Is an electrical report required?  No  677478 - Are there any further comments you would like to report in the Further Matters Considered Essential section of the report?  677480 - Other than drainage, are you aware of any other shared services?  677581 - Please select the most appropriate statement that the property falls into.  The value of this property is likely to rise and fall in line with general market conditions.		Yes
677478 - Are there any further comments you would like to report in the Further Matters Considered Essential section of the report?  677480 - Other than drainage, are you aware of any other shared services?  677581 - Please select the most appropriate statement that the property falls into.  The value of this property is likely to rise and fall in line with general market conditions.	Rear, Bathroom, Kitchen, Street)	
like to report in the Further Matters Considered Essential section of the report?  677480 - Other than drainage, are you aware of any other shared services?  No  677581 - Please select the most appropriate statement that the property falls into.  The value of this property is likely to rise and fall in line with general market conditions.	Rear, Bathroom, Kitchen, Street)  704018 - Do any of the following circumstances apply  677465 - Are you aware of any energy efficient	N/A
other shared services?  677581 - Please select the most appropriate statement that the property falls into.  The value of this property is likely to rise and fall in line with general market conditions.	Rear, Bathroom, Kitchen, Street)  704018 - Do any of the following circumstances apply  677465 - Are you aware of any energy efficient measures that have been added to the property?	N/A No
that the property falls into. conditions.	Rear, Bathroom, Kitchen, Street)  704018 - Do any of the following circumstances apply  677465 - Are you aware of any energy efficient measures that have been added to the property?  677507 - Is an electrical report required?  677478 - Are there any further comments you would like to report in the Further Matters Considered Essential	N/A No No
685468 - Is a reinspection required?	Rear, Bathroom, Kitchen, Street)  704018 - Do any of the following circumstances apply  677465 - Are you aware of any energy efficient measures that have been added to the property?  677507 - Is an electrical report required?  677478 - Are there any further comments you would like to report in the Further Matters Considered Essential section of the report?  677480 - Other than drainage, are you aware of any	N/A No No No
	Rear, Bathroom, Kitchen, Street)  704018 - Do any of the following circumstances apply  677465 - Are you aware of any energy efficient measures that have been added to the property?  677507 - Is an electrical report required?  677478 - Are there any further comments you would like to report in the Further Matters Considered Essential section of the report?  677480 - Other than drainage, are you aware of any other shared services?  677581 - Please select the most appropriate statement	N/A  No  No  No  No  The value of this property is likely to rise and fall in line with general market

## 5443 - Photographs Required







#### 5406 - Plot

61090 - Gardens:

Front

61091 - Does the plot exceed 1 acre?

No

677455 - Are you aware the applicant owns any land adjoining the subject property?

No

5407 - Garage

61100 - Garage:

Double Garage

61101 - Specify style of Garage:

Integral

#### 5408 - Parking

61111 - Parking arrangements (instead of, or additional to, garage):

Private Driveway

61112 - Please state the number of parking spaces:

2

#### 5409 - Outbuilding

61299 - Is Outbuildings none?

No

# 163 - External Elements

5417 - Flat Roof				
61330 - Existence		No		
61331 - Visibility		Full		
61332 - Covering		Not Known		
61333 - Feature		Not Applicable		
5419 - External Walls				
61370 - Visibility		Full		
61371 - Type		Solid		
61372 - Thickness		mm350		
61373 - Wall Finish		Brick		
61431 - DPC Construction		Not Applicable		
61450 - Adequacy of Sub Floor Ventilation		Adequate		
5420 - Windows, Glazing & External Joinery				
61390 - Windows (Framing)		PVCu		

61390 - Windows (Framing)		PVCu
61391 - Windows (Glazing)		Double Glazed
61412 - External Joinery	1	Timber

## 164 - Internal Elements

5429 - Fl	oors	
-----------	------	--

690579 - Existence	No
61570 - Ground Floor Construction of Subject	Not Applicable
61571 - Upper Floor Construction of Subject	Not Applicable

## 5442 - Fittings & Fixtures

61790 - Kitchen	Average
61791 - Bathroom	Average
61792 - Other Fittings and Fixtures	Average

## 165 - Services 5435 - Water 61902 - Existence No 61650 - Water Supply Mains 5436 - Drainage 61903 - Existence No 61670 - Drainage System Mains 5437 - Heating 61904 - Existence No Full 61691 - Extent

Gas

Radiators

61692 - Type

61693 - Outlet

# 190 - Valuation and Comps

5432 - Va	luation &	Comps
-----------	-----------	-------

61831 - Suitable as mortgage security	Yes
61832 - Present condition value	£250000
61833 - Retention	No
61834 - Retention amount	£0
61836 - Value after works complete	£300000
61830 - Instructed EV/PP	£150000
62106 - I can confirm that there is no conflict of interest and I have geographical competence in valuation location.	Yes
62107 - Any sign of suspicious circumstance/fraud?	No

### **Reinstatement Summary**

1500 sqm	GEA	@ £350.00 /sqm	£525000.00
		Total	£525000.00
		Total Reinstatement cost:	£525000.00