

	Temperature 8	D - I - 4!	. I . I	0
HIMPAU	i emperatiire a	C REISTIVE	HIIMIMIT	Sensor

Clear	——————(Ground)
White-RH signal	——— SE6
Blue	G
Brown	12V
Black-Temp Signal	SE5
CS700 Rain Gauge	
Clear	——— <u>↓</u> (Ground)
White	——— — (Ground ——— — (Ground

CS106/PTB110 Barometric Pressure Sensor

Blue	1H (SE1)
Yellow	(Ground)
Clear	(Ground)
Black	G
Red	12V
Green	C1

Red - Power 12V

CCFC WEB CAM

Black	G
White – Camera RX	C7 RS232 Logger TX
Green – Camera TX	C8 RS232 Logger RX