Clariant Produkte (Deutschland) GmbH
Höchst site, Quality Management
Fax: ++49 69 / 305-38467

CLARIANT

Clariant South East Asia Pte. Ltd.
#08-03/04 The Synergy
SINGAPORE 609917
SINGAPORE

I n s p e c t i o n c e r t i f i c a t e
according to EN10204-3.1

Date: 24.04.2025

Your order from 12.03.2025
Order No. : 4507206713
Material No. : 000000010788514735
Delivery no./Pos. : 54467868 / 900001
Order : 16270726
Material : DRYGEN P
Material-no. : 10788514735
Batch No. : 2103015359
Quantity : 720 KG

On the batch, of which the consignment is a part, the following values were determined.

Inspection characteristic/-method	Specification	Result
Aluminium TLP-Ge-01	24.6 - 25.6	25.2 %[m/m]
Aluminium oxide (as Al2O3) TLP-Ge-01	46.4 - 48.4	47.6 %[m/m]
Chloride TLP-Ge-02	16.3 - 17.3	17.0 %[m/m]
Iron TLP-Ge-04	<= 100	92 mg/kg
Grain size < 40 µm TLP-Ge-11	>= 99.5	100.0 %[m/m]
Molar ratio aluminium / chloride TLP-Ge-03	1.91 - 2.10	1.95
pH value (15 %[w/w] in water) TLP-Ge-05	4.10 - 4.45	4.17

Date of production: 01.04.2025

Best before date: 31.03.2029

Clariant Produkte (Deutschland) GmbH
Höchst site, Quality Management
Fax: ++49 69 / 305-38467

CLARIANT

Clariant South East Asia Pte. Ltd.
#08-03/04 The Synergy
SINGAPORE 609917
SINGAPORE

I n s p e c t i o n c e r t i f i c a t e
according to EN10204-3.1

Date: 24.04.2025

Material : DRYGEN P
Material No. : 10788514735
Batch No. : 2103015359

Inspection characteristic/-method	Specification	Result

We guarantee 4 years storage stability for all DRYGEN® types stored in originally sealed containers.
DRYGEN® S and P are hygroscopic and should therefore be kept in a dry place. Once containers have been opened, their contents should be used without delay since there is a risk of agglomeration caused by the adsorption of moisture from the atmosphere. Agglomerates are frequently the cause of valve blockage in aerosol products.

The above particulars do not release the customer from the obligation to carry out an inspection of goods received.

Helmut Madl (inspection representative)

This report does not require a signature.