Rear panel

TS-WXL



Big fans are noticeable.

Characteristic is the cable drop prevention band below the power connector. As expected for companies.

The fan was easily lost when the five screws were removed. It is a mystery why the fifth screw was needed



Fan guards and fans are crimped and cannot be easily removed.

Rakuten Ichiba
Amazon
Yahoo Shopping
Livedoor Department Store



TS-WXL

<u>←</u> <u>Key is in the way</u> Hack of record
LinkStation / KuroBox trying to
hack

Remove the cover

Copyright (C) 2003-2010 Yasunari Yamashita. All Rights Reserved. <u>Yasunari</u> yama yamasita.jp <u>Yasunari Yamashita</u>向 Mukoichi, Kyoto