Fast and slow modes

$$G(s) = \frac{100}{(s+10)^2}\left(\frac{1}{s+1} + \frac{0.5}{s+0.05}\right)$$

n=1

Trend IAE

fast and slow modes