



Quarterly of the National Fire Protection Association Volume 11

By National Fire Association

Rarebooksclub.com, United States, 2012. Paperback. Book Condition: New. 246 x 189 mm. Language: English . Brand New Book ***** Print on Demand *****. This historic book may have numerous typos and missing text. Purchasers can download a free scanned copy of the original book (without typos) from the publisher. Not indexed. Not illustrated. 1917 Excerpt: .great headway and did \$50,000 damage before it was extinguished. Even a well-ventilated basement, however, is a most unsuitable place for the storage of gasoline, which should be kept in outside tanks of approved construction. H-12611. There were no outside openings to this basement, and the smoke, being very dense, it was impossible for the firemen to reach the seat of the fire from the stairway opening. The fire was not extinguished until after the collapse of the first floor. Watch Service. H-5376. A loss of \$66,500 was caused by this fire, which, owing.to the absence of alarm service, had gained great headway before its discovery. H-7131. This \$150,000 fire was not discovered until it had been burning for several hours. No watchman service was maintained. S-15727. This fire occurred on a Saturday afternoon after the grocery had closed, but before the watchman, who was on...



Reviews

Extensive information for book fans. It is writter in basic words and never hard to understand. It is extremely difficult to leave it before concluding, once you begin to read the book.

-- Otis Wisoky

This publication is great. It is full of wisdom and knowledge You will not really feel monotony at at any time of the time (that's what catalogs are for relating to when you ask me).

-- Dr. Everett Dicki DDS