
(a) Weak loading information
Twice nll increase
Sensor loading $U_s/U_{a,0}$
(b) Active run bound
Twice nll increase
Step run 1 conductance ratio
(c) Disturbance length
Twice nll increase
T1 disturbance length (s)
(d) Nonnegative radiation
Twice nll increase
Radiation coefficient at 50 C / $U_{a,0}$