Item	Quantity	Unit Value	Total	Statutory Category
Comments Section of Inspection Report				
Roof			3500	b
Furnace Check			65	j
Vacuum Breakers			10	i
Smoke Detectors	5	10	50	-
Carbon Monoxide Detectors	2	25	50	-
Repair service walk			500	b
Repair chimney masonry			500	С
Paint shed			600	а
Repair window in bathroom			200	f
Install screens	11	30	330	f
Replace trim 2nd floor			50	О
Extend hot water heater relief pipe			10	n
Turn on all utilities				
Replace broken treads on front steps			300	b
Electrical section of report - prices not listed are covered in				
this price			1500	
Replace front GFCI				h
Rediaper Service Entrance gooseneck				h
Repair, replace, or remove AC				h
Repair 2 backyard bullding lights			50	
Provide GFCI in bathroom				h
Remove hanging wire and seal opening from driveway-side bedroom				h
Provide switched lighting in upstairs bedroom				h
Provide switched lighting in upstairs storage room				h
Bond around the water meter				h
Provide 20A GFCI outlet within 6 feet of washer and dryer.				h
Provide 230V to dryer outlet or remove				h
In basement, remove all lampholders with builtin outlets				h
Provide a junction box for the connection of the flex and furnace supply				h
In the main electrical panel, protect all NM cable or reroute to exit the top of the panel.				h
At junction box next to the main electrical panel, protect all NM cables				h
Additional repairs not required by the City				
Provide door at upstairs stairway			400	f
Replace screen door closure			25	f
Unclog drains			300	i
Interior paint			1200	k
Water heater			600	n
Total			10240	