Connector inspection note

Fictional equipment. Not operating instructions for real products.

Inspection record: SCAN-004

Connector J2 on cable B4 requires a tightening torque of 6 N m.

Connector J3 on cable B4 requires a tightening torque of 9 N m.

Recorded by the fictional Harbor test workshop.