


## Phase II DUT diagnostics - 0-67 GHz

### Corrected Lange coupler transmission from port 1



### Corrected Lange coupler return loss

